

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CT19013435/FVF3E2**Date:** 16/10/2019REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3013911900

**Claimant  
Vehicle No :** SKD8348T**Insured Vehicle  
No :** SMH5779H

Date of Loss: 28/07/2019

Nature of Claim: TP

Claim  
No: SNM19D203527C02DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKD8348T**

Make &amp; Model: NISSAN GTR, 3.8 (A)

Engine No: VR38005150A

Reg. Date: 25/05/2008 (Man. Year: 2008)

Chassis No: R35003839

Colour: Red

Odometer: 118249 km

Engine Capacity: 3799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/35 R20

Rear Tyre Size: 285/35 R20

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	37,000.00	25,935.00	11,065.00	29.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,330.00	2,370.00	64.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>40,700.00</b>	<b>27,265.00</b>	<b>13,435.00</b>	<b>33.01</b>

INSPECTION

Date of Assignment: 31/07/2019

Date Inspected: 01/08/2019 Inspected At:

Chuan Ho Auto Service (Sin Ming)  
160 Sin Ming Drive, #07-09, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** PARASURAM SHANMUGAM**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED THAT TP WITHDRAW CLAIM  
(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
<b>Parts:</b>	192	NISSAN GTR 3.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKD8348T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (VARIS JAPAN)	Cracked	24,000.00 FL	*24,000.00 FL
2	1		*FRONT BUMPER LH RETAINER	Necessary	225.00 FL	*225.00 FL
3	1		*FRONT BUMPER RH RETAINER	Necessary	225.00 FL	*225.00 FL
4	1		*FRONT BUMPER RH DRL	Not Necessary	2,800.00 FL	*- FL
5	1		*FRONT BUMPER RH CARNARD (VARIS JAPAN)	Scratched	5,000.00 FL	*5,000.00 FL
6	1		*FRONT BUMPER RH HEADLAMP	Cracked	4,600.00 FL	*4,600.00 FL
7	1		*FRONT BUMPER LH HEADLAMP	Not Necessary	4,600.00 FL	*- FL
8	1		*FRONT BUMPER CENTER TOP PLATE	Cracked	1,400.00 FL	*1,400.00 FL
9	1		*FRONT BUMPER RE-INFORCEMENT BAR	Not Necessary	1,800.00 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Broken	475.00 FL	*475.00 FL
11	1		*FRONT BUMPER SUPPORT REINFORCEMENT	Cracked	1,125.00 FL	*1,125.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>46,250.00</b>	<b>37,050.00</b>
<b>- List Item Discount on L Items 20.00/30.00% (\$\$)</b>	9,250.00	11,115.00
<b>Total Parts (\$\$)</b>	<b>37,000.00</b>	<b>25,935.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK LIGHTING, WIRING & FUSES	New	400.00	80.00
2	LABOUR TO DISMANTLE, REPAIR, REPLACE PARTS AND ALIGN FRONT PORTION	New	1,800.00	750.00
3	TO PUTTY, PRIMER, SPRAY PAINT FRONT BUMPER (DUAL COLOUR)	New	1,500.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,700.00</b>	<b>1,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >