

ASS. REC. BY:

REF:

CS/AWA19013455/Uvd3<sup>n2</sup>

Special Instruction:

Assigner: Marcus

## ASSIGNMENT (Office)

From (Person):

Hwee Lee Fong

of

AWAC

Date/Time:

31/7/19 @ 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 5589B

Insured:

QBE 2195H

at Workshop in/s

ABWIN Service

Tel:

6713 9400

of

8 Kalai Bukit Ave 4 # 0748

Policy No:

AVCP9B0089541801

Claim No:

NSV 1900383/HLF

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/07/2019

CA / REV / REP. / REV 24 HRS

118/19

H.O.D. Endorsement:

Date/Time:

4:18pm @ 31/7/19

Person Contacted:

shenifuh

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SJV 5589B - X	
	QBE 2195H - X	

ASS. REC. BY:

REF:

AWAC

## ASSIGNMENT

From:

Date:

01/08/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SV5589B

at Workshop m/s

ABWIN Service

of

8 kalki Bukit Ave 4 #07-48

Insured:

premier

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

16k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

cup

LTA 11842

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SV5589B

Yr Regn:

1110

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

nada

3

Lux

C.C.

15-98

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

173671

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6BL10X1A-0115047

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R16

R:

Firenze

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

nexen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/7/19

D.O.I.

17/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

net 458

102 28-1-2020 LTA 11842 bnd.

net 46. tender 1999

14/8/19

L/s \$4000 conf. with sherif (Red 11, 166, 40, 7490)

RECEIVED 14 AUG 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

14/8 - typist

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

8 + RS. SI

Photos

Others

TOTAL

250

Report Format:

TP

Lump Sum / L.B.E. (\$)

4000/p

## Nivitha (LKK Auto)

**From:** Hew, Lee Fong <LeeFong.Hew@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Wednesday, 31 July 2019 4:06 PM  
**To:** 'assignments@lkkauto.com'  
**Cc:** 'sur@lkkauto.com'; 'AbwinM9 - Sharifah'  
**Subject:** TP Survey assignment for SJV 5589B DOA: 27/07/2019 Our ref: NSV1900383/HLF

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do have** consensus in the appointment of **Mr Mohamad Taufikh** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	SJV 5589 B
Insured Vehicle	:	GBE 2195 H
Policy Number	:	AVCPSB0089541801
Name of Workshop	:	ABWIN SERVICE PTE LTD
Contact Number	:	6713 9400
Person to Contact	:	MS SHARIFAH
Estimated Cost of repairs	:	NA

Regards,  
Claims Division

Copy to ABWIN SERVICE PTE LTD (Your Ref: SJV5589B ) via Email.

Note -

- ( x )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail

(and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, Ltd or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

## Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.  
Advertise it for sale at just \$58, list till sold.

Mazda 3  Price Range  Depreciation  2010  Vehicle Type

Advanced  
Search

Home » Used Cars » Leco Auto Pte Ltd » Mazda 3 1.6A Luxury

### Mazda 3 1.6A Luxury

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

**Price** \$17,000

**Depreciation** \$8,660 /yr  
View models with similar depre

**Reg Date** 29-Apr-2010  
(8mths 27days COE left)

**Mileage** 137,878 km (14.9k /yr)

**Manufactured** 2009

**Road Tax** \$742 /yr

**Transmission** Auto

**Dereg Value** \$12,797 as of today (change)

**OMV** \$21,139

**COE** \$30,000

**ARF** \$21,139

**Engine Cap** 1,598 cc

**Power** 77.0 kW (103 bhp)

**Curb Weight** 1,275 kg

**No. of Owners** 2

**Type of Vehicle** Mid-Sized Sedan

#### Features

1.6L DOHC 16V VVT Engine, 4 Speed Automatic Steptronic Transmission, 2 x SRS Airbags, ABS, Keyless Entry/Engine Start, Retractable Side Mirrors View specs of the Mazda 3 Sedan (2009-2014)

#### Accessories

Factory Fitted Audio System, 16" Sports Rims, Multi-Function Steering Control, Leather Seats, Reverse Sensors, Solar Film, Fog Lights.

#### Description

Newer Facelift Luxury Model. Smooth And Quiet Drive. Surely The Best Condition Unit In Market. Low Depreciation Below \$700 Monthly, Much Better Than Renting A Car. Ideal Car To Own If You Are Looking For A Budget Japanese Made Sedan For A Short Term Drive. Also An Option To Renew COE Later. Too Many Good Points Of Buying This Unit So What Are You Waiting For! Call Us To Arrange To View Now!

#### Category

PARF Car

#### Status

Available (Pending)

A buyer have paid a deposit for this car.

#### Resources



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started

Compare

Posted on: 27-Jul-2019 | Last Updated on: 31-Jul-2019



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

#### Seller Information

<b>Company</b>	Leco Auto Pte Ltd	
	» dealer's pricelist	
	» 22 vehs sold   18 vehs available	
<b>Address</b>	61 Ubi Avenue 2 #01-05/#02-15	
	Search cars nearby this location	
<b>Location</b>	Automobile Megamart	
<b>Office No</b>	68410020 / 68460020	
<b>Contact Person(s)</b>	Jeff	91574802
	Douglas	96680056
	Eric	90550932

Mazda 3

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Seng Lee Hong Vehicle Trading » Mazda 3 1.6A Luxury

## Mazda 3 1.6A Luxury

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

**Price** \$17,700**Depreciation** \$9,200 /yr  
View models with similar depre:**Reg Date** 11-May-2010  
(9mths 9days COE left)**Mileage** 164,000 km (17.8k /yr)**Manufactured** 2010**Road Tax** \$742 /yr**Transmission** Auto**Dereg Value** \$12,088 as of today (change)**OMV** \$21,131**COE** \$19,641**ARF** \$21,131**Engine Cap** 1,598 cc**Power** 77.0 kW (103 bhp)**Curb Weight** 1,275 kg**No. of Owners** 4**Type of Vehicle** Mid-Sized Sedan

## Features

Powerful And Economical 1.6L DOHC 16V VVT Engine, 4 Speed Automatic Steptronic Transmission, SRS Airbags, ABS, Keyless Entry And Push Start. View specs of the Mazda 3 Sedan (2009-2014)

## Accessories

Multi Function Control Steering, Leather Seats, Sports Rims, Built In Audio/CD With Steering Controls, Auto Retractable Side Mirror.

## Description

Well Maintained, Mint Condition. Ideal For Short Term Usage With Low Depreciation.

## Category

PARF Car

## Status

Available

## Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

## Seller Information

<b>Company</b>	Seng Lee Hong Vehicle Trading
	» dealer's pricelist
	» 55 vehs sold   15 vehs available
<b>Address</b>	1 Bukit Batok Crescent #02-15
	Search cars nearby this location
<b>Location</b>	WCEGA Plaza
<b>Office No</b>	64672802
<b>Contact Person (s)</b>	Neo Lam Lee 96202802

Posted on: 15-Jul-2019 | Last Updated on: 28-Jul-2019

Upfront Payment

» more Financial info

Transfer Fee

\$25

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 021A

## Vehicle Details

Vehicle No.: SJV5589B  
Vehicle to be Exported: No  
Intended Deregistration Date: 01 Aug 2019  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA3 1.6L SDN LUX  
Primary Colour: White  
Manufacturing Year: 2009  
Engine No.: Z6809929  
Chassis No.: JM6BL10Z1A0115047  
Maximum Power Output: 77.0 kW (103 bhp)  
Open Market Value: \$21,679.00  
Original Registration Date: 29 Jan 2010  
First Registration Date: 29 Jan 2010  
Transfer Count: 1  
Actual ARF Paid: \$21,679.00

## Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 28 Jan 2020  
PARF Rebate Amount: \$10,839.00

## Intended COE Rebate Details

COE Expiry Date: 28 Jan 2020  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$20,501.00  
COE Rebate Amount: \$1,003.00  
**Total Rebate Amount: \$11,842.00**

The information contained herein is correct as at 01 Aug 2019

OK



ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875  
Tel: 67139400 Fax: 67139415  
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com  
Company Reg. No: 201318665G GST Reg. No: 201318685G



ATTN: MARCUS 62564315  
FROM: SHARIFAH

ESTIMATED COST: HQQ000065

TO : NTUC INCOME INSURANCE CO-OPERATIVE LTD  
ATTN : MOTOR CLAIM DEPARTMENT

**SJV55898**  
**TONY PATUA**  
BLK 902 JURONG WEST  
STREET 91  
#09-107  
SINGAPORE 640902  
CONTACT NO : 92410554

DATE	:	01-AUG-2019
MAKE	:	MAZDA
MODEL	:	MAZDA3 1.6L SDN LUX
CHASSIS NO	:	JM6BL10Z1A0115047
ENGINE NO	:	Z6809929
SERVICE ADVISOR	:	SHARIFAH
PAGE	:	1 OF 3

NCE CO-OPERATIVE LTD  
 NENT  
 not added  
 1/8/19  
 2/5 4000/ 1 unit spin

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR WINDSCREEN MOULDING	113.20	✓
1	BOOT LID	1,219.70	X
1	BOOT LID EMBLEM	74.50	✓
1	BOOT LID LOCK	186.10	X
1	BOOT LID HINGE	142.50	X
1	BOOT LID LAMP RH	337.10	✓
1	TAIL LAMP LH	1,174.30	X
1	TAIL LAMP RH	1,174.30	✓
1	TAIL LAMP PANEL RH	79.20	✓
1	REAR FENDER RH	1,094.90	✓
1	REAR FENDER INNER PANEL RH	987.20	X
1	REAR FENDER INNER TRIM RH	203.60	X
1	REAR FENDER INNER SHIELD RH	105.30	✓
1	REAR BUMPER	1,102.30	✓
1	REAR BUMPER REFLECTOR RH	62.20	✓
1	REAR BUMPER RETAINER RH	38.90	✓
1	REAR BUMPER REINFORCEMENT	556.30	✓
1	WEATHERSTRIP	347.80	X
1	REAR END PANEL	449.80	✓
1	REAR END PANEL TOP GARNISH	203.00	X
1	WHEEL ARCH BEARING	447.50	X
1	FUEL TANK COVER	83.20	X
1	FUEL TANK NECK	153.50	X
Sub Total		10,336.40	0.00

## SPECIAL NETT

1	WINDSCREEN SEALANT	per	50.00	40
1	WINDSCREEN INNER SEAL	per	50.00	30



**ABWIN SERVICE PTE LTD**

8 KAKI BUKIT AVENUE 4 - GATE 2  
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875  
 Tel: 67139400 Fax: 67139415  
 Email: servicecentre@abwin.com.sg Website: www.abwin.sg  
 Company Reg. No: 201310685G GST Reg. No: 201310685G

**ESTIMATED COST: HQQ000065**

**TO : NTUC INCOME INSURANCE CO-OPERATIVE LTD**  
**ATTN : MOTOR CLAIM DEPARTMENT**

DATE : 01-AUG-2019  
 MAKE : MAZDA  
 MODEL : MAZDA3 1.6L SDN LUX  
 CHASSIS NO : JM6BL10Z1A0115047  
 ENGINE NO : 76809929  
 SERVICE ADVISOR : SHARIFAH  
 PAGE : 2 OF 3

**SJV55898**  
**TONY PAIVA**  
 BLK 902 JURONG WEST  
 STREET 91  
 #09-107  
 SINGAPORE 640902  
 CONTACT NO : 92410554

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	WINDSCREEN PRIMER & CLEANER	11 50.00	X
1	BOOT LID SEALANT	11 50.00	X
1	REAR FENDER RH SEALANT	11 50.00	X
1	REAR END PANEL SEALANT	11 50.00	X
10	REAR END PANEL TOP GARNISH CLIPS	11 50.00	X
10	REAR BUMPER CLIPS	11 50.00	X
5	REAR FENDER INNER SHIELD RH CLIPS	11 30.00	X
1	SPORTS RIM RR	11 680.00	X
1	REVERSE SENSOR	11 300.00	X
<b>Sub Total</b>		<b>1,410.00</b>	<b>0.00</b>

**LABOUR**

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,200.00	1100
1	TO SPRAY PAINT ON AFFECTED AREAS	1,200.00	1100
1	TO REMOVE & REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING & RESETTING HEADLAMP FOCUS	100.00	30
1	TO APPLY UNDERCOATING FOR RUST PROOFING	250.00	80
1	TO DISMANTLE AND REFIX REAR WINDSCREEN COMPONENTS	150.00	120
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	100.00	50
1	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	120.00	60
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	180.00	80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**ABWIN SERVICE PTE LTD**

8 KAKI BUKIT AVENUE 4 - GATE 2  
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875  
 Tel: 67139400 Fax: 67139415  
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com  
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000065**

**TO : NTUC INCOME INSURANCE CO-OPERATIVE LTD**  
**ATTN : MOTOR CLAIM DEPARTMENT**

**SJV5589B**  
**TONY PAIVA**  
 BLK 902 JURONG WEST  
 STREET 91  
 #09-107  
 SINGAPORE 640902  
 CONTACT NO : 92410554

DATE : 01-AUG-2019  
 MAKE : MAZDA  
 MODEL : MAZDA3 1.6L SDN LUX  
 CHASSIS NO : JM6BL10Z1A0115047  
 ENGINE NO : Z6809929  
 SERVICE ADVISOR : SHARIFAH  
 PAGE : 3 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO DISMANTLE, REPLACE AND/OR REPAIR BOOT LID COMPONENTS	120.00	na X
<b>Sub Total</b>		<b>3,420.00</b>	<b>0.00</b>

<b>SUB-TOTAL</b>	<b>15,166.40</b>	<b>0.00</b>
<b>GST - 7 %</b>	<b>1,061.65</b>	<b>0.00</b>
<b>TOTAL</b>	<b>16,228.05</b>	<b>0.00</b>

**ABWIN SERVICE PTE LTD**

Prepared By




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA19013455/Uvd3n2		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 15-08-2019		
		Code : AWA		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 2195H	Veh. Inspected	SVJ 5589B	
Policy No.	AVCPSP0089541801	Coverage (\$)	0.00	
Claim No.	NSV1900383/HLF	Excess (\$)	0.00	
Assign From	HEW LEE FONG	Assign Date	31/07/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 3 LUX (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JM6BL10Z1A0115047	Colour	WHITE	
Odometer	173671	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	NEXEN	6 mm	
L/H Front Tyre	205/55 R16	NEXEN	6 mm	
R/H Rear Tyre	205/55 R16	FIRENZA	6 mm	
L/H Rear Tyre	205/55 R16	FIRENZA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/07/2019	Inspection Date	01/08/2019	
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 5589B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR WINDSCREEN MOULDING	NECESSARY	113.20	113.20
1	BOOT LID	TO REPAIR SEE LABOUR	1,219.70	-
1	BOOT LID EMBLEM	NECESSARY	74.50	74.50
1	BOOT LID LOCK	NOT NECESSARY	186.10	-
1	BOOT LID HINGE	NOT NECESSARY	142.50	-
1	BOOT LID LAMP RH	CRACKED	337.10	337.10
1	TAIL LAMP LH	NOT NECESSARY	1,174.30	-
1	TAIL LAMP RH	CRACKED	1,174.30	1,174.30
1	TAIL LAMP PANEL RH	BENT	79.20	79.20
1	REAR FENDER RH	BADLY DENTED	1,094.90	1,094.90
1	REAR FENDER INNER PANEL RH	TO REPAIR SEE LABOUR	987.20	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	203.60	-
1	REAR FENDER INNER SHIELD RH	TORN	105.30	105.30
1	REAR BUMPER	DISTORTED	1,102.30	1,102.30
1	REAR BUMPER REFLECTOR RH	BROKEN	62.20	62.20
1	REAR BUMPER RETAINER RH	CRACKED	38.90	38.90
1	REAR BUMPER REINFORCEMENT	BENT	556.30	556.30
1	WEATHERSTRIP	NOT NECESSARY	347.80	-
1	REAR END PANEL	BADLY DENTED	449.80	449.80
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	203.00	-
1	WHEEL ARCH BEARING	NOT NECESSARY	447.50	-
1	FUEL TANK COVER	NOT NECESSARY	83.20	-
1	FUEL TANK NECK	NOT NECESSARY	153.50	-
	LESS 20% DISCOUNT		-	-1,037.60
			10,336.40	4,150.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	30.00
1	WINDSCREEN PRIMER & CLEANER (SN)	NOT NECESSARY	50.00	-
1	BOOT LID SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER RH SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/AWA19013455/Uvd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
5	REAR FENDER INNER SHIELD RH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SPORTS RIM RR (SN)	TO REPAIR SEE LABOUR	680.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	300.00	-
			1,410.00	170.00
	<b>LABOUR</b>			
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF BOOT LID,REAR FENDER INNER PANEL RH AND SPORTS RIM RR.		1,200.00	1,100.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,200.00	1,100.00
	TO REMOVE & REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING & RESETTNG HEADLAMP FOCUS.		100.00	30.00
	TO APPLY UNDERCOATING FOR RUST PROOFING.		250.00	80.00
	TO DISMANTLE AND REFIX REAR WINDSCREEN COMPONENTS.		150.00	120.00
	TO DISMANTLE,REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING.		100.00	50.00
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT.		120.00	60.00
	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY.		180.00	80.00
	TO DISMANTLE,REPLACE AND/OR REPAIR BOOT LID COMPONENTS.	NOT NECESSARY	120.00	-
			3,420.00	2,620.00
	<b>GRAND TOTAL</b>		<b>15,166.40</b>	<b>6,940.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,000.00</b>

Report Ref No. CS/AWA19013455/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.