Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19013468/KDA3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994289 Claimant SLK3538X Insured Vehicle No: SLD1704H Vehicle No:

Date of Loss: 27/07/2019 Nature of Claim: ΤP Claim No: 1190355966SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLK3538X Reg No:

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR992275

Reg. Date: 13/01/2017 (Man. Year: 2016) Chassis No: JTDKB3FU403544322

Colour: Metallic Silver Odometer: 145630 km

Engine Capacity: 1798 cc

Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,433.66	2,176.65	1,257.01	36.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.69	478.35	612.34	56.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,524.35	2,655.00	1,869.35	41.32
+ GST 7.00/7.00% (S\$)	316.70	185.85	130.85	41.32
Nett Amount (S\$)	4,841.05	2,840.85	2,000.20	41.32
+ Car Rental (2.0 x S\$69.94/day) (S\$)		139.88		
+ Doo	:/Search Fee (S\$)	7.45		
1	Nett Liability (S\$)	2,988.18		

INSPECTION

Date of Assignment: 31/07/2019

05/08/2019 Inspected At: 385 SIN MING DRIVE Date Inspected:

Repairer: Esteem Performance Pte Ltd

(HQ)

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHAN JIA LE Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount			
1	1		*FRONT NUMBER PLATE	Serviceable	45.00 FL	*- FL			
2	1		*FRT NO PLATE REINF	Serviceable	129.00 FL	*-FL			
3	1		*R/F BUMPER COVER	Serviceable	25.70 FL	*-FL			
4	1		*FRONT BUMPER	Buckled	450.80 FL	*450.80 FL			
5	1		*L/F BUMPER BRACKET	Serviceable	107.20 FL	*-FL			
6	1		*R/F BUMPER BRACKET	Serviceable	107.20 FL	*- FL			
7	1		*FRT BUMPER REINF	Serviceable	711.50 FL	*-FL			
8	1		*FRT BUMPER ABSORBER	Serviceable	44.17 FL	*- FL			
9	1		*FRONT GRILLE	Serviceable	321.90 FL	*-FL			
10	1		*FRONT MANUFACT BADGE	Necessary	87.10 FL	*87.10 FL			
11	1		*RIGHT HEADLAMP ASSY	Cut	2,531.60 FL	*2,531.60 FL			
12	1		*R/F WING BADGE	Serviceable	44.17 FL	*- FL			
13	1		*WASHER CONTAINER	Serviceable	195.60 FL	*-FL			
14	1		*FRT BMP CLIP	Necessary	40.00 FL	*40.00 FL			
15	1		*FRT NUM PLATE FRT NUM PLATE	Serviceable	45.00 FS	*-FS			
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.								
				Sub Total (S\$)	4,885.94	3,109.50			
	- List Item Discount on L Items 30.00/30.00% (S\$)			1,452.28	932.85				
				Total Parts (S\$)	3,433.66	2,176.65			
Report was unsubmitted during this print-out.									

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	129.0 WU X 50.00 SGD/H	New	645.00	120.00
2	LABOUR COST 60.0 WU X 50.00 SGD/H	New	300.00	225.00
3	MATERIAL COST	New	145.69	133.35
		Gross Labour Cost (S\$)	1,090.69	478.35
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >