

ASS. REC. BY:

Jen

REF:

NTUC NS/INC1901341/EP302

ASSIGNMENT

From:

Date:

30/7/19

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SHB 882 R

at Workshop m/s

SMRT

of

woodlands Depot

Insured:

YN7384B

Policy No.

5087585904-02 (07/02/2019-01/02/2020)

Claims No.

NT/1055544-002

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 882 R

Yr Regn:

19/03/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota / London Taxi

C.C.

2499

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

513822

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LJ4 97C7000-5099097

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175R16C

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Austone

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

27/7/19

D.O.I.

30/7/19

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Summary 30/7/19, Estimate do 31/7/19 (System down) 07/19/2111
	SHB 882 R - NA/TM1 13013056181 DOA - 27/09/2013 YN 7384B
	YN 7384B - X
19/8/19	Finalize \$1159, 3 repair days (P.h. Sec) (Led \$4713.56, 80%)
RECEIVED 20 AUG 2019	

Date/Time, File Pass to?



Preli. Report

1) 20/8 19/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

160

Transportation:

S + RS, SI

Photos

Others

TOTAL

160

Report Format:

TP

Lump Sum / HSD: (\$)

USD

TP Claims against NTUC Income: Follow-Through Survey

Date : 19/08/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1056954-002	CITYCAB PTE LTD	SHC 342C	SLI 3580C	06/08/2019	\$ 1,964.88	\$ 600.00
2	MT/1057535-002	COMFORT TRANSPORTATION PTE LTD	SH 9332R	PC 401X	10/08/2019	\$ 5,853.92	\$ 3,300.00
3	MT/1057607-002	COMFORT TRANSPORTATION PTE LTD	SH 8832X	SJX 2172D	13/08/2019	\$ 1,609.05	\$ 1,000.00
4	MT/1057573-002	COMFORT TRANSPORTATION PTE LTD	SH 7896T	GBE 9881P	12/08/2019	\$ 1,298.48	\$ 300.00
5	MT/1056575-002	CITYCAB PTE LTD	SHC 7402S	GBB 8710Y	03/08/2019	\$ 2,571.05	\$ 529.25
6	NOT OI	SMRT TAXIS PTE LTD	SHB 2P	SLA 1509J	29/07/2019	\$ 16,288.40	\$ 2,000.00
7	MT/1055544-002	SMRT TAXIS PTE LTD	SHB 882R	YN 7384B	27/07/2019	\$ 5,863.56	\$ 1,150.00
8	MT/1056750-002	COMFORT TRANSPORTATION PTE LTD	SHC 8047C	SLM 688E	6/8/2019	\$ 8,341.48	\$ 3,100.00

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="27/07/2019 08:53"/>
Vehicle No.(For Motor)	<input type="text" value="YN7384B"/>	Certificate Number	<input type="text"/>

[Search](#)

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5087585907-02		ENG BEE PAPER MERCHANT (PTE) LTD	198003952D	GCV	Comprehensive	YN7384B	YN7384B	02/02/2019	01/02/2020

[Continue](#)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB882R
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2019
Vehicle Make:	THE LONDON TAXI CO
Vehicle Model:	LONDON TX4 2.5 DIESEL AUTO
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	VM62C55786
Chassis No.:	LJU97C7B0DS000097
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$37,542.00
Original Registration Date:	19 Mar 2013
First Registration Date:	19 Mar 2013
Transfer Count:	0
Actual ARF Paid:	\$44,559.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Mar 2021
PARF Rebate Amount:	\$28,963.00
Intended COE Rebate Details	
COE Expiry Date:	18 Mar 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$67,858.00
COE Rebate Amount:	\$13,840.00
Total Rebate Amount:	\$42,803.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/07/2019 13:06
Date Of Accident	27/07/2019 17:20
Exact Location Of Accident	BLOCK 278 & 279 CAR PARK BISHAN NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB882R
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	TAY AH HOONG
NRIC No	S0298271D
Date Of Birth	19/05/1946
Occupation	OUTDOOR
Date Of Driving Pass	26/03/1964
Driving Experience	55 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	271
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING FROM BETWEEN BLOCK 278 & 279 CAR PARK AT BISHAN ST 24, AROUND 5.20 PM ON 27/07/2019. A LORRY YN7384B STATION BETWEEN THE PARKING LOT SUDDENLY TURN OUT WITHOUT LOOKING BEHIND AND HIT AND DENTED MY LEFT SIDE AND MY POWER STEERING CANNOT MOVE. THE DRIVER SAY HE WAS USING HIS PHONE AND DID NOT NOTICE I WAS BESIDE HIM. HE ADMITTED HE WAS USING HIS PHONE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7384B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	SUN LIHUI
NRIC/Passport Number	G8585718K
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Address	271
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING FROM BETWEEN BLOCK 278 & 279 CAR PARK AT BISHAN ST 24, AROUND 5.20 PM ON 27/07/2019. A LORRY YN7384B STATION BETWEEN THE PARKING LOT SUDDENLY TURN OUT WITHOUT LOOKING BEHIND AND HIT AND DENTED MY LEFT SIDE AND MY POWER STEERING CANNOT MOVE. THE DRIVER SAY HE WAS USING HIS PHONE AND DID NOT NOTICE I WAS BESIDE HIM. HE ADMITTED HE WAS USING HIS PHONE.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7384B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	SUN LIHUI
NRIC/Passport Number	G8585718K
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper. At the bottom left corner, there is a small portion of a label that reads "DECLARATION OF".

DECLARATION D

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number : TAX/07/19/2111
Type of Repair : Accident Repair
Vehicle Registration Number : SHB882R

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-7845-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
Accident Date and Time : 27/07/2019 09:20 AM
Vehicle Age(In Months) : 76

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FRONT BUMPER ASSY	1	951.74	951.74	10.00	856.57	Replace	1	0	Repair	CHT X R
One Time Key In	Main			LAMP ASSY- DIRECTIONA	1	103.00	103.00	10.00	92.70	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LAMP ASSY- FRONT FOG	1	214.66	214.66	10.00	193.19	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER ASSEMBLY- FRON	1	591.36	591.36	10.00	532.22	Replace	1	532.22	Replace	/ 00
One Time Key In	Main			HEADLAMP ASSEMBLY LH	1	642.02	642.02	10.00	577.82	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LINER- FRONT WHEELARC	1	142.17	142.17	10.00	127.95	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WHEEL TRIMS	1	77.27	77.27	10.00	69.54	Replace	1	0	Repair	X R
One Time Key In	Main			ROAD- WHEEL	1	610.04	610.04	10.00	549.04	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LAMP ASSY- SIDE REPEA	1	34.30	34.30	10.00	30.87	Replace	0	0	Not Give	X N/A
									Total Spare Part Cost	3,029.90	Surveyor Total 532.22			
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%) 20			
									Final Spare Part Cost	2,423.92	Final Sur Total 425.78			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	RESPRAY WHEEL CAP	180.00	50	
4	Main	TO RESPRAY RIM	180.00	50	
Total:			1,116.00	500.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ NK /
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	/ NK /
3	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	/ NK /
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ NK /
6	Main	TOWING CHARGE	56.00	0	
Total:			536.00	120.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,423.92	425.78
Total Labour Cost	845.00	300.00
Total Spray Painting	1,116.00	500.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Other	536.00	120.00
Overall Total	4,920.92	1,452.22
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	4,900.00	1,450.00
Surveyor Approved Amount		1,450.00
No of Repair Days*	6	3
Remarks	-	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.
Surveyor Name		STEVE CHEN
Signature		 1/8/19
Survey Date	31/07/2019	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5263.56



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63695502
Estimator Telephone Number : 68682623
Accident Reporting Number : 88852672



Date Generated : 16/08/2019

User ID : PohSuan

Section A - Accident Details

Registration Number	SHB882R
Case Reference Number	TAX/07/19/2111
Registration Date	19/3/2013
Company Type	SMRT Taxis Pte Ltd
Make	LONDON TAXI
Model	TX4
Name of Driver	TAY AH HOONG
Type of Accident	Side Swipe
Accident Date and Time	27/7/2019 5:20 PM
Accident Reported Date and Time	29/7/2019 11:09 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	29/7/2019 9:31 AM
Replacement Vehicle issued?	No
Job Card Number	24102602
Special Instruction to ARC, if any	NTUC - LKK
Prepared Date and Time	30/7/2019 4:19 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,116.00	\$500.00
Total Spare Part Cost	\$3,029.90	\$532.22
Total Other Cost	\$535.00	(\$182.22)
TOTAL COST	\$5,526.90	\$1,150.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	31/07/2019 2:17 PM	31/07/2019 2:02 PM
Signature		
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0174	Invoice Number	
Quotation Date	14.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
RESPRAY WHEEL CAP	\$180.00	\$50.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,116.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$302.22)
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TOWING CHARGE	\$56.00	\$0.00
Total Other Costs	\$536.00	(\$182.22)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		JHM667	FRONT BUMPER ASSY	1.00	\$951.74	100.00	\$0.00	Replace	Repair
		11870000 84	LAMP ASSY-DIRECTIONA	0.00	\$103.00	0.00	\$0.00	Replace	Not Given
		11870000 85	LAMP ASSY-FRONT FOG	0.00	\$214.66	0.00	\$0.00	Replace	Not Given
		11820001 49	FENDER ASSEMBLY-FRON	1.00	\$591.36	10.00	\$532.22	Replace	Replace
		11870000 77	HEADLAMP ASSEMBLY LH	0.00	\$642.02	0.00	\$0.00	Replace	Not Given
		11880004 81	LINER-FRONT WHEELARC	0.00	\$142.17	0.00	\$0.00	Replace	Not Given
		11840002 48	WHEEL TRIMS	1.00	\$77.27	100.00	\$0.00	Replace	Repair
		11840002 44	ROAD-WHEEL	0.00	\$610.04	0.00	\$0.00	Replace	Not Given
		11870001 62	LAMP ASSY-SIDE REPEA	0.00	\$34.30	0.00	\$0.00	Replace	Not Given
Total					\$3,366.56		\$532.22		

532.22
+ 300.00
+ 620.00
1452.22
- 20.00
1161.78
415 \$1150/-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19013471/Eqf3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 21-08-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7384B	Veh. Inspected	SHB 882R	
Policy No.	5087585907-02	Coverage (\$)	0.00	
Claim No.	MT/1055544-002	Excess (\$)	0.00	
Assign From		Assign Date	30/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	LONDON TAXI	c.c	2499	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	LJU97C7B0DS000097	Colour	WHITE	
Odometer	513822	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175 R16C	AUSTONE	5 mm	
L/H Front Tyre	175 R16C	AUSTONE	5 mm	
R/H Rear Tyre	175 R16C	AUSTONE	5 mm	
L/H Rear Tyre	175 R16C	AUSTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/07/2019	Inspection Date	30/07/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 882R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FENDER ASSEMBLY-FRON (DISC 10%)	DENTED	591.36	532.22
1	LAMP ASSY-DIRECTIONA	NOT NECESSARY	103.00	-
1	LAMP ASSY-FRONT FOG	NOT NECESSARY	214.66	-
1	HEADLAMP ASSEMBLY LH	NOT NECESSARY	642.02	-
1	LINER-FRONT WHEELARC	NOT NECESSARY	142.17	-
1	ROAD-WHEEL	NOT NECESSARY	610.04	-
1	LAMP ASSY-SIDE REPEA	NOT NECESSARY	34.30	-
1	FRONT BUMPER ASSY	TO REPAIR SEE LABOUR	951.74	-
1	WHEEL TRIMS	TO REPAIR SEE LABOUR	77.27	-
			3,366.56	532.22
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FRONT BUMPER ASSY AND WHEEL TRIMS.		845.00	300.00
	SPRAY PAINT.		1,116.00	500.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TOWING CHARGE.		56.00	-
			2,497.00	920.00
	GRAND TOTAL		5,863.56	1,452.22
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,150.00

Report Ref No. NS/INC19013471/Eqf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.