



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003401	Page	1
Registration No	: SLV8977X	Date	: 2. Aug 2019	Customer No.	: WZA006
Chassis No	: JHMGK3850JX204808	Svc Advisor	: NG SIN HAI	Engine No	: L13B11030070
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Date Time	: 2. Aug 2019 7:44:19 PM	Surveyor Name	:
Owner's Name	: PUA JIUNN SIONG	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 2/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33500-T5A-J02	TAILLIGHT ASSY,R. X	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. X	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID X	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID X	1	81.70	25	61.27	4.29	65.56
34270-T5A-J01	LIGHT ASSYHIGH MOUNT STOP X	1	79.80	25	59.85	4.19	64.04
68100-TAR-U10ZZ	TAILGATE COMP st/ ✓	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE ?	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE ?	1	78.90	25	59.17	4.14	63.31
74810-S6A-003	HANDLETAILGATE X	1	60.40	25	45.30	3.17	48.47
75722-T5L-T01	EMBLEMRR. na -	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARNISH ASSY,RR LICENCE X	1	105.50	25	79.12	5.54	84.66
34100-S60-013	LIGHT ASSYLICENCE X	2	34.10	25	51.15	3.58	54.73
04715-T5A-J50ZZ	FACE,RR.BUMPER de ✓	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R,RR.BUMPER X	1	20.70	25	15.52	1.09	16.61
71503-T5A-J50	COVER,RR.EXPI FIN X ✓	1	9.30	25	6.97	0.49	7.46
71505-T5A-J50	GARNISH,RR.BUMPER X ?	1	38.30	25	28.72	2.01	30.73
71507-T5A-J60	COVER,L,RR.BUMPER X	1	20.70	25	15.52	1.09	16.61

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003401	Page	2
Registration No	: SLV8977X	Date	: 2. Aug 2019	Customer No.	: WZA006
Chassis No	: JHMGK3850JX204808	Svc Advisor	: NG SIN HAI	Engine No	: L13B11030070
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Date Time	: 2. Aug 2019 7:44:19 PM	Surveyor Name	:
Owner's Name	: PUA JIUNN SIONG	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 2/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>me</i>	1	16.90	25	12.67 ✓	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>me</i>	1	16.90	25	12.67 ✓	0.89	13.56
91505-TM8-003	CLIP,BUMPER <i>me</i>	7	2.30	25	12.07 ✓	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPR. <i>Repair</i>	1	320.40	25	240.30	16.82	257.12
04655-TAS-300ZZ	PANEL SET,RR.FLOOR <i>X</i>	1	683.30	25	512.47	35.87	548.34
84640-T5A-003ZA	LINING ASSYRR.PANEL <i>B X</i>	1	60.80	25	45.60	3.19	48.79
72841-SH3-315	OILSHEET <i>X</i>	3	40.70	25	91.57	6.41	97.98
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>me</i>	1	11.40	25	8.55 ✓	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>me</i>	2	6.50	25	9.75 ✓	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 <i>me</i>	1	8.50	25	6.37 ✓	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>me</i>	2	60.00		120.00 ✓	8.40	128.40
Sum Item					3251.58	227.62	3,479.20
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 ✓		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 ✓		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00 ✓		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 <i>X</i>		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 ✓		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00 <i>X</i>		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00 <i>280</i>		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>280</i>		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00 ✓		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00 ✓		80.00	5.60	85.60
BKRP02M	CUT OFF & RENEW RR PANEL.	1	4000.00 <i>1680</i>		4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00 <i>1350</i>		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 <i>X</i>		450.00	31.50	481.50

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No. : SQT19003401	Page 3
Registration No : SLV8977X	Date : 2. Aug 2019	
Chassis No : JHMGK3850JX204808	Customer No. : WZA006	
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)	Svc Advisor : NG SIN HAI	
Owner's Name : PUA JIUNN SIONG	Engine No : L13B11030070	
Ins Policy No. :	Date Time : 2. Aug 2019 7:44:19 PM	
Date of Accident : 2/8/2019	Surveyor Name :	
	Survey Date :	
	Authorisation Date :	

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	560.00		560.00	39.20	599.20
					Sum Labor	11030.00	772.10

Survey By	<u>Rasul - 4p 90010568</u>						
Date & Time	<u>09/09/19 @ 1345</u>				Total Amount	14,281.58	999.72
Excess					Total (Inclusive of GST)		15,281.30
Status	<u>5 days</u>						
Signature	<u>[Signature]</u>						

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 2/8/2019 8:12:17 PM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.