

H5190 Tomh



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLV8977X
Chassis No : JHM GK3850JX204808
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : PUA JIUNN SIONG
Ins Policy No. :
Date of Accident : 2/8/2019

Document No. : SQT19003401 Page 1
Date : 2. Aug 2019
Customer No. : WZA006
Svc Advisor : NG SIN HAI
Engine No : L13B11030070
Date | Time : 2. Aug 2019 7:44:19 PM
Surveyor Name :
Survey Date :
Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount Includ GST |
|-----------------|--------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|--------|---------------|-------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: | | | | | | |
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR ?Xsuc | 1 | 320.00 | | 320.00 | 22.40 | 342.40 |
| BO-NUM-COMP-L | NUMBER PLATE WITH CASING-L(N) Xsuc | 1 | 45.00 | | 45.00 | 3.15 | 48.15 |
| 33500-T5A-J02 | TAILLIGHT ASSY.R. X | 1 | 223.90 | 25 | 167.92 | 11.75 | 179.67 |
| 33550-T5A-J02 | TAILLIGHT ASSYL. X } suc | 1 | 223.90 | 25 | 167.92 | 11.75 | 179.67 |
| 34150-T5A-J01 | LIGHT ASSY.R.LID X | 1 | 81.70 | 25 | 61.27 | 4.29 | 65.56 |
| 34155-T5A-J01 | LIGHT ASSYL.LID X | 1 | 81.70 | 25 | 61.27 | 4.29 | 65.56 |
| 34270-T5A-J01 | LIGHT ASSYHIGH MOUNT STOP Xnn | 1 | 79.80 | 25 | 59.85 | 4.19 | 64.04 |
| 68100-TAR-U10ZZ | TAILGATE COMP st | 1 | 730.60 | 25 | 547.95 | 38.36 | 586.31 |
| 74440-T5A-003 | WEATHERSTRIPTAILGATE ?Xsuc | 1 | 92.30 | 25 | 69.22 | 4.85 | 74.07 |
| 74801-T5S-K01 | LOCK ASSY,TAILGATE ?Xsuc | 1 | 78.90 | 25 | 59.17 | 4.14 | 63.31 |
| 74810-S6A-003 | HANDLETAILGATE Xsuc | 1 | 60.40 | 25 | 45.30 | 3.17 | 48.47 |
| 75722-T5L-T01 | EMBLEMRR. nn | 1 | 10.90 | 25 | 8.17 | 0.57 | 8.74 |
| 74890-T5A-A11 | GARNISH ASSY,RR LICENCE Xsuc | 1 | 105.50 | 25 | 79.12 | 5.54 | 84.66 |
| 34100-S60-013 | LIGHT ASSYLICENCE Xsuc | 2 | 34.10 | 25 | 51.15 | 3.58 | 54.73 |
| 04715-T5A-J50ZZ | FACE,RR.BUMPER de | 1 | 492.70 | 25 | 369.52 | 25.87 | 395.39 |
| 71502-T5A-J60 | COVER,R,RR.BUMPER X | 1 | 20.70 | 25 | 15.52 | 1.09 | 16.61 |
| 71503-T5A-J50 | COVER,RR,EXPL.FIN X } nn | 1 | 9.30 | 25 | 6.97 | 0.49 | 7.46 |
| 71505-T5A-J50 | GARNISH,RR.BUMPER X | 1 | 38.30 | 25 | 28.72 | 2.01 | 30.73 |
| 71507-T5A-J60 | COVER,L,RR.BUMPER X | 1 | 20.70 | 25 | 15.52 | 1.09 | 16.61 |

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|---------------------------|--------------------------------------------------------------------------------|-----------------------|------------------------|-----------------------------|--------------|
| Customer : | AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811 | Document No. : | SQT19003401 | Page | 2 |
| Registration No : | SLV8977X | Date : | 2. Aug 2019 | Customer No. : | WZA006 |
| Chassis No : | JHMGK3850JX204808 | Svc Advisor : | NG SIN HAI | Engine No : | L13B11030070 |
| Model : | JAZZ 1.3LXR CVT 18YM (EURO 6) | Date Time : | 2. Aug 2019 7:44:19 PM | Surveyor Name : | |
| Owner's Name : | PUA JIUNN SIONG | Survey Date : | | Authorisation Date : | |
| Ins Policy No. : | | | | | |
| Date of Accident : | 2/8/2019 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|----------------------------------------------------|-----|---------------------|--------|----------------|---------------|------------------|
| 71593-T5A-J50 | SPACER,R.RR.BUMPER SIDE <i>m</i> | 1 | 16.90 | 25 | 12.67 | 0.89 | 13.56 |
| 71598-T5A-J50 | SPACER,L.RR.BUMPER SIDE <i>m</i> | 1 | 16.90 | 25 | 12.67 | 0.89 | 13.56 |
| 91505-TM8-003 | CLIP,BUMPER <i>m</i> | 7 | 2.30 | 25 | 12.07 | 0.84 | 12.91 |
| 66100-TAR-T00ZZ | PANEL COMPR. <i>Repair X</i> | 1 | 320.40 | 25 | 240.30 | 16.82 | 257.12 |
| 04655-TAS-300ZZ | PANEL SET,RR.FLOOR <i>X m</i> | 1 | 683.30 | 25 | 512.47 | 35.87 | 548.34 |
| 84640-T5A-003ZA | LINING ASSYRR.PANEL <i>B X m</i> | 1 | 60.80 | 25 | 45.60 | 3.19 | 48.79 |
| 72841-SH3-315 | OILSHEET <i>X m</i> | 3 | 40.70 | 25 | 91.57 | 6.41 | 97.98 |
| 73127-TY0-000 | RUBBER CWINDSHIELD DAMPER <i>m</i> | 1 | 11.40 | 25 | 8.55 | 0.60 | 9.15 |
| 73214-T5A-013 | RUBBERWINDSHIELD DAMPER <i>X m</i> | 2 | 6.50 | 25 | 9.75 | 0.68 | 10.43 |
| 73226-SZW-000 | DAMPERSTD 5X5 <i>m</i> | 1 | 8.50 | 25 | 6.37 | 0.45 | 6.82 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) <i>m</i> | 2 | 60.00 | | 120.00 | 8.40 | 128.40 |
| Sum Item | | | | | 3251.58 | 227.62 | 3,479.20 |
| BOSUN | SUNDRIES | 1 | 100.00 <i>30</i> | | 100.00 | 7.00 | 107.00 |
| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| BOJSE | SEALANT FOR REAR END PANEL | 1 | 80.00 <i>X m</i> | | 80.00 | 5.60 | 85.60 |
| BOJSE | SEALANT FOR TAILGATE | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BOJSE | SEALANT FOR REAR FLOOR PANEL | 1 | 80.00 <i>X m</i> | | 80.00 | 5.60 | 85.60 |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| BMF00D | RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N) | 1 | 560.00 <i>X m</i> | | 560.00 | 39.20 | 599.20 |
| BMI02D | REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK | 1 | 560.00 <i>280</i> | | 560.00 | 39.20 | 599.20 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | 560.00 <i>280</i> | | 560.00 | 39.20 | 599.20 |
| BG02D | REMOVE & INSTALL RR. WINDSCREEN.(N) | 1 | 560.00 | | 560.00 | 39.20 | 599.20 |
| BODAMKIT | WINDSCREEN DAM KIT. | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BKRP02M | CUT OFF & RENEW RR PANEL | 1 | 4000.00 <i>1680</i> | | 4000.00 | 280.00 | 4280.00 |
| BP06R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1 | 3000.00 <i>1350</i> | | 3000.00 | 210.00 | 3210.00 |
| BKOT00R | REMOVE & RENEW RR FLOOR INSULATOR.(N) | 1 | 450.00 <i>X m</i> | | 450.00 | 31.50 | 481.50 |

Printed on 2/8/2019 8:12:17 PM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|----------------------------------------------------------------------------------|---------------------|--------------------------|---------------------------|----------------|
| Customer | : AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811 | Document No. | : SQT19003401 | Page | 3 |
| Registration No | : SLV8977X | Date | : 2. Aug 2019 | Customer No. | : WZA006 |
| Chassis No | : JHMGK3850JX204808 | Svc Advisor | : NG SIN HAI | Engine No | : L13B11030070 |
| Model | : JAZZ 1.3LXR CVT 18YM (EURO 6) | Date Time | : 2. Aug 2019 7:44:19 PM | Surveyor Name | : |
| Owner's Name | : PUA JIUNN SIONG | Survey Date | : | Authorisation Date | : |
| Ins Policy No. | : | | | | |
| Date of Accident | : 2/8/2019 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|---------|-------------------------------------------|-----|------------|--------|-----------------|---------------|------------------|
| BKBU01R | REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA | 1 | 560.00 | 4.8% | 560.00 | 39.20 | 599.20 |
| | Sum Labor | | | | 11030.00 | 772.10 | 11,802.10 |

Survey By: Rasul - 4p 90010568
Date & Time: 09/09/19 @ 1345
Excess: _____
Status: 5 days
Signature: [Signature]

Total Amount 14,281.58 999.72 15,281.30
Total (Inclusive of GST) 15,281.30

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.