

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19013505/APA3Q2

**Date:** 23/06/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SML7308A	<b>Insured Vehicle No :</b>	SHD4953H
Date of Loss: 27/07/2019	Nature of Claim:	TP Claim No: MCT19070708

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML7308A</b>		
Make & Model:	TOYOTA ESQUIRE, 1.8 HYBRID 7-SEATER GI CVT (A)	Engine No:	2ZR0C78145
Reg. Date:	31/05/2019 (Man. Year: 2018)	Chassis No:	ZWR800358335
Colour:	Grey	Odometer:	4287 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,649.85	1,030.00	4,619.85	81.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	970.00	1,250.00	56.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,869.85</b>	<b>2,000.00</b>	<b>5,869.85</b>	<b>74.59</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>550.89</b>	<b>140.00</b>	<b>410.89</b>	<b>74.59</b>
<b>Nett Amount (S\$)</b>	<b>8,420.74</b>	<b>2,140.00</b>	<b>6,280.74</b>	<b>74.59</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
		<b>(S\$)</b>	2,540.00	
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,270.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,270.00</b>		

#### INSPECTION

Date of Assignment:	01/08/2019	
Date Inspected:	05/08/2019 Inspected At:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2020)
<b>Parts:</b> M1-MPV	TOYOTA ESQUIRE 1.8 HYBRID 7-SEATER GI CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML7308A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,675.80 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINER	Not Necessary	132.70 FL	*- FL
3	1		*REAR AXLE	Not Necessary	2,648.70 FL	*- FL
4	1		*REAR WHEEL HUB	Not Necessary	923.30 FL	*- FL
5	1		*REAR SHOCK ABSORBER	Not Necessary	339.30 FL	*- FL
6	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
7	1		*REAR SPORT RIM	Cut	900.00 FS	*750.00 FS
8	1		*REAR TYRE	Cut	400.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,079.80</b>	<b>1,030.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,429.95	0.00
<b>Total Parts (S\$)</b>	<b>5,649.85</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
3	TO REMOVE AND REFIT UNDERCARRIAGE	New	500.00	0.00
4	(REAR) TO SPRAY PAINTING	New	700.00	500.00
5	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS	New	700.00	300.00
6	TO REMOVE AND REFIT INNER TRIM	New	150.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,220.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >