

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3173D

DATE 30/7/2019 16:40

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>x 1/2</i>			\$ 544.50
	Front Bumper Bracket Top (RH) <i>x</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>?</i>			\$ 24.60
	Headlamp (RH) <i>x</i>			\$ 1,388.00
	Front Fender (RH) <i>-</i>			\$ 663.00
	Front Fender Shield (RH) <i>x</i>			\$ 174.90
	Front Fender Retainer <i>x</i>			\$ 24.60
	Front Door Mirror Assy (RH) <i>-</i>			\$ 670.00
	Front Wheel Rim (RH) <i>x</i>			\$ 325.30
	Front Wheel Hub Cap (RH) <i>-</i>			\$ 107.10
	SUB TOTAL			\$ 3,944.40
	LESS 20%			\$ 788.88
	DISCOUNTED TOTAL			\$ 3,155.52
	Labour Charge			
	Panel Beating			\$ 400.00 ³⁰⁰
	Spray Painting Charge			\$ 600.00 ⁴⁵⁰
	Wiring Charge			\$ 50.00 ²⁰
	Tuff Kote			\$ 50.00 ²⁰
	FRT Wheel Alignment			\$ 80.00 ^x
	TOTAL LABOUR			\$ 1,180.00
	ESTIMATE TOTAL			\$ 4,335.52
<p><i>1/2 1/2</i></p> <p><i>31/7/19 1130hrs</i></p> <p><i>2 Reps.</i></p> <p><i>4/5</i></p> <p><i>After Repair photo</i></p> <div data-bbox="824 1415 1338 1814" data-label="Text"> <p>LKK Auto Centre has been notified the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey and/or spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "without prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				