

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 11 Oct 2019

Preliminary Advice

Vehicle No	: GBH7183T	Accident Date	: 16/07/2019
Make	: TOYOTA DYNA 1.5T	Policy No.	: 29094733
Assignment Date	: 01/08/2019	Excess	: S\$600.00
Date of Inspection	: 02/08/2019	Est. Duration of Repair	: 6 days
Inspection At	: Hing Lee Motor Car Repair & Welder Works (HQ) 397D Woodlands Road Singapore 677996		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,240.90
Revised Amount	:S\$	6,838.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,838.52
Lump Sum Repair :S\$ 5,450.00		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	22,955.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,045.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.