

22/03/2002

SS. REC. BY:

REF CS/MSG 14013539/kpf302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

Meriman

From (Person): Irene Tan Get Ing

of MSIG

Date/Time: 2.9.19 10.46a.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 7000U

Insured: XE 2672L

at Workshop m/s Rhino Repair

Tel: 62548858

of 160 Sin ming Drive #03-14

Policy No: S28906605MKC

Claim No: 601073

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

map

H.O.D. Endorsement:

Date/Time: 2.9.19 10.52a.m

Person Contacted: Bing Zong


Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---|
| | GBB 7000U - CC6 / A16 110 23871 / K92934 Don - 09/11/2011 |
| | XE 2672L - X |
| | Dismantle: 5/8/2019 |
| | After repair: 7/8/2019 |
| 1/10 | Received email from Irene to conduct paper survey. |

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of 03-14
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 05 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA 6170 REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: G5BB 7000V Yr Regn: 06, 10
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Hiace c.c. 2982
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 305227 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JT194T02P40 0059399
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 175 R: 195R 15X8
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Journey
 Front R/Bal. 8 mm Rear R/Bal. 6 mm
 L/Bal. 8 mm L/Bal. 6 mm
 D.O.A. 26/7/19 D.O.I. 2/8/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|----------------|---|
| <u>1</u> | <u>File pass to NO estimate</u> |
| | <u>Estimated repair range \$3,000 - \$4,000.</u> |
| | <u>Submit lump sum \$1500, 5days (red: 1600: 33) \$3200</u> |
| <u>18/8/19</u> | <u>Cor review to submit</u> |

| | | | |
|----------------------------|--|--|------------------|
| Date/Time, File Pass to? | <input type="checkbox"/> : Prell. Report | Days Of Repair: <u>5</u> | Survey Fee: |
| 1) | <input type="checkbox"/> : Final Report | Resurvey No. of Trlp: _____ | Transportation: |
| Date/Time, File Return to? | | Add Fee: <input type="checkbox"/> : Site Insp (\$ _____) | S - RS. \$ _____ |
| 2) | | <input type="checkbox"/> : Interview (\$ _____) | Fees |
| | | <input type="checkbox"/> : Tech Invs (\$ _____) | Others |
| | | <input type="checkbox"/> : Weekend (\$ _____) | TOTAL |

| |
|-----|
| 120 |
| 80 |
| 11 |
| 211 |

Report Format: TP
 Lump Sum / I.B.I: (\$) 1500 3200

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 29 Jul 2019 | | 02 Aug 2019 10:46 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | | | | | | | | | | | | | | | | |
|---|---|------------------------|---|----------------------|-------------------|--------------|-----------------|------------|---------|---------|-------------|--------------|------------|-------|-------------|--|--|--|--|--|--|--|--|--|
| CLAIM SUBFOLDER DETAILS | | | | [Created by insurer] | | | | | | | | | | | | | | | | | | | | |
| Insured: | KIM SOON LEE PTE LTD , Co. Reg. No.: 200304459N | | | | | | | | | | | | | | | | | | | | | | | |
| Main Claimant: | RHINO RENTAL PTE LTD , Co. Reg. No.: 201325388E | | | | | | | | | | | | | | | | | | | | | | | |
| Vehicle Reg. No.: | GBB7000U | Date of Loss: | 26/07/2019 14:00 - :59 [109 Months and 5 Days From LTA Reg Date (Man Yr)] | | | | | | | | | | | | | | | | | | | | | |
| Claim Type: | TP / 601073 | Policy/Cover Note No.: | S28906605MKC (Comprehensive) Coverage: 01/03/2019 - 29/02/2020 | | | | | | | | | | | | | | | | | | | | | |
| Vehicle Reg. No. (Insured): | XE2672L | Policy No. (Claimant): | | | | | | | | | | | | | | | | | | | | | | |
| | | Excess: | | | | | | | | | | | | | | | | | | | | | | |
| Repairer: | Rhino Repairs Pte Ltd (HQ) 160 SIN MING DRIVE #03-14, SIN MING AUTOCITY, 575722 Sin Ming - Tel: | | | | | | | | | | | | | | | | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541] | | | | | | | | | | | | | | | | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/08/2019] | | | | | | | | | | | | | | | | | | | | | | | |
| Driver/Custodian (Insured): | WANG DONGYOU (), NRIC: G6793216T, Tel: +6585028013 Email: | | | | | | | | | | | | | | | | | | | | | | | |
| Adj Asg. Remarks: | on WP. Liab: Dispute(NR). Disagree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Lim Bing Zong @ 6254 8858. | | | | | | | | | | | | | | | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | View All | Compose Case Mail | | | | | | | | | | | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | | | | | | | | | | | | | | | | |
| <input type="checkbox"/> ALL ASSOCIATED TASKS | | | | | | | | | | | | | | | | | | | | | | | | |
| <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> | | | | | Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? | No results. | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? | | | | | | | | | | | | | | | |
| No results. | | | | | | | | | | | | | | | | | | | | | | | | |
| <table border="1"> <thead> <tr> <th>View All</th> <th>Search Tasks</th> <th>Create New Task</th> <th>Complete</th> </tr> </thead> </table> | | | | | View All | Search Tasks | Create New Task | Complete | | | | | | | | | | | | | | | | |
| View All | Search Tasks | Create New Task | Complete | | | | | | | | | | | | | | | | | | | | | |

Nivitha (LKK Auto)

From: Irene Tan <irene_tan@sg.msig-asia.com>
Sent: Tuesday, 1 October 2019 2:48 PM
To: Veron Chen (LKKAuto); Shiao Chan (LKKAuto); Olivia Lau (LKKAuto); Celine Fong (LKKAuto); Denise Tay (LKKAuto)
Cc: Admin-D (LKKAuto)
Subject: Please prepare your paper survey report on GBB7000U; Our claim no.: 601073/IT

Importance: High

Good afternoon Veron,

We refer to the PRI assignment given on 2.8.19.

Please prepare and upload your paper survey report asap.

Irene Tan
Senior Executive, Motor Claims Services
D: +65 6594 2541 | F: +65 6225 7402 | irene_tan@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg    

A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|-------------------------|
| Owner ID Type: | Company |
| Owner ID: | 388E |
| Vehicle Details | |
| Vehicle No.: | GBB7000U |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 20 Sep 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | HIACE MANUAL |
| Primary Colour: | Silver |
| Manufacturing Year: | 2010 |
| Engine No.: | 1KD2015258 |
| Chassis No.: | JTFHT02P400059399 |
| Maximum Power Output: | - |
| Open Market Value: | \$25,387.00 |
| Original Registration Date: | 21 Jun 2010 |
| First Registration Date: | 21 Jun 2010 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$1,270.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 20 Jun 2020 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | \$32,501.00 |
| COE Rebate Amount: | \$2,437.00 |
| Total Rebate Amount: | \$2,437.00 |

The information contained herein is correct as at 20 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------|
| Date Of Report | 26/07/2019 17:18 |
| Date Of Accident | 26/07/2019 14:45 |
| Exact Location Of Accident | CHANGI SOUTH LANE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | GBB7000U |
| Insured/Policyholder | |
| Name Of Registered Owner | RHINO RENTAL PTE LTD |
| Co Reg No | 201325388E |
| Email Address | INFO@RHINORENTAL.SG |
| Mobile Phone No | (LOCAL) +65-88580588 |
| Alternative Phone No | OFFICE-88580588 |

Vehicle Particulars

| | |
|--|--------------------|
| Manufacturer | TOYOTA |
| Model | HIACE MANUAL |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | YES |
| Policy Number | 5107952193-000017 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | PEH ZHI YAO KEEDAN |
| NRIC No | S8606862A |
| Date Of Birth | 12/03/1986 |
| Occupation | INDOOR |
| Date Of Driving Pass | 09/10/2006 |
| Driving Experience | 12 YEARS AND 9 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98757902 |
| Fax Number | |
| Contact Number | |
| EEmail Address | NOEMAIL |

| | |
|---|----------------------------------|
| Address | BLK 625 YISHUN STREET 61 #05-119 |
| Postcode | 760625 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-----------------------|
| Vehicle Registration Number | XE2672L |
| Vehicle Make/Model/Colour | MINICAB (PRIME MOVER) |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | WANG DONG YOU |
| NRIC/Passport Number | G6793216T |
| Contact Number | 85028013 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 26-7-19


Driver's Signature
(If driver is not the policyholder)
Date & Time: 26-7-19



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN

A: GBB7000U
B: XE 2672L

CHANGI SOUTH LANE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26-07-2019 14:44 hrs I was driving along Changi South Lane, while waiting for Red Light at the Junction. Suddenly I heard a Loud Bang from the rear of the van my vehicle moved to the front a little when I went down of the vehicle to check the rear I saw vehicle B reverse ~~his~~ his vehicle. We exchange our particulars and took a few photos before we left the scene.

→ Repair other workshop *

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 26-7-19
 Company Chop (if applicable)


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 26-7-19


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



HIN TAT AUGUSTINE & PARTNERS

Advocates & Solicitors Commissioners For Oaths Notaries Public

UEN NO. 53130863D


20 UPPER CIRCULAR ROAD
#02-10/12 THE RIVERWALK
SINGAPORE 058416
TEL : (65) 6533 0212
FAX : (65) 6533 0313

(65) 6338 3536 (Direct Fax)
Service By Fax Not Accepted

WEBSITE: www.htapartners.com.sg
WRITER : MARILYN HO SU FEN (marilyn@htapartners.com.sg)
SECRETARY : RUBY ONG (ruby@htapartners.com.sg)

In Association with:
Strohal Legal Group Pte Ltd
International Legal Consultants

Our Ref : TCL.MH.ro.50477.19.rr
Your Ref : XE 2672L 601073



25 September 2019

Kim Soon Lee Pte. Ltd.
200 Bedok South Avenue 1
Singapore 469331

By Certificate of Posting (w/o encl)
(for your information only)

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay #24-01
Hong Leong Building
Singapore 048581
Attn : Motor Claims Department



By Hand & By Fax (w/o encl)

Dear Sirs

ACCIDENT INVOLVING GBB 7000U & XE 2672L ALONG CHANGI SOUTH LANE ON 26 JULY 2019 @ 1455HRS

We act for Rhino Rental Pte Ltd, the owner of motor vehicle no. GBB 7000U, in relation to the above-captioned road traffic accident.

We are instructed that you were the owner & driver and/or the insurer of motor vehicle no. XE 2672L at the material time. We are further instructed that the accident was caused by your authorized driver and/or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

| | |
|---|--------------------|
| 1. Cost of Repairs (inclusive of GST) | S\$4,800.00 |
| 2. Loss of Use (9 days x S\$120.00 per day) | S\$1,080.00 |
| 3. LTA Search Fees | S\$ 7.49 |
| 4. Costs (inclusive of GST) | S\$ 749.00 |
| 5. Incidentals | <u>S\$ 50.00</u> |
| Total | <u>S\$6,686.49</u> |

.../Page 2

TAN HIN TAT
AUGUSTINE SOH KHENG YEOW
SEAN LIM THIAN SIONG
TANG CHI LOONG

WOO FGONG LIN
TAN E-FANG
CLAIRE THAM LI MEI

CAROLYN LIM MAY LEAN
HO KIM FOONG
SERENA GOH MAE LI
GONG CHIN NAM
MOHD ZIKRI B MOHD MUZAMMIL
CHRISTINE CHUAH HUI FEN
MARILYN HO SU FEN
ANDREW PATRICK HILL
THIAN RUI LING

CONSULTANTS: LIM KIA TONG
JANET WEE-TAN

eLitigation

HIN TAT AUGUSTINE & PARTNERS

Page No. 2

Our Ref. TCL.MH.ro.50477.19.rr

Your Ref. XE 2672L

Date : 25 September 2019

The following supporting documents are enclosed herewith: -


1. Copy of Singapore Accident Statement by GBB 7000U;
2. Copy of Repair Bill from Rhino Repairs Pte Ltd;
3. Copy of LTA search result of XE 2672L;
4. Copy of Survey Invoice & Survey Report from Impact Analysis Consultant;
5. **32 pcs of original** photographs of motor vehicle no. GBB 7000U.

Please note that you / your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our client will have no alternative but to commence proceedings against you / your insured driver without further notice to you / your insured driver.

Please note that if you / insured driver have a counterclaim against our client arising out of the accident, you / your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **eight (8)** weeks of your receipt of this letter.

Please note that our client's claim is in respect of its property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully,



MARILYN HO SU FEN

Enc.

cc: client

By fax



Rhino Repairs Pte Ltd
160 Sin Ming Drive #03-14
Singapore 575722
Office: 6254 8858 Fax: 6250 9702
Company/GST Reg. No.: 201600994N

RHINO RENTAL PTE LTD
160 SIN MING DRIVE
#03-14
S(575722)
Tel: 6254 8858 Fax: 6250 9702
Attn: TAN GUAN YU (8858 0588)

Tax Invoice
Inv No. : INV19090036
Invoice Date : 16 Sep 2019
Ref : WJ1909033
Terms : 30 Days
Veh. No. : GBB7000U

| # | Description | Qty | UOM | U/P | Disc | Amt |
|---|------------------------------|------|-----|----------|------|----------|
| 1 | LUMP SUM REPAIR FOR GBB7000U | 1.00 | | 4,800.00 | 0.00 | 4,800.00 |

Name : _____

Includes GST 7.0% : S\$ 314.02
Total : S\$ 4,800.00

NRIC No. : _____

Signature : _____

For bank transfer, please transfer payment to the following account:
Rhino Repairs Pte Ltd
OCBC 695-316547-001
Thank you for supporting us!

For Rhino Repairs Pte Ltd

(Authorised Signature)



Our reference: 19-8-8440

Date: 6/8/2019

INVOICE NO. 8440

Rhino Rental Pte Ltd
c/o Rhino Repairs Pte Ltd
160 Sin Ming Drive #03-14
Sin Ming Autocity
Singapore 575722

Registration No. **GBB7000U**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

| S/No. | Description of Services Provided | Qty | Amount |
|---------------------|---|-----|-------------------------|
| 1 | Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous. | 1 | \$ 548.00 |
| Total amount | | | <u>\$ 548.00</u> |

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.



L. L. Tan (Ms)
Principal Consultant

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd

Our reference: 19-8-8440

Date: 6/8/2019

c/o Rhino Repairs Pte Ltd
160 Sin Ming Drive #03-14
Sin Ming Autocity
Singapore 575722

Dear Sirs

**RE: Road Traffic Accident on 26/7/2019
Rhino Rental Pte Ltd**

In accordance with your instructions received in this office on **2/8/2019**, we made arrangements to examine the vehicle on **2/8/2019** at above-mentioned address. The following data was recorded:


Vehicle details

| | | | |
|------------------|----------|---------------------|-------------------|
| Make | Toyota | Registration | GBB7000U |
| Model | Hiace | Chassis | JTFHT02P400059399 |
| Colour | Silver | Gearbox | Manual |
| Odometer | 305227km | Paintwork | Good |
| Steering | In order | Brakes | In order |
| Condition | Good | | |

Tyre Depths

| | | |
|-------------|---------|-------------|
| Front left | 195R15C | 85% Journey |
| Front right | 195R15C | 85% Journey |
| Rear left | 195R15C | 85% Journey |
| Rear right | 195R15C | 85% Journey |

Impact Direction & Area of Damage:



| | |
|---------------------|--------------|
| Status | REPAIRABLE |
| Magnitude | Medium |
| Legal status | Unroadworthy |

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of **\$4,800.00** and **7** working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd

Our reference 19-8-8440
Date 6/8/2019
Page 2

Section A: Damaged Parts Assessment

| Part's Description | Qty | Condition As Inspected | Repairer's Estimate | Our Adjustment |
|--------------------|-----|------------------------|---------------------|----------------|
|--------------------|-----|------------------------|---------------------|----------------|

List Items:

| | | | | |
|--|---|------------------|----------------|---------------------------|
| Tail gate | 1 | bent | 1445.90 | 1445.90 |
| Tail gate inner trim | 1 | serviceable | 210.20 | 0.00 |
| Tail gate top lock | 1 | damaged | 412.50 | <i>R</i> 412.50 <i>X</i> |
| Tail gate weatherstrip | 1 | ripped | 329.10 | <i>Sm</i> 329.10 <i>X</i> |
| Tail gate logo | 1 | necessary | 60.10 | 60.10 |
| Tail gate sticker "HIACE" | 1 | necessary | 65.20 | 65.20 |
| Rear bumper | 1 | deformed | 422.50 | 422.50 |
| Rear bumper side retainer @\$80.10 | 2 | necessary | 160.20 | <i>Sm</i> 160.20 <i>X</i> |
| Rear bumper lower bracket @\$21.90 | 3 | bent | 65.70 | 65.70 |
| Rear tail lamp @\$302.80 | 2 | cracked | 605.60 | 605.60 |
| Rear tail lamp panel rh | 1 | repair | 145.10 | 0.00 |
| Rear tail lamp lower garnish @\$115.80 | 1 | rh bent lh refix | 231.60 | <i>Sm</i> 115.80 <i>X</i> |
| Rear end panel outer | 1 | bent | 445.80 | 445.80 |
| Rear end coner panel rh | 1 | repair | 358.30 | 0.00 |
| Sub- Total cost | | | 4957.80 | 4128.40 |
| Percentage discount : 25% | | | 1239.45 | 1032.10 |
| Sub-Total cost for parts | | | 3718.35 | 3096.30 |

Special Nett Items:

| | | | | |
|---------------------------------|---|-------------|---------------|--------------------------|
| Tail gate "70km/h" sticker | 1 | necessary | 20.00 | 20.00 |
| Tail gate windscreen sealant | 1 | necessary | 50.00 | 50.00 <i>40.50</i> |
| Rear bumper clips @\$4.50 | 8 | necessary | 36.00 | 36.00 |
| Rear tail lamp clips | 4 | necessary | 18.00 | <i>nn</i> 18.00 <i>X</i> |
| Rear reverse sensor | 1 | malfunction | 280.00 | 250.00 <i>200.00</i> |
| Tail gate "8PAX" sticker | 1 | necessary | 20.00 | 20.00 |
| Sub-Total cost for parts | | | 424.00 | 394.00 |

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd

Our reference 19-8-8440

Date 6/8/2019

Parts Repair

| | | | | |
|--|---|---|----------------|----------------|
| | * | * | 0.00 | 0.00 |
| | | | 0.00 | 0.00 |
| | | | 4142.35 | 3490.30 |

Our reference 19-8-8440

Date 6/8/2019

Page 3

Section B: Labour Cost Calculation

| | Hourly rate | Manhr. Req. | Total |
|--|--------------------|-------------|----------------------------|
| To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts. | \$ 45.00 | 23 | \$ 1,035.00 ⁶⁰⁰ |
| Putty & Spray painting to adjacent panels. Job allowance. Paint / material. | Sub-contract work. | | \$ 600.00 ⁴⁵⁰ |
| Apply rust proofing on the adjacent panels. | Sub-contract work. | | \$ 60.00 |
| Remove and replace rear bumper reverse sensor & conduct distance safety setting. | \$ 45.00 | 1.7 | \$ 76.50 ⁵⁰ |
| Transfer of existing tailgate mechanism. | \$ 45.00 | 1.8 | \$ 81.00 ⁶⁰ |
| Remove and refix tailgate rear windscreen glass. (2-man job) | \$ 45.00 | 3 | \$ 135.00 ¹²⁰ |
| Wiring / bulb checking | \$ 50.00 | 0.5 | \$ 25.00 |
| Total labour cost | | | \$ 2,012.50 |

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

6154.85

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd ● Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd


Our reference 19-8-8440

Date 6/8/2019

Section C: Summary Table of Total Repair Cost

| Description | | Cost | |
|--|-----|------------|-----------|
| Damaged Parts Assessment (See section A) | | \$3,490.30 | |
| Further discount | 20% | \$698.06 | |
| Recommended cost of parts | | \$2,792.24 | (1) |
| Labour Cost Calculation (See section B) | | \$2,012.50 | (2) |
| Total Repair Cost (Round off to hundred) | | \$4,800.00 | (1) + (2) |

We would recommend a sum of \$4,800.00 and 7 working days for repair. No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.



Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma.Mechanical Engineering
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council
ACTA certified Trainer, Singapore
SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
- Impact Analysis Academy Pte Ltd
- IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
- Infoknights International Services (Philippines)
- IABN Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 29 Jul 2019 | | 02 Aug 2019 10:46 Edit Adj Rpt | S\$3,200.00 Edit Estimates | S\$3,200.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|--|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | KIM SOON LEE PTE LTD , Co. Reg. No.: 200304459N | | | | | | | | |
| Main Claimant: | RHINO RENTAL PTE LTD , Co. Reg. No.: 201325388E | | | | | | | | |
| Vehicle Reg. No.: | GBB7000U | Date of Loss: | 26/07/2019 14:00 - :59 [109 Months and 5 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 601073 | Policy/Cover Note No.: | S28906605MKC (Comprehensive) Coverage: 01/03/2019 - 29/02/2020 | | | | | | |
| Vehicle Reg. No. (Insured): | XE2672L | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Rhino Repairs Pte Ltd (HQ) 160 SIN MING DRIVE #03-14, SIN MING AUTOCITY, 575722 Sin Ming - Tel: | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 03/08/2019] | | | | | | | | |
| Driver/Custodian (Insured): | WANG DONGYOU (), NRIC: G6793216T, Tel: +6585028013 Email: | | | | | | | | |
| Adj Asg. Remarks: | on WP. Liab: Dispute(NR). Disagree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Lim Bing Zong @ 6254 8858. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*GBB7000U (601073)
[XE2672L]
TP
RHINO RENTAL PTE LTD
Jul 26 2019 2:00PM
[KIM SOON LEE PTE LTD]
Rhino Repairs Pte Ltd

| Upload Documents | | | Upload Photos | | | Compose New Letter | | | View | View in Browser | |
|---------------------------|-----------------|---|---------------|--|--|--------------------|--|-----------|-------------------------------------|-----------------|-------------------------------------|
| Assessment Reports | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | | | | | Thumbnail | Print | | |
| 1 | 01/10/19 14:50 | Accident Statement From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load HTM | | | |
| Photos/Images | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | | | | | Thumbnail | Print | | |
| 1 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 4 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 5 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 6 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 7 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 8 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 9 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 10 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 11 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 12 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 13 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 14 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 15 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 16 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 17 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 18 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 19 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 20 | 01/10/19 14:50 | Accident Photo From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | Thumbnail | Print | | |
| 1 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 4 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 5 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 6 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 7 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 8 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 9 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 10 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 11 | 20/09/19 08:44 | General View | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|---|--|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 12 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 20/09/19 08:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 20/09/19 08:45 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 20/09/19 08:45 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 01/10/19 14:17 | LOD with final repair bill, survey report & pictures |  Load PDF | |
| 2 | 01/10/19 14:48 | instruction to LKK to prepare paper survey report |  Load PDF | |
| 3 | 01/10/19 14:50 | TP E-file Report <small>From:SC - Reg. No: XE2672L, Claimant: KIM SOON LEE PTE LTD</small> |  Load PDF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 18/11/19 09:13 | Colour Photo |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | | Reset | Save | Print |
|--|--|-------|------|-------|
| There are no document checklists configured. | | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19013539/KTF3E2

Date: 18/11/2019

REFERENCE

| | | |
|--|-----------------------------|------------------|
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | S28906605MKC |
| Claimant | Insured Vehicle No : | XE2672L |
| Vehicle No : GBB7000U | | |
| Date of Loss: 26/07/2019 | Nature of Claim: TP | Claim No: 601073 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | GBB7000U | Engine No: | 1KD2015258 |
| Make & Model: | TOYOTA HIACE, 3.0 D (M) | Chassis No: | JTFHT02P400059399 |
| Reg. Date: | 21/06/2010 (Man. Year: 2010) | Odometer: | 305227 km |
| Colour: | Silver | | |
| Engine Capacity: | 2982 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-----------|------------------|--------------|
| Front Tyre Size: | 195 R15X8 | Rear Tyre Size: | 195 R15X8 |
| Front Left Side: | Giti 8 mm | Rear Left Side: | Journey 6 mm |
| Front Right Side: | Giti 8 mm | Rear Right Side: | Journey 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 4,142.35 | 2,649.10 | 1,493.25 | 36.05 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,012.50 | 1,365.00 | 647.50 | 32.17 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 6,154.85 | 4,014.10 | 2,140.75 | 34.78 |
| Approved Total (Overridden) (S\$) | | 3,200.00 | | |
| (S\$) | 6,154.85 | 3,200.00 | 2,954.85 | 48.01 |
| + GST 7.00/7.00% (S\$) | 430.84 | 224.00 | 206.84 | 48.01 |
| Nett Amount (S\$) | 6,585.69 | 3,424.00 | 3,161.69 | 48.01 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 02/08/2019 | |
| Date Inspected: | 02/08/2019 Inspected At: | Rhino Repairs Pte Ltd (HQ) 160 SIN MING DRIVE #03-14, SIN MING AUTOCITY Singapore 575722 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | |
|---|--|
| Reference | |
| Part Source: | (Last Synchronised: 18 Nov 2019) |
| Parts: | N/A TOYOTA HIACE 3.0 D (M) (Model not available in database) |
| Labour: | Repairer's (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBB7000U) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *TAIL GATE | Bent | 1,445.90 FL | *1,445.90 FL |
| 2 | 1 | | *TAIL GATE INNER TRIM | Serviceable | 210.20 FL | *- FL |
| 3 | 1 | | *TAIL GATE TOP LOCK | Repair | 412.50 FL | *- FL |
| 4 | 1 | | *TAIL GATE WEATHERSTRIP | Serviceable | 329.10 FL | *- FL |
| 5 | 1 | | *TAIL GATE LOGO | Necessary | 60.10 FL | *60.10 FL |
| 6 | 1 | | *TAIL GATE STICKER HIACE | Necessary | 65.20 FL | *65.20 FL |
| 7 | 1 | | *REAR BUMPER | Deformed | 422.50 FL | *422.50 FL |
| 8 | 2 | | *REAR BUMPER SIDE RETAINER | Serviceable | 160.20 FL | *- FL |
| 9 | 3 | | *REAR BUMPER LOWER BRACKET | Bent | 65.70 FL | *65.70 FL |
| 10 | 2 | | *REAR TAIL LAMP | Cracked | 605.60 FL | *605.60 FL |
| 11 | 1 | | *REAR TAIL LAMP PANEL RH | Repair | 145.10 FL | *- FL |
| 12 | 1 | | *REAR TAIL LAMP LOWER GARNISH | Serviceable | 231.60 FL | *- FL |
| 13 | 1 | | *REAR END PANEL OUTER | Bent | 445.80 FL | *445.80 FL |
| 14 | 1 | | *REAR END CONER PANEL RH | Repair | 358.30 FL | *- FL |
| 15 | 1 | | *TAIL GATE 70KM/H STICKER | Necessary | 20.00 FS | *20.00 FS |
| 16 | 1 | | *TAIL GATE WINDSCREEN SEALANT | Necessary | 50.00 FS | *40.00 FS |
| 17 | 8 | | *REAR BUMPER CLIPS | Necessary | 36.00 FS | *36.00 FS |
| 18 | 4 | | *REAR TAIL LAMP CLIPS | Not Necessary | 18.00 FS | *- FS |
| 19 | 1 | | *REAR REVERSE SENSOR | Mnlfuction | 280.00 FS | *200.00 FS |
| 20 | 1 | | *TAIL GATE 8PAX STICKER | Necessary | 20.00 FS | *20.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 5,381.80 | 3,426.80 |
| - List Item Discount on L Items 25.00/25.00% (S\$) | 1,239.45 | 777.70 |
| Total Parts (S\$) | 4,142.35 | 2,649.10 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS | New | 1,035.00 | 600.00 |
| 2 | PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL | New | 600.00 | 450.00 |
| 3 | APPLY RUST PROOFING ON THE ADJACENT PANELS | New | 60.00 | 60.00 |
| 4 | REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING | New | 76.50 | 50.00 |
| 5 | TRANSFER OF EXISTING TAILGATE MECHANISM | New | 81.00 | 60.00 |
| 6 | REMOVE AND REFIX TAILGATE REAR WINDSCREEN GLASS (2-MAN JOB) | New | 135.00 | 120.00 |
| 7 | WIRING / BULB CHECKING | New | 25.00 | 25.00 |
| Gross Labour Cost (S\$) | | | 2,012.50 | 1,365.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >