

22/03/2012

ASS. REC. BY:

REF: CS/MSG 19013540/V9F372

Special Instruction:

Surveior: MARCUS

ASSIGNMENT (Office)

From (Person): Muhammad Ashik B madi of MSG Date/Time: 2.8.19 10.47a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKM 1862 Insured: SKS 6389Jat Workshop m/s Nineteen Auto Vitez Tel: 94507920of Blk 19 F95 Bukit Road 4 # 01-53Policy No: 29120002 MCX Claim No: 607152

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 31.7.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 2.8.19 11.00a.m Person Contacted: Gilman H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKM 1862 - KA / QBE 19013485 / 24	D.O.A - 31/07/2019
	SKS 6389J - AD / QBE 19013485 / 24	D.O.A - 31/07/2019
03/8/19 @ 9.40am	Informed Muhi Ashik, we are pending estimate from repairer.	
11/8/19 @ 4.01pm	varised to Muhi Ashik via Message.	

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

msw/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

SKM186Z
Nissan

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

896

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

20

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

4653
Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

next day
LTA 67911 Dep. 15k 4yrs 5m.

11/9/19 confirmed L/S \$20,000 with £1m. (Red 23406.18, 54%)

RECEIVED 12 SEP 2019

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

20

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format:

MER-TP

Lump Sum / I.B.A. (\$

20000

TOTAL

250
11

261

12/9/2019

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 11 Sep 2019

Preliminary Advice

Insured Vehicle No	: SKS6389J	Accident Date	: 31/07/2019
TP Vehicle No	: SKM186Z	Assignment Date	: 02/08/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 20.00
Date of Inspection	: 02/08/2019		
Inspection At	: NINETEEN AUTOWERKS PTE LTD (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,406.18
Revised Amount	:S\$	25,601.73
Check Items (Estimated)	:S\$	0.00
Total	:S\$	25,601.73
Lump Sum Repair	:S\$	20,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2019		02 Aug 2019 10:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Precursor Investment, Co. Reg. No.: 53148578A								
Main Claimant:	GOH KIM HANN, ID: S7407465J								
Vehicle Reg. No.:	SKM186Z	Date of Loss:	31/07/2019 14:00 - :59						
Claim Type:	TP	Policy/Cover Note No.:	29120002MCX (TP, Fire & Theft) Coverage: 25/03/2019 - 24/03/2020						
Vehicle Reg. No. (Insured):	SKS6389J	Policy No. (Claimant):							
		Excess:							
Repairer:	Nineteen Autowerks Pte Ltd (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 94507920								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/08/2019]								
Adj Asg. Remarks:	on WP. Liab: Dispute(NR). Agree on SJE. Assign: Marcus from LKK Auto Consultants Pte Ltd. Contact: 9450 7920.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Monday, 5 August 2019 9:40 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SKM 186Z (YOUR POLICY NO.: 29120002MCX)

This mail is associated with :

***SKM186Z**

[SKS6389J]

TP

GOH KIM HANN

Jul 31 2019 2:00PM

[Precursor Investment]

Nineteen Autowerks Pte Ltd

Dear Muhd Ashik,

Please be informed that we have inspected the vehicle SKM 186Z on 02/08/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



ALL-NEW
Mercedes-Benz GLE450 AMG
Premium Plus

TEST DRIVE TODAY!

☎ 6250 6696 / 9637 5329

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



3.08-41.3 Sta Grade B No Major
Damage, 2 Year Warranty \$0
Down, Monthly Pm \$468
GV Credit Pte Ltd. Starbe

- Free VICOM evaluation
- Free grooming and 6 months
- In-house workshop ensures
- Member of SVTA and hire p
- 100% deposit refund for un

YONG LEE SEN
AutoMart Since 2002

[Browse by Category](#)
[Sort by Date Posted](#)

5 vehicles

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	toyota vellfire		Any	Any	2013	Any	Any	
	Toyota Vellfire 2.4A Z		\$82,800	\$15,220 /yr	13-Aug-2013	2,362 cc	95,912 km	
1 Owner! 7 Seater Vellfire! Versatile Usage For Corporate, Business Transport And Family Travelling. Luxurious Cabin Size And Very Comfortable Passenger Seats Arrangement. Call Us To Arrange To View Now!								
	Posted: 01-Aug-2019	Tags: 2013 Toyota Vellfire, 2013 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota						
	Toyota Vellfire 2.4A Z G-Edition		\$89,000	\$14,860 /yr	30-Dec-2013	2,362 cc	-	
Elegant Black MPV, One Owner Only, With Twin Moonroof, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In House Loan Available.								
	Prime Motor & Leasing							
	Posted: 26-Jul-2019	Tags: 2013 Toyota Vellfire, 2013 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota						
	Toyota Vellfire 2.4A Z G-Edition		\$82,800	\$15,320 /yr	28-May-2013	2,360 cc	89,906 km	
NDP Offer! High ARF! Low Deprecation! High Loan Are Available At Low Interest Rate! Twin Sunroof, Dual Power Sliding Doors, Rear Captain Seats, Keyless Entry/Start/Stop, Auto HID Headlights, LED Tail Lamp, Extended Premium Warranty Can Be Arranged For An Ad								
	Starise Automobile							
	Posted: 25-Jul-2019	Tags: 2013 Toyota Vellfire, 2013 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota						
	Toyota Vellfire 2.4A Z		\$86,888	\$15,650 /yr	23-Aug-2013	2,362 cc	-	
7 Seater Vellfire! All Receipts Proven! All Wear And Tear Parts Changed! Serviced Regularly! Versatile Usage For Corporate, Business Transport And Family Travelling. Luxurious Cabin Size And Very Comfortable Passenger Seats Arrangement. Call Us To Arrange To View								
	Posted: 23-Jul-2019	Tags: 2013 Toyota Vellfire, 2013 toyota vellfire, Toyota Vellfire, toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota						
	The Toyota Previa is the de facto MPV							
	The Toyota Previa is an MPV that excels with its space, practicality and a level of luxury some may not reach.							
	Find out more!							
	Toyota Vellfire 2.4A Z num Selection		\$76,800	\$15,640 /yr	18-Feb-2013	2,362 cc	-	

[Compare:](#)

N Regularly Maintained, Accident Free, Frozen Paintwork, One Of Its Kind. Owner Consigned, Owner Upgrading. Please Call Fr

Das WeltAuto.
Used cars you can trust. Guaranteed.

Visit the **sgCarMart Carnival @ Downtown East**
for exclusive deals on our certified pre-owned cars!
From 31 Aug to 1 Sep 2019



toyota vellfire

Price Range

Depreciation

2013

Vehicle Type



Home » Used Cars » Prime Motor & Leasing » Toyota Vellfire 2.4A Z G-Edition

Toyota Vellfire 2.4A Z G-Edition

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



PRIME MOTOR & LEASING



[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price \$89,000

Depreciation \$14,860 /yr
View models with similar depre

Reg Date 30-Dec-2013
(4yrs 4mths 24days COE left)

Mileage N.A.

Manufactured 2012

Road Tax \$1,638 /yr

Transmission Auto

Dereg Value \$71,297 as of today (change)

OMV \$39,380

COE \$87,001

ARF \$47,132

Engine Cap 2,362 cc

Power 125.0 kW (167 bhp)

Curb Weight 1,970 kg

No. of Owners 1

Type of Vehicle MPV

Features

Air, ABS, Powerful And Reliable 2.4L Inline 4 Cylinder Engine, Keyless Entry/Start, 2 Power Sliding Doors, Twin Moonroof.

Accessories

Leather Seats, Sports Rims, Audio System.

Description

Elegant Black MPV, One Owner Only, With Twin Moonroof, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In House Loan Available.

Category

PARF Car

Compare



Shortlist

Com

Report Error

M

Seller Information

Company

Prim

» deal

» 109

Address

5 Ben

Seard

Office No

6872

Contact Person(s)

Jack I

Eliz

Larry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	465J

Vehicle Details

Vehicle No.:	SKM186Z
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.4Z GOLDEN EYES A
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	2AZG226804
Chassis No.:	ANH208292826
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$39,426.00
Original Registration Date:	30 Dec 2013
First Registration Date:	30 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$47,197.00 23598

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2023
PARF Rebate Amount:	\$33,037.00

Intended COE Rebate Details

COE Expiry Date:	29 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,300.00
COE Rebate Amount:	\$34,874.00
Total Rebate Amount:	\$67,911.00

The information contained herein is correct as at 05 Aug 2019

OK



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

*not Authorized
Halter Tel: 62563561*

*2/5 @ 20.000
2/8/19 20 day.
the phb After repair*

2 August 2019

REG NO.: SKM 186 Z
MAKE/MODEL: TOYOTA VELLFIRE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION LIST ITEMS	AMT(\$)
1	Rear windscreen inner seal	\$ <i>rep</i> 85.00
1	Rear tailgate	\$ <i>body DO</i> 1,593.98
2	Rear tailgate dampers	\$ <i>11</i> 570.00
1	Rear tailgate inner board	\$ <i>del/for</i> 455.70
2	Rear tailgate lamps	\$ <i>cr</i> 882.96
1	Rear tailgate lock	\$ <i>rod/for</i> 350.90
1	Rear tailgate logo	\$ <i>rep</i> 64.96
1	Rear tailgate rubber	\$ <i>for</i> 300.40
1	Rear tailgate "Vellfire" emblem	\$ <i>rep</i> 75.76
1	Rear tailgate opening switch	\$ <i>11</i> 135.00
1	Rear tailgate number plate garnish <i>1055.10</i>	\$ <i>cr</i> 1,763.27
2	Rear taillamps <i>524.40 x 2 = 1048.80</i>	\$ <i>cr</i> 1,560.20
1	Rear end panel	\$ <i>body DO</i> 755.60
1	Rear end panel inner garnish	\$ <i>70.1</i> 265.90
1	Rear bumper <i>989.70</i>	\$ <i>D.S</i> 1,575.88
2	Rear bumper side <i>425.10 x 2 = 850.20</i>	\$ <i>del/for</i> 1,370.00
2	Rear bumper side brackets <i>66.50</i>	\$ <i>abs cr</i> 240.20
2	Rear bumper reflectors	\$ <i>11</i> 171.40
4	Rear bumper PDC sensors <i>265 x 3 = 795.00</i>	\$ <i>cr/stand</i> 2,081.20
1	Rear bumper sensor buzzer	\$ <i>11</i> 185.00
1	Rear bumper tow hook cover	\$ <i>de</i> 45.00
1	Rear smart keyless sensor	\$ <i>cr</i> 235.00
2	Rear fenders <i>1355.10</i>	\$ <i>del/for</i> 3,114.60
2	Rear fender inner garnishes <i>766.10 x 2 = 1532.20</i>	\$ <i>del/for</i> 2,323.26
1	Rear fender air vent	\$ <i>D.S</i> 62.00
2	Rear fender inner shields <i>98.10</i>	\$ <i>del/for</i> 290.00
2	Rear fender quarter glass with mouldings <i>300.70</i>	\$ <i>abs cr</i> 601.40
1	Rear spare tyre carriage	\$ <i>11</i> 275.00
1	Rear spare tyre carriage lock catch	\$ <i>11</i> 106.50
1	Rear floor panel	\$ <i>scrapped (Buc)</i> 985.00
1	Rear exhaust silencer	\$ <i>11</i> 625.69
2	Rear exhaust mountings	\$ <i>11</i> 71.78
1	Front bonnet	\$ <i>del/for</i> 899.40
2	Front bonnet hinges	\$ <i>for</i> 178.00
1	Front bonnet lock	\$ <i>for</i> 118.50
1	Front bonnet rubber <i>66.80</i>	\$ <i>rep</i> 122.40
2	Front headlamp assy <i>2265.50 x 2 = 4531.00</i>	\$ <i>cr</i> 8,486.80
2	Front headlamp center garnishes	\$ <i>11</i> 192.80
		\$ 33,216.44

LIST ITEMS

1	Front grille	761.10	\$	Cne	1,507.20	✓
1	Front grille logo		\$	11	155.80	x
1	Front bumper	1281.10	\$	12/2e	1,872.60	✓
2	Front bumper fog lamps		\$	11	763.80	x
2	Front bumper fog lamp covers		\$	11	363.50	x
1	Front bumper inner sponge		\$	To.11	181.50	✓
1	Front bumper lower grille	325.50	\$	11	681.50	✓
1	Front bumper reinforcement		\$	11	561.50	✓
2	Front bumper side retainers		\$	11	242.20	x
2	Front bumper tow hook covers	35x2=70	\$	ee	90.00	✓
2	Front bumper PDC sensors	265x2=530.00	\$	shub	1,040.60	✓
1	Front support panel		\$	11	1,518.50	x
1	Front support panel top garnish		\$	11	371.40	x
2	Front support panel side garnishes		\$	11	264.80	x
1	Air con condenser		\$	shub/2am	1,462.91	✓
1	Radiator	1910.10	\$	shub/2am	1,995.60	✓
1	Radiator fan assy		\$	811	1,185.00	x
1	Air intake duct		\$	11	118.25	x
1	Front wiper tank		\$	11	281.80	x
			\$		47,874.90	
			\$	Less 25%	11,968.73	
			\$		35,906.18	

2694897

SPECIAL NETT ITEMS

1	Rear windscreen sealant		\$	shu	80.00	40
1	Rear bumper clip (1 set)		\$	shu	50.00	✓
1	Rear reverse camera		\$	shub	480.00	350
1	Front bumper clip (1 set)		\$	shu	50.00	✓
1	Front number plate with holder		\$	shu	50.00	40
			\$		710.00	

S/NLABOUR CHARGES

1	To check wiring and reset headlamps focussing.	\$	80.00	30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	
3	To remove and refit inner garnishes.	\$	150.00	100
4	To remove and refit rear reverse sensor and camera.	\$	150.00	50
5	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00	80
6	To remove, replace air-con condenser, refill gas and conduct leakage test.	\$	180.00	100
7	To remove and refit rear windscreen glass.	\$	180.00	120
8	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	60
9	To apply undercoating.	\$	300.00	120
10	Panel beating.	\$	2,800.00	2200
11	To re-spray painting on the affected areas.	\$	2,600.00	2000
		\$	6,790.00	

28601.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to inspection
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GRAND TOTAL:

Acknowledged by Repairer: _____

Signature: _____

Date: _____

\$	43,406.18
----	-----------

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19013540/UQF3N2
Date: 17/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29120002
Claimant Vehicle No :	SKM186Z	Insured Vehicle No :	SKS6389J
Date of Loss:	31/07/2019	Nature of Claim:	TP
		Claim No:	602152

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM186Z	Engine No:	2AZG226804
Make & Model:	TOYOTA VELLFIRE, 2.4 Z (A)	Chassis No:	ANH208292826
Reg. Date:	30/12/2013 (Man. Year: 2013)	Odometer:	82889 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	36,616.17	20,741.73	15,874.44	43.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,790.00	4,860.00	1,930.00	28.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	43,406.17	25,601.73	17,804.44	41.02
Approved Total (Overridden) (\$\$)		20,000.00		
Nett Amount (\$\$)	43,406.17	20,000.00	23,406.17	53.92

INSPECTION

Date of Assignment:	02/08/2019	
Date Inspected:	02/08/2019	Inspected At:
		Nineteen Autowerks Pte Ltd (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE Singapore 417808
Estimated Period of Repair:	20.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2019)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 Z (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM186Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Necessary	85.00 FL	*85.00 FL
2	1		*REAR TAILGATE	Badly Dented	1,593.98 FL	*1,593.98 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	570.00 FL	*- FL
4	1		*REAR TAILGATE INNER BOARD	Deformed/Torn	455.70 FL	*455.70 FL
5	2		*REAR TAILGATE LAMPS	Cracked	882.96 FL	*882.96 FL
6	1		*REAR TAILGATE LOCK	Dented/Jammed	350.90 FL	*350.90 FL
7	1		*REAR TAILGATE LOGO	Necessary	64.96 FL	*64.96 FL
8	1		*REAR TAILGATE RUBBER	Twisted	300.40 FL	*300.40 FL
9	1		*REAR TAILGATE VELLFIRE EMBLEM	Necessary	75.76 FL	*75.76 FL
10	1		*REAR TAILGATE OPENING SWITCH	Not Necessary	135.00 FL	*- FL
11	1		*REAR TAILGATE NUMBER PLATE GARNISH	Cracked	1,763.27 FL	*1,055.10 FL
12	2		*REAR TAILLAMPS	Cracked	1,560.20 FL	*1,048.80 FL
13	1		*REAR END PANEL	Badly Dented	755.60 FL	*755.60 FL
14	1		*REAR END PANEL INNER GARNISH	Torn	265.90 FL	*265.90 FL
15	1		*REAR BUMPER	Distorted	1,575.88 FL	*989.70 FL
16	2		*REAR BUMPER SIDE	Deformed/Torn	1,370.00 FL	*850.20 FL
17	1		*REAR BUMPER SIDE BRACKETS	N/s Cracked	240.20 FL	*66.50 FL
18	2		*REAR BUMPER REFLECTORS	Not Necessary	171.40 FL	*- FL
19	1		*REAR BUMPER PDC SENSORS (4 Pcs)	Cracked/Shorted (3 Pcs only)	2,081.20 FL	*795.00 FL
20	1		*REAR BUMPER SENSOR BUZZER	Not Necessary	185.00 FL	*- FL
21	1		*REAR BUMPER TOW HOOK COVER	Deformed	45.00 FL	*45.00 FL
22	1		*REAR SMART KEYLESS SENSOR	Cracked	235.00 FL	*235.00 FL
23	1		*REAR FENDERS	N/s Badly Dented/O/s Repair	3,114.60 FL	*1,355.10 FL
24	2		*REAR FENDER INNER GARNISHES	Deformed/Torn	2,323.26 FL	*1,532.20 FL
25	1		*REAR FENDER AIR VENT	Distorted	62.00 FL	*62.00 FL
26	1		*REAR FENDER INNER SHIELDS	O/s Torn	290.00 FL	*98.10 FL
27	1		*REAR FENDER QUARTER GLASS WITH MOULDINGS	N/s Necessary	601.40 FL	*300.70 FL
28	1		*REAR SPARE TYRE CARRIAGE	Not Necessary	275.00 FL	*- FL
29	1		*REAR SPARE TYRE CARRIAGE LOCK CATCH	Not Necessary	106.50 FL	*- FL
30	1		*REAR FLOOR PANEL	Crumpled/Buckled	985.00 FL	*985.00 FL
31	1		*REAR EXHAUST SILENCER	Repair	625.69 FL	*- FL
32	2		*REAR EXHAUST MOUNTINGS	Not Necessary	71.78 FL	*- FL
33	1		*FRONT BONNET	Bent/Buckled	899.40 FL	*899.40 FL
34	2		*FRONT BONNET HINGES	Serviceable	178.00 FL	*- FL
35	1		*FRONT BONNET LOCK	Twisted	118.50 FL	*118.50 FL
36	1		*FRONT BONNET RUBBER	Necessary	122.40 FL	*66.80 FL
37	2		*FRONT HEADLAMP ASSY	Cracked	8,486.80 FL	*4,531.00 FL
38	2		*FRONT HEADLAMP CENTER GARNISHES	Not Necessary	192.80 FL	*- FL
39	1		*FRONT GRILLE	Cracked	1,507.20 FL	*761.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT GRILLE LOGO	Not Necessary	155.80 FL	*- FL
41	1		*FRONT BUMPER	Dented/Deformed	1,872.60 FL	*1,281.10 FL
42	2		*FRONT BUMPER FOG LAMPS	Not Necessary	763.80 FL	*- FL
43	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	363.50 FL	*- FL
44	1		*FRONT BUMPER INNER SPONGE	Torn	181.50 FL	*181.50 FL
45	1		*FRONT BUMPER LOWER GRILLE	Twisted	681.50 FL	*325.50 FL
46	1		*FRONT BUMPER REINFORCEMENT	Bent	561.50 FL	*561.50 FL
47	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	242.20 FL	*- FL
48	2		*FRONT BUMPER TOW HOOK COVERS	Deformed	90.00 FL	*70.00 FL
49	2		*FRONT BUMPER PDC SENSORS	Shorted	1,040.60 FL	*530.00 FL
50	1		*FRONT SUPPORT PANEL	Repair	1,518.50 FL	*- FL
51	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	371.40 FL	*- FL
52	2		*FRONT SUPPORT PANEL SIDE GARNISHES	Not Necessary	264.80 FL	*- FL
53	1		*AIR CON CONDENSER	Bent/Punctured	1,462.91 FL	*1,462.91 FL
54	1		*RADIATOR	Bent/Punctured	1,995.60 FL	*1,910.10 FL
55	1		*RADIATOR FAN ASSY	Serviceable	1,185.00 FL	*- FL
56	1		*AIR INTAKE DUCT	Not Necessary	118.25 FL	*- FL
57	1		*FRONT WIPER TANK	Not Necessary	281.80 FL	*- FL
58	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
59	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
60	1		*REAR REVERSE CAMERA	Shorted	480.00 FS	*350.00 FS
61	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
62	1		*FRONT NUMBER PLATE WITH HOLDER	Broken	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **48,584.90** **27,478.97**
 - List Item Discount on L Items 25.00/25.00% (S\$) 11,968.73 6,737.24

Total Parts (S\$) **36,616.17** **20,741.73**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	100.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	80.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS AND CONDUCT LEAKAGE TEST	New	180.00	100.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
8	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
9	TO APPLY UNDERCOATING	New	300.00	120.00
10	PANEL BEATING	New	2,800.00	2,200.00
11	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,600.00	2,000.00
Gross Labour Cost (S\$)			6,790.00	4,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >