

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19013559/AKA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SJT6975Z

Insured Vehicle No : SGQ498A

Date of Loss: 27/07/2019

Nature of Claim: TP

Claim No: 1789161889SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT6975Z**

Make & Model: MERCEDES-BENZ CLC180, 1.8 Kompressor (A)

Engine No: 27194631228049

Reg. Date: 27/10/2009 (Man. Year: 2009)

Chassis No: WDB2037462E071531

Colour: Bronze

Odometer: 143535 km

Engine Capacity: 1796 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,335.80	9,637.07	6,698.73	41.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	2,230.00	2,190.00	49.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,755.80	11,867.07	8,888.73	42.83
Approved Total (Overridden) (\$\$)		9,500.00		
(\$\$)	20,755.80	9,500.00	11,255.80	54.23
+ GST 7.00/7.00% (\$\$)	1,452.91	665.00	787.91	54.23
Nett Amount (\$\$)	22,208.71	10,165.00	12,043.71	54.23
+ Loss of Use (7.0 x S\$120.00/day) (\$\$)		840.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		11,012.45		
Global Sum Settlement (\$\$)		11,000.00		

INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 01/08/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,350.00 FL	*- FL
2	1		*BOOTLID OUTER PROTECTOR	Cracked	1,350.00 FL	*895.00 FL
3	1		*BOOTLID LOGO	Necessary	70.00 FL	*70.00 FL
4	1		*BOOTLID LOCK	Damaged	280.00 FL	*280.00 FL
5	1		*BOOTLID WEATHERSTRIP	Necessary	211.50 FL	*211.50 FL
6	1		*REAR BUMPER	Deformed	1,580.50 FL	*1,350.00 FL
7	2		*REAR BUMPER SIDE RETAINER	Necessary	185.00 FL	*185.00 FL
8	1		*REAR BUMPER LOWER LIP	Cut	530.00 FL	*530.00 FL
9	1		*REAR REINFORCEMENT BAR	Bent	811.50 FL	*687.00 FL
10	1		*REAR REINFORCEMENT BAR SPONGE	Cracked	230.00 FL	*230.00 FL
11	1		*REAR BUMPER TOWING COVER	Deformed	70.50 FL	*70.50 FL
12	1		*REAR BUMPER CENTER BRACKET	Cracked	211.40 FL	*211.40 FL
13	1		*REAR BUMPER CENTRE CHROME	Necessary	180.00 FL	*180.00 FL
14	2		*REAR BUMPER SIDE CHROME	Necessary	267.00 FL	*267.00 FL
15	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,280.00 FL	*560.00 FL
16	4		*REVERSE SENSOR RUBBER	Not Necessary	102.00 FL	*- FL
17	4		*REVERSE SENSOR HOLDER	Not Necessary	242.00 FL	*- FL
18	2		*TAIL LAMP	Cracked	1,645.00 FL	*1,645.00 FL
19	1		*TAIL LAMP LOWER BRACKET	Not Necessary	88.40 FL	*- FL
20	1		*REAR END PANEL	Dented	1,055.90 FL	*1,055.90 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	240.00 FL	*240.00 FL
22	1		*REAR FLOOR PANEL	Cracked	1,988.50 FL	*698.00 FL
23	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	530.00 FL	*- FL
24	1		*SPARE TYRE TRAY	Cracked	422.80 FL	*306.00 FL
25	1		*TOOLS COMPARTMENT	Not Necessary	320.00 FL	*- FL
26	1		*EXHAUST CHROME TIP	Bent	420.00 FL	*180.00 FL
27	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
28	1		*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*BOOT LID STICKER	Necessary	500.00 FS	*300.00 FS
30	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
31	1		*REAR BUMPER STICKER	Necessary	500.00 FS	*350.00 FS
32	1		*SET TAIL LAMP CLIP	Necessary	20.00 FS	*20.00 FS
33	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	20.00 FS	*20.00 FS
34	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,002.00	10,622.30
- List Item Discount on L Items 10.00/10.00% (S\$)	1,666.20	985.23
Total Parts (S\$)	16,335.80	9,637.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,WELD ,CUT ,KNOCK ,STRAIGHTEN ,ADJUST GRAZE JOIN	New	1,600.00	1,000.00
2	TO PUTTY ,SPRAY PAINT ,POLISH ,WAX AFFECTED PARTS AND PANELS	New	1,400.00	900.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	150.00	80.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	TRANFER BOOTLID MECHANISM	New	80.00	0.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	60.00
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	180.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	480.00	100.00
Gross Labour Cost (\$)			4,420.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >