

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19013561/KEA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJS6149Y	Insured Vehicle No :	SHB4445T
Date of Loss: 26/07/2019	Nature of Claim: TP	Claim No: MCT19070696

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS6149Y		
Make & Model:	KIA CERATO FORTE, 1.6 (A)	Engine No:	G4FC9H286217
Reg. Date:	26/08/2009 (Man. Year: 2009)	Chassis No:	KNAFW411MA5114830
Colour:	Metallic Black	Odometer:	142015 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 2 mm	Rear Left Side:	Michelin 2 mm
Front Right Side:	Michelin 2 mm	Rear Right Side:	Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,675.06	7,114.32	3,560.74	33.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	2,880.00	420.00	12.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,975.06	9,994.32	3,980.74	28.48
Approved Total (Overridden) (\$\$)		8,000.00		
Nett Amount (\$\$)	13,975.06	8,000.00	5,975.06	42.76
+ Loss of Use (16.0 x S\$60.00/day) (\$\$)		960.00		
Nett Liability (\$\$)		8,960.00		
Global Sum Settlement (\$\$)		7,960.00		

INSPECTION

Date of Assignment:	31/07/2019	
Date Inspected:	02/08/2019 Inspected At:	LKW AUTO SERVICES 176 SIN MING AUTOCARE DRIVE #02-01 SINGAPORE 575721
Estimated Period of Repair:	11.0 days	

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$25,000

LTA REBATE: \$12,992

NETT VALUE: \$12,008

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2020)
Parts:	144	KIA CERATO FORTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS6149Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Bent	965.80 FL	*965.80 FL
2	1	*REAR BOOT LOCK	Jammed	186.40 FL	*135.00 FL
3	1	*REAR BOOT LOCK CATCH	Repair	76.30 FL	*- FL
4	1	*REAR BOOT WEATHERSTRIP (50%)	Distorted / Dented	293.85 FS	*71.30 FS
5	1	*REAR BOOT EMBLEM CERATO	Necessary	82.40 FL	*82.40 FL
6	1	*REAR BOOT EMBLEM FORTE	Necessary	67.30 FL	*67.30 FL
7	1	*REAR BOOT EMBLEM LOGO	Necessary	75.20 FL	*75.20 FL
8	2	*REAR BOOT LAMP ASSY	Serviceable	617.00 FL	*- FL
9	2	*REAR BOOT HINGE	Repair	373.40 FL	*- FL
10	2	*REAR TAIL LAMP ASSY	Mtg Distorted	672.60 FL	*672.60 FL
11	2	*REAR FENDER	Buckled	1,952.80 FL	*1,854.00 FL
12	1	*REAR END PANEL	Bent	486.20 FL	*486.20 FL
13	1	*REAR END PANEL GARNISH	Dented	263.90 FL	*169.20 FL
14	1	*REAR WINDSCREEN GLASS MOULDING	Necessary	215.00 FL	*121.00 FL
15	1	*REAR EXHAUST SILENCER	Bent	793.60 FL	*686.00 FL
16	1	*REAR BUMPER	Bent	759.80 FL	*759.80 FL
17	1	*REAR BUMPER LOWER DISFUSER	Distorted	576.00 FL	*421.00 FL
18	12	*REAR BUMPER CLIP	Necessary	45.60 FL	*45.60 FL
19	4	*REAR BUMPER REVERSE SENSOR	Shorted (2 PCS ONLY)	1,460.00 FL	*440.00 FL
20	4	*REAR BUMPER REVERSE SENSOR HOLDER	Serviceable	138.80 FL	*- FL
21	1	*REAR BUMPER REINFORCEMENT	Bent	386.20 FL	*285.00 FL
22	2	*REAR BUMPER SIDE RETAINER	Distorted	128.40 FL	*128.40 FL
23	2	*REAR BUMPER CORNER RETAINER	Serviceable	174.20 FL	*- FL
24	1	*BUMPER FOAM	Cracked	186.30 FL	*186.30 FL
25	1	*SPARE TYRE PANEL	Repair	386.90 FL	*- FL
26	1	*EXHAUST HEAT SHIELD	Bent	286.80 FL	*117.00 FL
27	1	*REAR NUMBER PLATE }	Dented	35.00 FS	*45.00 FS
28	1	*REAR NUMBER PLATE CASING }	Dented	35.00 FS	*- FS
29	1	*REAR BOOT EMBLEM C&C	Necessary	30.00 FS	*30.00 FS
30	1	*WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,810.75	7,884.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,135.69	769.78

Total Parts (\$\$)	10,675.06	7,114.32
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,300.00	1,200.00
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	150.00	120.00
4	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,350.00	1,200.00
5	TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR	New	100.00	100.00
6	TO REMOVE & REINSTALL REAR WINDSCREEN GLASS	New	140.00	120.00
7	TO INSTALL REVERSE SENSORS	New	80.00	60.00
8	TO CARRY OUT EXHAUST WORKS	New	80.00	60.00
9	TOWING CHARGES	New	50.00	0.00
Gross Labour Cost (\$\$)			3,300.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >