



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101442

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/03/2021
Reference CC6/CTI19013584/Aba3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLL 722U
Insured Veh. GBB 3528R
Claim No. SNM19D203629
Policy No. DMCVSN1915271900
Accident Date 31/07/2019
Inspection Date 01/08/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI19013584/Aba3q2	
			Date: 09/03/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 3528R	Veh. Inspected	SLL 722U	
Policy No.	DMCVSN1915271900	Coverage (\$)	0.00	
Claim No.	SNM19D203629	Excess (\$)	0.00	
Assign From		Assign Date	01/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRC1890GC208928	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/07/2019	Inspection Date	01/08/2019	
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			16 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 722U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	631.20	631.20
1	REAR BUMPER RETAINER RH	NECESSARY	45.00	45.00
1	REAR BUMPER TOP GARNISH RH	TO REPAIR SEE LABOUR	86.80	-
1	REAR BUMPER TOP GARNISH BRACKET RH	NOT NECESSARY	65.00	-
1	REAR BUMPER SENSOR RH	NOT NECESSARY	260.00	-
10	REAR BUMPER CLIP	NECESSARY	80.00	30.00
1	REAR TAIL LAMP RH	CUT	821.80	821.80
1	REAR TAIL LAMP BRACKET RH	NOT NECESSARY	55.20	-
1	REAR FENDER RH	DISTORTED	1,223.80	1,223.80
1	REAR FENDER GLASS C/W MOULDING RH	NOT NECESSARY	448.20	-
1	REAR FENDER SLIDER MECH RH	NOT NECESSARY	256.70	-
1	REAR DOOR RH	DISTORTED	1,185.50	1,185.50
1	REAR DOOR LOWER OUTER GARNISH RH	DISTORTED	363.80	363.80
8	REAR DOOR LOWER OUTER GARNISH CLIP RH	NECESSARY	40.00	30.00
1	ROCKER PANEL	TO REPAIR SEE LABOUR	585.20	-
2	ROCKER PANEL FRT AND REAR COVER RH	DEFORMED	163.40	163.40
1	ROCKER PANEL COVER RH	DEFORMED	622.10	622.10
10	ROCKER PANEL COVER CLIP RH	NECESSARY	80.00	30.00
1	REAR DOOR OUTER HANDLE RH	CUT	97.10	97.10
1	REAR DOOR OUTER HANDLE COVER RH	CUT	55.60	55.60
1	REAR DOOR OUTER WINDOW GARNISH (CHROME) RH	NOT NECESSARY	291.30	-
1	REAR DOOR INNER TRIM RH	NOT NECESSARY	790.00	-
1	REAR DOOR INNER LOC RH	NOT NECESSARY	861.70	-
1	REAR DOOR INNER LOCK CATCH RH	NOT NECESSARY	37.70	-
1	REAR DOOR INNER SILDER CATCH RH	NOT NECESSARY	21.60	-
1	REAR DOOR W/POWER MOTOR RH	NOT NECESSARY	492.30	-
1	REAR DOOR W/STRIP RH	NECESSARY	164.20	164.20
1	REAR DOOR REGULATOR RH	DAMAGED	492.30	492.30
1	CENTER PILLAR RH	TO REPAIR SEE LABOUR	964.00	-

Report Ref No. CC6/CTI19013584/Aba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CENTER PILLAR INNER TRIM UPPER RH	NOT NECESSARY	98.20	-
1	CENTER PILLAR INNER TRIM LOWER RH	NOT NECESSARY	83.30	-
1	SEAT BELT RH	NOT NECESSARY	478.60	-
1	FRT DOOR PILLAR RH	TO REPAIR SEE LABOUR	862.70	-
1	FRT DOOR RH	DISTORTED	985.20	985.20
1	FRT DOOR LOWER OUTER GARNISH RH	DEFORMED	289.70	289.70
8	FRT DOOR LOWER OUTER GARNISH CLIP RH	NECESSARY	40.00	30.00
1	FRT DOOR OUTER WINDOW GARNISH (CHROME) RH	CRACKED	282.70	282.70
1	FRT DOOR OUTER HANDLE WITH SENSOR RH	DAMAGED	325.90	325.90
1	FRT DOOR OUTER HANDLE COVER RH	CUT	75.80	75.80
1	FRT DOOR WINDOW GLASS RH	SHATTERED	564.50	564.50
1	FRT DOOR WINDOW REGULATOR RH	DAMAGED	492.30	492.30
1	FRT DOOR W/STRIP RH	NECESSARY	164.20	164.20
1	FRT DOOR INNER TRIM BOARD RH	DEFORMED	797.60	797.60
1	FRT DOOR W/POWER MOTOR RH	NOT NECESSARY	492.30	-
1	FRT DOOR INNER LOCK RH	JAMMED	335.60	335.60
1	FRT DOOR INNER LOCK CATCH RH	NOT NECESSARY	35.60	-
1	FRT DOOR 1/4 WINDOW GLASS	SHATTERED	397.60	397.60
1	FRT DOOR UPPER HINGE RH	NECESSARY	48.60	48.60
1	FRT DOOR LOWER HINGR RH	BENT	48.60	48.60
1	FRT DOOR CHECKER RH	BENT	52.80	52.80
1	FRT DOOR W/STRIP RH	REPEATED	126.20	-
1	FRT SIDE MIRROR ASSY RH	DISTORTED	692.80	692.80
1	FRT FENDER RH	DISTORTED	598.40	598.40
1	FRT FENDER OUTER TRIM (CHROME) RH	DEFORMED	187.70	187.70
1	FRT FENDER COWLING RH	DEFORMED	145.70	145.70
10	FRT FENDER COWLING CLIP RH	NECESSARY	80.00	30.00
1	FRT FENDER INNER PANEL RH	TO REPAIR SEE LABOUR	422.90	-
1	FRT W/SCREEN GLASS C/W MOULDING	NOT NECESSARY	2,682.60	-
1	FRT ABSORBER RH	BENT	382.10	382.10
1	FRT KNUCKLE RH	BENT	298.40	298.40
1	FRT KNUCKLE BEARING RH	DAMAGED	165.80	165.80

Report Ref No. CC6/CTI19013584/Aba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT LOWER ARM RH	BENT	676.30	335.00
1	FRT DRIVE SHAFT RH	NOT NECESSARY	1,229.10	-
1	FRT CROSS MEMBER	NOT NECESSARY	1,363.70	-
1	STRG BACK AND PINION	NOT NECESSARY	4,659.20	-
1	DASHBOARD CENTER BEAM	NOT NECESSARY	573.90	-
1	DASHBOARD	NOT NECESSARY	979.80	-
1	FRT H/LAMP RH	CRACKED	2,581.20	2,237.00
1	FRT H/LAMP BRACKET RH	NOT NECESSARY	64.90	-
1	FRT BUMPER	TO REPAIR SEE LABOUR	789.20	-
1	FRT BUMPER RETAINER RH	NOT NECESSARY	41.80	-
10	FRONT BUMPER CLIP	NECESSARY	80.00	30.00
1	REAR ABSORBER RH	NOT NECESSARY	391.00	-
1	REAR KNUCKLE RH (NPA)	NOT NECESSARY	-	-
1	REAR KNUCKLE BEARING RH	DAMAGED	360.40	360.40
1	REAR LOWER ARM RH (NPA)	NOT NECESSARY	-	-
1	REAR AXLE	NOT NECESSARY	1,611.20	-
1	STEERING WHEEL	DAMAGED	1,890.00	990.00
	LESS 20% DISCOUNT		-8,261.52	-3,460.04
			33,046.08	13,840.16
1	FRT RIM RH (SN)	CUT	965.00	680.00
1	REAR RIM RH (SN)	CUT	965.00	680.00
	LESS 20% DISCOUNT		-386.00	-
			1,544.00	1,360.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDOW GLASS SEALANT RH (SN)	NOT NECESSARY	80.00	-
1	1/4 WINDOW GLASS SEALANT RH (SN)	NECESSARY	80.00	50.00
1	FRT W/S GLASS TINTED FILM (SN)	NOT NECESSARY	450.00	-
1	FRT DOOR GLASS TINTED FILM RH (SN)	NECESSARY	150.00	100.00
1	REAR DOOR GLASS TINTED FILM RH (SN)	NOT NECESSARY	150.00	-
1	REAR FENDER GLASS TINTED FILM RH (SN)	NOT NECESSARY	150.00	-
1	REAR FENDER SEALANT RH (SN)	NECESSARY	80.00	50.00

Report Ref No. CC6/CTI19013584/Aba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL SEALANT RH (SN)	NOT NECESSARY	80.00	-
1	FRT DOOR PILLAR SEALANT RH (SN)	NOT NECESSARY	80.00	-
1	FRT TYRE RH (SN)	NOT NECESSARY	280.00	-
1	REAR TYRE RH (SN)	NOT NECESSARY	280.00	-
1	ERP BRACKET (SN)	NOT NECESSARY	25.00	-
			1,885.00	200.00
	LABOUR			
	TO KNOCK ,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA.		2,800.00	1,600.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		2,200.00	1,600.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.		150.00	100.00
	TO R&R FRONT AND REAR DOOR PARTS.		240.00	160.00
	TO R&R FRONT AND REAR UNDER CARRIAGE.		600.00	480.00
	TO CHECK AND ALIGN FOUR WHEEL ALIGNMENT .		150.00	80.00
	TO REPROGRAM AND REDIANOS STEERING SENSOR AND FAULT CODE.	NOT NECESSARY	350.00	-
	TO R&R H/LAMP AND CHECK FOCUS.		80.00	60.00
	TO R&R UPHOLSTERY & ATTACHMENT PARTS.		400.00	150.00
	TO R&R FRT W/SCREEN GLASS .	NOT NECESSARY	150.00	-
	TO R&R RR LUGGAGE COMPARTMENT.		120.00	60.00
	TO CHECK CHASSIS ALIGNMENT.	NOT NECESSARY	400.00	-
	TO REMOVE SHUTTER GLASS & VACUUM INTERIOR.		180.00	80.00
			7,820.00	4,370.00
GRAND TOTAL			44,295.08	19,770.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,800.00

Report Ref No. CC6/CTI19013584/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 722U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 722U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 722U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 722U

RE-INSPECTION

