

2019/08/01

ASS. REC. BY:

REF: 083/MSG 19013632/R190307

Special Instruction:

Surveyor: Ravi

ASSIGNMENT (Office)

From Person: Pauline them

of MSL

Date/Time: 28/08/2019

Estimated Cost:

Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT2636E

Insured: SML 689DR

at Workshop in/s: JCM Rental

Tel: 6734 3438

of 1 Bukit Batok Crescent #04-47

Policy No: 29126726AVW

Claim No: 601FF8

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11/07/2019

Person Contacted:

Mr. Meng

Vehicle: IN DUT

Date/Time	Action/Instruction	Signature
	<u>SLT2636E - 03/MSG/19013632/04/07/2</u>	<u>28/08/2019</u>
	<u>SML 689DR - X</u>	

* Billing PRS + PS.

28/10/19 Submit Final Prg \$1300, 5 days (Red \$4050, 76%)

* Reopen ref. for amend report to us \$3000 / 7 days.

After surveyor, Ravi reviewed the video footage.

(Red \$2750, 44%)

→ viewing the video matter

* Our surveyor after reviewed the video footage is adjusted the repair cost.

29/11/19

pas

Pass

659M
COR XRAY: 2025/APR

2009 CLR

SLT 2636E

SLT 2636G
JCM RENTAL

BURR BRICK CRG CENT #04-47
MS16

HYUNDAI I30 1.6 A 1591

GRGY

155885

KMHDCSIDMAU 218626

100% 100% 100% 100%

100% 100% 100% 100%

100% 100% 100% 100%

100% 100% 100% 100%

100% 100% 100% 100%

100%

BS/DUN/EXNGVA/GR/PS/LAZA/MPL/CHTSU/MRISUM

TOYO/YOKO

WESTAKE

Food

5

5

31/07/19

Driver held at

JCM RENTAL

Des of Damages: Frnt / Rear / C-S / R/C / Roof/Rail

1% UIC / Chassis frame / Body Structure / Fuel/Idle / Air/Brk

RECEIVED 22 OCT 2019

Do Not Finalise

Check the status of the report

☐

Final Report

☐

Final Report

Days of Repair

Highway No. of Trip

Add Fuel

☐

214.00

☐

214.00

☐

214.00

☐

214.00

Report Format

Lump Sum

mer
PRG. TP
1300

120
80

11

211

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	659M
Vehicle Details	
Vehicle No.:	SLT2636E
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Aug 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 (FD) 1.6 DOHC AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U747733
Chassis No.:	KMHDC51DMAU218626
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$13,393.00
Original Registration Date:	29 Oct 2009
First Registration Date:	29 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$13,393.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Oct 2019
PARF Rebate Amount:	\$6,696.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$26,175.00
COE Rebate Amount:	\$25,484.00
Total Rebate Amount:	\$32,180.00

The information contained herein is correct as at 05 Aug 2019

OK

Shiau Chan (LKKAuto)

From: Pauline Tham <pauline_tham@sg.msig-asia.com>
Sent: Friday, 6 December 2019 5:50 PM
To: Bryan Ang (LKKAuto); SUR
Subject: RE: Yref : GS/19/4448/JCM/JP/YM - SLT2636E, OREF : 601778

Dear Byran

Thanks for the prompt reply

Kindly expedite on the survey report.

Thanks.

Pauline Tham

Senior Executive, Claims Services, Motor

D: +65 6594 2545 | F: +65 6225 7402 | pauline_tham@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Sent: Friday, 6 December 2019 5:19 PM
To: Pauline Tham <pauline_tham@sg.msig-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: Yref : GS/19/4448/JCM/JP/YM - SLT2636E, OREF : 601778

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Pauline

Have reviewed the video recording, the contact between insured vehicle and the TP vehicle started from the left front of TP vehicle stretching towards the left rear of TP vehicle.

Dear Shiau Chan

Please get surveyor to review the adjustment in our survey report and re-adjust accordingly if necessary.

If our surveyor is of the view that no adjustment is required, than please update Pauline.

Our ref: CS3/MSG19013632/R1qd3e2

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pauline Tham <pauline_tham@sg.msig-asia.com>

Sent: Friday, 6 December 2019 4:25 PM

To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: assignments <assignments@lkkauto.com>

Subject: RE: Yref : GS/19/4448/JCM/JP/YM - SLT2636E, OREF : 601778

Importance: High

Dear Bryan

Third party submitted that video footage for our view (in merimen).

Please let us know if there is a need for survey report amendment.

Thanks.

Pauline Tham

Senior Executive, Claims Services, Motor

D: +65 6594 2545 | F: +65 6225 7402 | pauline_tham@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Pauline Tham

Sent: Monday, 21 October 2019 9:08 AM

To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: assignments <assignments@lkkauto.com>

Subject: RE: Yref : GS/19/4448/JCM/JP/YM - SLT2636E, OREF : 601778

Dear Sir

Please upload paper survey report asap.

Thanks.

Pauline Tham

Senior Executive, Claims Services, Motor

D: +65 6594 2545 | F: +65 6225 7402 | pauline_tham@sg.msig-asia.com

Precise Appraiser Pte Ltd

Reg no. 201924041Z

VEHICLE DAMAGE ASSESSMENT REPORT

To: JCM Rental Pte Ltd

CC: TCRP Pte Ltd
1 Bukit Batok Crescent #04-47
WCEGA Plaza
Singapore 658064

REFERENCES

Ref No	: 2009/0006	Date of Report	: 5/8/2019
Claim Type	: Third Party	Date of Request	: 11/7/2019
Third party vehicle	: SLT2636E	Date of Accident	: 11/7/2017
Insured Vehicle	:	Date of Inspection	: 1/8/2019
Your Reference No	:		

DAMAGED VEHICLE PARTICULARS

Registration Plate No	: SLT2636E	Engine Modification	: NIL
Model / Make	: Hyundai i30	Pre-accident damage	: NIL
Colour	: Silver	General Condition	: Good
Manufacturing Year	: 2009	General Paint Work	: Good
Engine No	: G4FCHU747733	Steering	: Serviceable
Engine Capacity	: 1600cc	Handbrake	: Serviceable
Chassis No	: KMH10CS1DMAU118626	Footbrake	: Serviceable
Odometer No	: 115864		
Transmission	: Auto		

TYRES CONDITION

Front Right		Rear Left	
Make	: Continental	Make	: Bridgestone
Size	: 205/60 R16	Size	: 205/60 R16
Front Left		Rear Right	
Make	: Continental	Make	: Bridgestone
Size	: 205/60 R16	Size	: 205/60 R16

The above millimetres represent the remaining life of tyre treads

VEHICLE REPAIR COST


Descriptions	Repairer (\$\$)	Difference (\$\$)	Adjuster (\$\$)
Parts	5,707.68		2,701.84
Labour	5,480.00		3,980.00
Calculated Cost (\$\$):	11,187.68	4,503.84	6,683.84

Recommended Lump Sum Repair Cost (\$\$)
Estimate Repair Duration
Survey Inspection At
Survey Inspection Address

: 5,350.00
: 9
: TCRP Pte Ltd
: 1 Bukit Batok Crescent #04-47
: WCEGA Plaza
: Singapore 658064

DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the L.H. portion. Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated 9 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs



Automotive Appraiser
MSAAA

Disclaimer

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle. All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

Our Reference: 2009/0006

Your Reference:

Vehicle Number: 5LT2636E

S/N	Qty	Description	Condition	Repairer Estimate (\$)	Our Assessment (\$)
Parts					
1	1pcs	Front bumper Repair	Holder torn	435	435 X
2	1pcs	Front bumper lh retainer Xsvc	Torn	25.9	25.9 X
3	1pcs	LH headlamp SCR	Base crack	606.2	606.2
4	2pcs	Front lh fender	Dented	559	559
5	1pcs	Front lh fender inner shield Xsvc	Deformed	56.5	56.5 X
6	1pcs	Support panel Xan	Serviceable	836.9	-
7	1pcs	Front lh shock absorber Xsvc	Bent	246.3	246.3 X
8	1pcs	Front lh knuckle arm	Bent	309	309
9	1pcs	Front lh knuckle bearing	Necessary	135.9	135.9
10	1pcs	Front lh wheel hub	Warp	167.9	167.9
11	1pcs	Steering rack Xsvc	Serviceable	872.9	-
12	1pcs	Cross member Xsvc	Serviceable	1920	-
13	1pcs	Front lower arm SVC X	Bent	301.6	301.6 X
14	1pcs	Front lower arm ball joint Xsvc	Warp	92.4	92.4 X
15	1pcs	Front lh anti roll bar link Xsvc	Serviceable	69.1	69.1 X
Total				6634.6	3004.8
Less 20%				1326.92	600.96
Parts Sub Total				5307.68	2403.84

1778
20%
1422.40

Special Nett

29	1pcs	Front LH sport Rim	Scarp	400	300
Total				400	300

SCR

300

Labour					
2		To check wiring system	80	30	
		To R&R front LH undercarriage	600	100	
6		To conduct wheel alignment	200	60	
8		To panel beat on front LH fender inner panel, front LH door and rear LH door. To R&R front and rear bumper and others attachments.	2500	600	
9		To respray on front bumper, front LH door, Rear LH door, Rear LH fender, Rear bumper and accident affected area	2000	1200	
8		Rust proofing	100	60	
Labour Total			5480	3980	
Sub Total (labour and parts)			11187.68	6583.84	

2050

1422.40

300.00

2050.00

3772.40

20%

3017.92

45-3000

7 days

[Signature]
2/10/2019

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19013632/R1QD3E2

Date: 12/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29126726AVW

Claimant

Vehicle No : SLT2636E

Insured Vehicle No : SML6890R

Date of Loss: 31/07/2019

Nature of Claim: TP

Claim No: 601778

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT2636E

Make & Model: HYUNDAI I30 (FD), 1.6 DOHC (A)

Engine No: G4FC9U747733

Reg. Date: 29/10/2009 (Man. Year: 2009)

Chassis No: KMHDC51DMAU218626

Colour: Grey

Odometer: 155885 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,707.68	1,722.40	3,985.28	69.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	2,050.00	3,430.00	62.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,187.68	3,772.40	7,415.28	66.28
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	11,187.68	3,000.00	8,187.68	73.18

INSPECTION

Date of Assignment: 05/08/2019

Date Inspected: 05/08/2019 Inspected At:

JCM Rental Pte Ltd (HQ)
1 Bukit Batok Crescent, #04-47
Wcega Plaza
Singapore 658064

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: OUR SURVEYOR AFTER VIEWING THE VIDEO & RE-ADJUSTED THE REPAIR COST.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2019)
Parts:	144	HYUNDAI I30 (FD) 1.6 DOHC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT2636E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	435.00 FL	*- FL
2	1		*FRONT BUMPER LH RETAINER	Serviceable	25.90 FL	*- FL
3	1		*LH HEADLAMP	Scratched	606.20 FL	*606.20 FL
4	2		*FRONT LH FENDER	Bent	559.00 FL	*559.00 FL
5	1		*FRONT LH FENDER INNER SHIELD	Serviceable	56.50 FL	*- FL
6	1		*SUPPORT PANEL	Not Necessary	836.90 FL	*- FL
7	1		*FRONT LH SHOCK ABSORBER	Serviceable	246.30 FL	*- FL
8	1		*FRONT LH KNUCKLE ARM	Bent	309.00 FL	*309.00 FL
9	1		*FRONT LH KNUCKLE BEARING	Bent	135.90 FL	*135.90 FL
10	1		*FRONT LH WHEEL HUB	Bent	167.90 FL	*167.90 FL
11	1		*STEERING RACK	Serviceable	872.90 FL	*- FL
12	1		*CROSS MEMBER	Serviceable	1,920.00 FL	*- FL
13	1		*FRONT LOWER ARM	Serviceable	301.60 FL	*- FL
14	1		*FRONT LOWER ARM BALL JOINT	Serviceable	92.40 FL	*- FL
15	1		*FRONT LH ANTI ROLL BAR LINK	Serviceable	69.10 FL	*- FL
16	1		*FRONT LH SPORT RIM	Scratched	400.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,034.60	2,078.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,326.92	355.60
Total Parts (S\$)	5,707.68	1,722.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	80.00	30.00
2	TO CONDUCT WHEEL ALIGNMENT	New	200.00	60.00
3	TO PANEL BEAT ON FRONT LH FENDER INNER PANEL, FRONT LH DOOR AND REAR LH DOOR. TO R&R FRONT AND REAR BUMPER AND OTHERS ATTACHMENTS	New	2,500.00	600.00
4	TO RESPRAY ON FRONT BUMPER, FRONT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER AND ACCIDENT AFFECTED AREA	New	2,000.00	1,200.00
5	RUST PROOFING	New	100.00	60.00
6	TO R&R FRONT LH UNDERCARRIAGE	New	600.00	100.00
Gross Labour Cost (\$\$)			5,480.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >