

ASS. REC. BY:

REF: CS/FCI 19013634/Ad3⁰²

Special Instruction:

Assignee: Adnan

ASSIGNMENT (Office)

From (Person): Sithara

of FCI

Date/Time: 10:22am @ 5/8/19

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: QBD 7351X

Insured: SHC 7473L

at Workshop m/s Keng Car Repairs

Tel: 6747 7636

of 1 Kaki Bukit Ave 6 # 02-06

Policy No:

Claim No: D.1900 5038 MF3H

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 30/7/2019

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 11:39am @ 5/8/19

Person Contacted: Sharon

Vehicle ID: (LOFT)

Date/Time	Action/Instruction
	Rehman ✓
	QBD 7351X - X
	SHC 7473L - X
21/8-11:54am	pending estimate sent via email.
	lump sum \$1400f (Red: 1226.87; 46%)
	3days

MOTOR SURVEY ASSIGNMENT

Date	02-08-2019	Our Ref No. D19005038MFSH
Accident Date	30-07-2019	Claim Type. Third Party
Insured Vehicle	SHC7473L	Third Party Vehicle. GBD7351X
Survey Location	1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT	
Contact Person.	SHARON	
Contact No.	67477636/ 0	Fax No. 67485071
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KANG CAR REPAIRERS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 21 August 2019 11:54 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005038MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBD 7351X on 20/08/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 5 August 2019 11:51 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005038MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 5 August 2019 10:22 AM
To: ASSIGNMENTS@LKKAUTO.COM

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@r Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848 FAX: 65073849
 ATTN: Motor Claim Department

Estimate No: EST1900238
 Date: 02 Aug 2019

Veh Reg No: GBD7351X
 Make/Model: TOYOTA
 DYNA3.0DIESEL TURBO
 M/T2WDLORRY

Chasis No: KDY2318018052
 Reg. Date: 30/03/2015
 Your Ref No: SHC7473L

Claim Type: Third Party
 Accident Date: 30/07/2019
 TP Veh Reg No: SHC7473L

Dense.

Estimate Repair Cost to Vehicle No :GBD7351X

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC TAIL LAMP - RH <i>crack d</i>	286.70 ✓	
2	1 PC TAIL LAMP PANEL RH <i>Dented</i>	179.10 ✓	
3	1 PC TAIL GATE LOCK RH <i>Best.</i>	166.40 ✓	
4	1 PC TAIL GATE LOWER PANEL <i>Repair</i> 771	424.80 +	
5	1 PC TAIL GATE LOCK RH BRACKET <i>Best</i> 578.25	79.10 -	
6	1 PC TAIL GATE LOCK RH RUBBER <i>cut</i>	21.30 -	
7	1 PC TAIL GATE REFLECTOR - RH <i>crack d</i>	38.40 -	
		1,195.80	85
		Less 25%	298.95
			896.87
Special Net			
8	1 PC REAR NUMBER PLATE <i>new</i>	50.00 +	
9	1 SET REVERSE SENSORS <i>new d</i> 200	250.00 200	
		300.00	300.00
Labour			
10	1 TO CHECK WIRING 980	50.00 30	
11	1 (REAR) TO SPRAY PAINTING	700.00 500	
12	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00 400	
13	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
		1,430.00	1,430.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department

Estimate No: EST1900238
Date: 02 Aug 2019

Veh Reg No: GBD7351X
Make/Model: TOYOTA
DYNA3.0DIESEL TURBO
M/T2WDLORRY

Chassis No: KDY2318018052
Reg. Date: 30/03/2015
Your Ref No: SHC7473L

Claim Type: Third Party
Accident Date: 30/07/2019
TP Veh Reg No: SHC7473L

Estimate Repair Cost to Vehicle No :GBD7351X

Quantity	Description	List Price	Amount
		SS	SS
		Total	SS 2,626.85
		Add GST @ 7%	183.88
		Total Amount Payable	SS 2,810.75

TOTAL: SINGAPORE DOLLAR TWO THOUSAND EIGHT HUNDRED TEN AND CENTS SEVENTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
t/s 20/08/19.

03 Days

total: 1758.25

t/s: 1 HK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013634/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7473L	Veh. Inspected	GBD 7351X
Policy No.		Coverage (\$)	0.00
Claim No.	D19005038MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	05/08/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDY2318018052	Colour	SILVER
Odometer	118322	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	155 R13	YOKOHAMA	6 mm
L/H Rear Tyre	155 R13	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/07/2019	Inspection Date	20/08/2019
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7351X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL LAMP-RH	CRACKED	286.70	286.70
1	TAIL LAMP PANEL RH	DENTED	179.10	179.10
1	TAIL GATE LOCK RH	BENT	166.40	166.40
1	TAIL GATE LOWER PANEL	TO REPAIR SEE LABOUR	424.80	-
1	TAIL GATE LOCK RH BRACKET	BENT	79.10	79.10
1	TAIL GATE LOCK RH RUBBER	CUT	21.30	21.30
1	TAIL GATE REFLECTOR-RH	CRACKED	38.40	38.40
	LESS 25% DISCOUNT		-298.95	-192.75
			896.85	578.25
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
			300.00	200.00
LABOUR				
	TO CHECK WIRING.		50.00	30.00
	(REAR) TO SPRAY PAINTING.		700.00	500.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. INCLUSIVE OF THE REPAIR OF TAIL GATE LOWER PANEL.		600.00	400.00
	TO REMOVE AND REFIT REVERSE SENSOR.		80.00	50.00
			1,430.00	980.00
GRAND TOTAL			2,626.85	1,758.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/FC119013634/Atd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.