

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19013668/QKA3E2

Date: 27/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100507206	
Claimant Vehicle No : GBJ2546C	Insured Vehicle No : SLM9558M	
Date of Loss: 13/07/2019	Nature of Claim: TP	Claim No: 8599165553SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ2546C		
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No: 1KD2833118	
Reg. Date: 01/03/2019 (Man. Year: 2018)	Chassis No: JTFHT02P300246603	
Colour: White	Odometer: 14985 km	
Engine Capacity: 2982 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C	Rear Tyre Size: 195 R15C	
Front Left Side: Bridgestone 8 mm	Rear Left Side: Bridgestone 8 mm	
Front Right Side: Bridgestone 8 mm	Rear Right Side: Bridgestone 8 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/08/2019		
Date Inspected: 06/08/2019	Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair: 2.0 days		

Adjuster: OI SUN PIN

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*FRT NUMBER PLATE GARNISH	Scratched	0.00 F	*- F
3	1		*FRT BUMPER	Crumpled	0.00 F	*- F
					Total Parts (S\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >