

22/03/2003

ASS. REC. BY:

REF: CS/MSG 19013718/vqf3ⁿ²

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Christina Wong of MSG Date/Time: 6.8.19 10.05 a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 3466T Insured: GBF 7337Cat Workshop m/s Tan him motor Tel: 68585151of 1. Doh Lam 6Policy No: A2907 3388 MKC Claim No: 601552

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 22.7.19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 6.8.19 10.16 a.mPerson Contacted: caymenVehicle: IN / OUT

Date/Time Action/Instruction (✓) Estimate

GBJ 3466T - NA/MSG 19012937/r3DOA: 22/07/2019GBF 7337C - ✓

20/8/19 @ 2.40pm Informed Christina Wong, we are pending estimate from repairer.

22/8/19 @ 9.27am revised to Christina Wong via Marcmen.

(08/11/13)

ASS. REC. BY:

REF *msg*

ASSIGNMENT

From:

Date:

14.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBJ 3466T

at Workshop m/s

Tan him motor

of

1 Defu Lane 6

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

200p.m owner waiting

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

msg 274 25313

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBJ 3466T

Yr Regn:

3 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM

Make:

Toyota

Dyna

c.c

2982

Colour

blue

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35Y40K212.052

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~in order~~ / Jammed / Leaked / Burnt or

Brake: ~~in order~~ / Jammed / Leaked / Burnt or

Modi: ~~NI~~ / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 75 R15

R:

155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

8/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

D.O.I.

19/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/8/19 Confused P/P \$500 with lawyer. (Red \$3987.45, 89%.)

RECEIVED 28 AUG 2019

[Signature]
23/8/2019

Date/Time, File Pass to?

☐

: Preli. Report

1) *26/8/19*

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150
11
161

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

500

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 22 Aug 2019

Preliminary Advice

Insured Vehicle No	: GBF7337C	Accident Date	: 22/07/2019
TP Vehicle No	: GBJ3466T	Assignment Date	: 06/08/2019
Make	: TOYOTA DYNA 150	Est. Duration of Repair	: 2.00
Date of Inspection	: 19/08/2019		
Inspection At	: TAN LIM MOTOR PTE LTD (DEFU) 1 DEFU LANE 6 SINGAPORE 539365		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,487.45
Revised Amount	:S\$	500.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	500.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019		06 Aug 2019 10:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ALIFF'S PUFF N SUCH , Co. Reg. No.: 53114478W, Tel: +6590612527								
Main Claimant:	SEMGAS (S) PTE LTD , Co. Reg. No.: 200206783Z								
Vehicle Reg. No.:	GBJ3466T	Date of Loss:	22/07/2019 09:00 - :59 [3 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 601552	Policy/Cover Note No.:	A29073388MKC (Comprehensive) Coverage: 26/02/2019 - 25/02/2020						
Vehicle Reg. No. (Insured):	GBF7337C	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/08/2019]								
Driver/Custodian (Insured):	SHARBUDEEN ALLAUDDIN (38 / Male) , NRIC: G5153176R, Tel: +6590894902 Email:								
Adj Asg. Remarks:	on WP. Liab: Reject. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Caymen @ 6858 5151.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 20 August 2019 2:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE GBJ 3466T (YOUR REF: 601552)

This mail is associated with :

***GBJ3466T (601552)**

[GBF7337C]

TP

SEMGAS (S) PTE LTD

Jul 22 2019 9:00AM

[ALIFF'S PUFF N SUCH]

Tan Lim Motor Pte Ltd

Dear Christina,

Please be informed that we have inspected the vehicle GBJ 3466T.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 783Z

Vehicle Details

Vehicle No.: GBJ3466T

Vehicle to be Exported: No

Intended Deregistration Date: 01 Aug 2019

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 5MT

Primary Colour: Blue

Manufacturing Year: 2018

Engine No.: 1KD2834271

Chassis No.: JTFAT35Y40K212052

Maximum Power Output: -

Open Market Value: \$27,082.00

Original Registration Date: 27 Mar 2019

First Registration Date: 27 Mar 2019

Transfer Count: 0

Actual ARF Paid: \$1,355.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Mar 2029

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$26,230.00

COE Rebate Amount: \$25,313.00

Total Rebate Amount: \$25,313.00

The information contained herein is correct as at 01 Aug 2019

OK



陳林隆嗎私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

MSIG Insured's Veh No : GBF7337C

Date of Accident : 22 July 2019

not Attached
Man

P/P \$ 500

2 dy.

*Take photo After 19-
19/8/19*

Messrs Semgas (S) Pte Ltd

Date : 02 August 2019

Estimate To Repair GBJ3466T - Toyota DYNA 150 5MT

Chassis No : JTFAT35Y40K212052

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid	\$ 1,067.00
02	1 pc	tailgate lid Dyna sticker	\$ 20.00
03	1 pc	side gate lid LH	\$ 1,699.00
04	1 pc	side gate lid lock handle	\$ 168.00
05	1 pc	side gate lid lock latch	\$ 34.30
06	1 pc	side gate lid stopper LH	\$ 15.00
07	1 pc	side gate lid stopper bracket	\$ 168.00
08	1 pc	rear lamp LH	\$ 222.70
09	1 pc	rear lamp panel LH	\$ 42.60
			\$ 3,436.60
Less 25 %			\$ 859.15
			\$ 2,577.45
<u>SPECIAL NETT ITEMS</u>			
10	1 pc	tailgate lid 70KM/H Sticker	\$ 20.00
11	1 pc	tailgate lid 'Danger Highly Flammable' Sticker	\$ 100.00
12	1 pc	tailgate lid Union Corporate Sticker	\$ 100.00
			\$ 220.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas.	\$ 180.00
02		To check electrical lighting concerned.	\$ 60.00
03		To reinstall of rear bumper parking sensor.	\$ 150.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00
05		Putty and spray painting of the affected portion.	\$ 700.00
			\$ 1,690.00
Total			\$ 4,487.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illume modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

X
X
X
X
X
X
X
X
X

X
X
X

X
X
X

200
300

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19013718/UQF3N2

Date: 28/08/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29073388MKC
Claimant Vehicle No :	GBJ3466T	Insured Vehicle No :	GBF7337C
Date of Loss:	22/07/2019	Nature of Claim:	TP
		Claim No:	601552

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ3466T	Engine No:	1KD2834271
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y40K212052
Reg. Date:	27/03/2019 (Man. Year: 2018)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,797.45	0.00	2,797.45	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	500.00	1,190.00	70.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,487.45	500.00	3,987.45	88.86
+ GST 7.00/7.00% (S\$)	314.12	35.00	279.12	88.86
Nett Amount (S\$)	4,801.57	535.00	4,266.57	88.86

INSPECTION

Date of Assignment:	06/08/2019	Inspected At:	Tan Lim Motor Pte Ltd (Defu)
Date Inspected:	19/08/2019		1 Defu Lane 6
			Singapore 539365

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Aug 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3466T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Repair	1,067.00 FL	*-FL
2	1		*TAILGATE LID DYNA STICKER	Not Necessary	20.00 FL	*-FL
3	1		*SIDE GATE LID LH	Not Necessary	1,699.00 FL	*-FL
4	1		*SIDE GATE LID LOCK HANDLE	Repair	168.00 FL	*-FL
5	1		*SIDE GATE LID LOCK LATCH	Not Necessary	34.30 FL	*-FL
6	1		*SIDE GATE LID STOPPER LH	Not Necessary	15.00 FL	*-FL
7	1		*SIDE GATE LID STOPPER BRACKET	Repair	168.00 FL	*-FL
8	1		*REAR LAMP LH	Not Necessary	222.70 FL	*-FL
9	1		*REAR LAMP PANEL LH	Not Necessary	42.60 FL	*-FL
10	1		*TAILGATE LID 70KM/H STICKER	Not Necessary	20.00 FS	*-FS
11	1		*TAILGATE LID DANGER HIGHLY FLAMMABLE STICKER	Not Necessary	100.00 FS	*-FS
12	1		*TAILGATE LID UNION CORPORATE STICKER	Not Necessary	100.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,656.60	0.00
- List Item Discount on L Items 25.00/25.00% (S\$)	859.15	0.00
Total Parts (S\$)	2,797.45	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	180.00	0.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	0.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	0.00
4	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	600.00	200.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	300.00
Gross Labour Cost (\$\$)			1,690.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >