

23/03/2012

ASS. REC. BY:

REF: CS3/CT119013730/Ecf3

Special Instruction:

Surveyor:

Grovp

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping of CT1

Date/Time: 6.8.19 11.39a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 9485E

Insured: GBD 3882

at Workshop m/s Eng Soon

Tel: 67606271

of 3937 woodland Road

Policy No: DMCSN15138519044

Claim No: SNM 19D203608007

Sum Insured:

Excess:

Make of Veh:

D.O.A. 1.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 6.8.19 11.58a.m

Person Contacted: Mr KO

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	PA 9485E -X
	GBD 3882 - CS/CT118016970 / R14642 D.O.A - 17/09/2018
	Dismantle: 6/8/2019
	After repair: 13/8/2019


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____ PA 9485E 5/4/10
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Hiace
 Colour: White
 Sp. Reading: 273547
 Eng/No: _____
 C/No: JTFJT02P809001314
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/80R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 1/8/19 D.O.A. 6/8/19
 Survey held at Eng Soon

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV- 11K

Repair range - 5K-6K - 6 days

[Signature]
 16/8/2019

Date/Time, File Pass to?

☐ : Prelim. Report
☐ : Final Report

Date/Time, File Return to?

2

Report Format:

PRO

Lump Sum / T.B.F.:

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) \$ - R\$ 24

) Phone

) Other

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Insp (\$☐ Workshop (\$

10/1/19

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019		06 Aug 2019 11:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:									
Main Claimant:		LAM CHUAN IMPORT/EXPORT PTE LTD							
Vehicle Reg. No.:		PA9485E	Date of Loss:	01/08/2019 17:00 - :59					
Claim Type:		TP / SNM19D203608C02	Policy/Cover Note No.:	DMCSN15138519044					
Vehicle Reg. No. (Insured):		GBD388L	Policy No. (Claimant):						
		Excess:	\$50.00						
Repairer:		Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/08/2019]							
Adj Asg. Remarks:		PLEASE SURVEY AND REVERT							
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIa Records Management Centre established by the General Insurance Association of Singapore (GIa) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at this centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/08/2019 10:29
Date Of Accident 01/08/2019 17:30
Exact Location Of Accident ALONG PIE TOWARDS CHOA CHU KANG BTW EXIT 35 & 36
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number PA9485E
Insured/Policyholder
Name Of Registered Owner LAM CHUAN IMPORT-EXPORT (PTE) LTD
Co Reg No 197200190H
Email Address INFO@LAMCHUAN.COM
Mobile Phone No
Alternative Phone No OFFICE-93226787
Vehicle Particulars
Manufacturer TOYOTA
Model HIACE-3.0 D COMMUTER (M)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy or repair to your vehicle? NO
No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number P90324073MKC
Cover Note Number
Driver
Name of Driver HUANG SHULEI
Passport No/FIN G5084248M
Date Of Birth 04/10/1973
Occupation OUTDOOR
Date Of Driving Pass 19/07/2017
Driving Experience 2 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-93226787
Fax Number
Contact Number
Email Address NOEMAIL

Address 728778
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD388L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver YEO TIONG SAN
NRIC/Passport Number S1479380A
Contact Number 67535388
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

A: PA 9485E

B: GBD 388L

PIE towards Choo Chu Kang



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01/08/2019 at 17.30 hrs, I was driving my vehicle PA 9485E and travelling along PIE towards Choo Chu Kang between Exit 35 and Exit 36. In front there is a traffic jam and my vehicle was stationary and suddenly a vehicle GBD 388L hit my rear and causing damages to my rear portion of my vehicle.

DECLARATION

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	190H
Vehicle Details	
Vehicle No.:	PA9485E
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER MANUAL
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	1KD1986349
Chassis No.:	JTFJT02P800001314
Maximum Power Output:	-
Open Market Value:	\$34,417.00
Original Registration Date:	05 Apr 2010
First Registration Date:	05 Apr 2010
Transfer Count:	0
Actual ARF Paid:	\$1,721.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Apr 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$27,590.00
COE Rebate Amount:	\$1,779.00
Total Rebate Amount:	\$1,779.00

The information contained herein is correct as at 07 Aug 2019

OK



Sports rim do not just perk up the aggressive outlook of a car, it actually does improve performance with its lighter weight. Find yourself a beautiful set of rims from the list of tyre & rims retailers.

Find out more!



Fuel Types: Diesel

1 Owner, Durable Toyota Hiace 3.0 Manual With Silent Powerful 14D Euro 4 Turbo Engine. Well Maintained And Regular Service Just Done, Call Us Now For Viewing.

Posted: 31-Jul-2019 Tags: 2013 Toyota truck, 2013 toyota pick, Toyota Hiace, Toyota Hiace, Toyota, Hiace, hiace, Used Toyota




Fuel Type: Diesel

Super Reliable Toyota Haze! Very Good Condition! New Paintwork! Good Condition Leather Seats! No Repairs Needed! Drive Off With No Worries! High Trade-in! Door Step Viewing Can Be Arranged!

Seydik, A. and Pinar, L.

Received: 11-Jan-2019 *Topic*: 2010 Forests Major, 2010 Science Major, Treeless Major, Tropical Major, Tropical Major, Tropical Major, Tropical Major, Tropical Major, Tropical Major




COE]

Fuel Type: Diesel
1 Owner Only, Condition Very Well Maintain, New Paint, New Upholstery, Got Rear Aircon, Powerful Engine, High Loan With Low Interest, Trade In Welcome, Drive Off Immediately. Come Try It, Call Us To Know More.

SG Money Link (Pte) Ltd

Revised: 06-Aug-2018 Page: 2002 Twisted Fibers; 2002 twisted fibers; Twisted Fibers; twisted fibers; Twists; fibers; fibers used Twists



Fuel Type: Diesel

1 Owner And Very Good Condition! Servicing Done, No Repair Needed, Do Not Worry About The Loan We Provide 100% Loan With Low Interest, Low Monthly Instalment, Bank/In House, Welcome Trade In, Call For Viewing.

*99 Automotive Pte Ltd

Printed: 03-Aug-2019 Total: 2310 Treated flies: 2613 Treated flies: Treated males: 1000 Treated flies: Treated males: 1000 Treated flies: Treated males: 1000



Fuel Types: Diesel

Wow! 1 Owner, Original Tip Top Condition, No Repairs Needed, Fast, Well Maintained, Responsive Call Now. 5 Years COE \$35800

SG Motor Link Pte Ltd

Model: 04-Aug-2019 - Regn: 2010 Toyota Hiace, 2010 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Hiace, Used Toyota




COE)

Fuel Type: Diesel

5 Weeks Warranty! Good Condition! No Repair Needed! Comes With Free Full Servicing Inclusive Of Changing Of Timing Belt As Well! Best Commercial Van In The Market! Can Renew 5 Years COEI! Don't Miss Out This Tip Top Condition Van! Air Con, Gear Box, Engine, Susp...

Net Link Partners, Inc. Ltd.

Posted: 06-Aug-2019 Page: 2010 Toyota Hiace, 2010 Axiom Hiace, Toyota Hiace, Swift Hiace, Toyota Hiace Hiace Hiace Hiace Hiace



Fuel Type: Diesel

Van Still In Good Condition, No Repair Needed, Powerful Engine With Big Cargo Boots Space, Selling As It Is Original Condition, Good To Renew Car.

Revised: 15 Aug 2018 Tag: 2018 Trunk Mass, 2018 Fork Length, Fork Mass, Chum Scale, Fork Angle, Fork Index, Fork Shape

Save this search criteria, to get email alerts whenever a result is found.

Year	Model	Price	Depreciation	mpg (City)	Eng Cap	Mileage	Veh Type
------	-------	-------	--------------	------------	---------	---------	----------

[For old advertisements, view Expired ads.](#)

20 ▼ கனம்மேயு/பாடுதல்

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)

424Part 4 The taxation of individuals for paid and unpaid care, Tenika, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from work, budget, solar cars, luxury cars, sports cars & supercars, SUV, MPV, hatchback, to CCE cars & CPE cars. You can also buy from a car dealer, book a car lease, financial services, low mileage cars, car finance, carpark, refuel & car insurance. Find out what Toyota Hoda, Tenika Honda Singapore, used Toyota Honda Singapore, used vehicles Singapore or even buy used Toyota Honda Singapore. We have new car dealers offering parallel imports, authorised car dealers, and used car dealers in car sale. Find out car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, low estate properties for sale, motor car performance cars for discussion, future discussion, commercial vehicle leasing & F&E result.

All press and other information displayed on Spicard.com are gathered from sources and listed on algorithms that are believed by Spicard.com to be reliable, but no assurance can be given that this information is accurate, complete or current. Spicard.com does not assume any responsibility for errors or omissions or to warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2019 soCarMart. All rights reserved.

Toyota Hiace Used Vehicle List (17 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Hiace 3.0M (New 5-yr COE) (Diesel)	\$34,800	\$6,950 /yr	14-Jan-2010	2,982 cc	180,000 km	KSL Automotive Pte Ltd	Available
Most Sort After Van In The Market. 5 Doors, Manual, Reliable And Economical Workhorse, Everything Done Up And Ready To Go! Call Us Now For No-Obligation Viewing And Test Drive!							
Office No. - 62660777 Pearlyn - 87002017 Ah Wei - 84888378 Lee - 97961166							
Toyota Hiace 3.0M (New 5-yr COE) (Diesel)	\$33,800	\$6,750 /yr	26-Jan-2010	2,982 cc	-	QiFei Auto Pte Ltd	Available
Fresh 5-yr COE! Well-maintained Unit, Necessary Repairs And Maintenance Have Been Done Up. New Paintwork. Driveaway Condition! 100% Loan Available, Call To View!							
Office No. - 69083777 Jon Toh - 87505453 Eugene - 90927943							
Toyota Hiace 3.0M (New 5-yr COE) (Diesel)	\$35,800	\$7,150 /yr	09-Feb-2010	2,982 cc	179,000 km	SG Motor Link Pte Ltd	Available
1 Owner Only, Super Good Condition, Price Negotiable, Well Maintain By Previous Owner, Low Mileage, Selling With 5 Years COE, High Loan Available, Call Fast To View.							
Office No. - 62508527 CS - 86682223 Jay Lee - 88693466 YK Ong - 90260360							
Toyota Hiace 3.0M (New 5-yr COE) (Diesel)	\$32,800	\$6,550 /yr	25-Mar-2010	2,982 cc	-	Ezy-1 Pte Ltd	Available
New 5 Years COE. Wonderful Condition. Powerful Engine, New Paintwork Done. Aircon And Gearbox In Excellent Condition. Major Wear And Tear All Replaced. Call Us Now							
Office No. - 68730300 Jun Hao - 86885353 Andy Poon - 91366333							
Toyota Hiace Commuter 3.0A GL (New 5-yr COE) (Diesel)	\$35,800	\$7,150 /yr	01-Apr-2010	2,982 cc	356,000 km	Think One Automobile & Trading	Available
Office No. - 65553300 Chris - 90688008 Eric - 91638879 Sheila - 93911969							
Toyota Hiace Commuter 3.0A High Roof (New 5-yr COE) (Diesel)	\$37,800	\$7,550 /yr	29-Apr-2010	2,982 cc	-	Hon Brothers Motor	Available
Please Call To Arrange For Viewing, Thanks.							
Office No. - 67788862 Ivan Ho - 97200193 Chong - 88003223 Sam Tan - 97421147 Tony Hon - 81184141							
Toyota Hiace 3.0M (New 5-yr COE) (Diesel)	\$32,800	\$6,550 /yr	30-Apr-2010	2,982 cc	-	Boeki Auto Pte Ltd	Available
Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only							
Office No. - 67555005 Boeki - 82180500							
Toyota Hiace 3.0M (New 5-yr COE) (Diesel)	\$34,900	\$6,970 /yr	13-May-2010	2,982 cc	-	Friends Auto Trading	Available
New 5 Years COE, 1 Owner Only! New Paintwork, Nice Cushion, Beautiful And Clean Interior, Well Maintained, Serviced Regularly, Flexible Loan Available At Low Interest Rate, Trade In Welcome, Don't Mis...							
Office No. - 63823933 Andy - 96323933 Tan - 96948242							
Toyota Hiace 3.0M (New 5-yr COE) (Diesel)	\$33,800	\$6,750 /yr	08-Jun-2010	2,982 cc	-	Motorworld	Available
1 Owner! Accident Free! Immaculate Condition, Well Maintained And Always Serviced On Time. Good Condition, No Repair Needed, We Offer In House And Bank Financing With 100% Loan Available, We Would Ens...							
Office No. - 67470801 Derek - 96872514 Jayson - 90996088							

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019		06 Aug 2019 11:39 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	LAM CHUAN IMPORT/EXPORT PTE LTD		
Vehicle Reg. No.:	PA9485E	Date of Loss:	01/08/2019 17:00 - :59 [111 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203608C02	Policy/Cover Note No.:	DMCSN15138519044
Vehicle Reg. No. (Insured):	GBD388L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 19/08/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PA9485E (SNM19D203608C02)
[GBD388L]

TP

LAM CHUAN IMPORT/EXPORT PTE LTD

Aug 1 2019 5:00PM

[-]

Eng Soon Painting Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/08/19 18:48	General View		Load JPG	☒
2	06/08/19 18:48	General View		Load JPG	☒
3	06/08/19 18:48	General View		Load JPG	☒
4	06/08/19 18:48	General View		Load JPG	☒
5	06/08/19 18:48	General View		Load JPG	☒
6	06/08/19 18:48	General View		Load JPG	☒
7	06/08/19 18:48	General View		Load JPG	☒
8	06/08/19 18:48	General View		Load JPG	☒
9	06/08/19 18:48	General View		Load JPG	☒
10	06/08/19 18:48	General View		Load JPG	☒
11	06/08/19 18:48	General View		Load JPG	☒
12	06/08/19 18:48	General View		Load JPG	☒
13	06/08/19 18:48	General View		Load JPG	☒
14	06/08/19 18:48	General View		Load JPG	☒
15	06/08/19 18:48	General View		Load JPG	☒
16	06/08/19 18:48	General View		Load JPG	☒
17	06/08/19 18:48	General View		Load JPG	☒
18	06/08/19 18:48	General View		Load JPG	☒
19	06/08/19 18:48	General View		Load JPG	☒
20	06/08/19 18:48	General View		Load JPG	☒
21	06/08/19 18:48	General View		Load JPG	☒
22	06/08/19 18:48	General View		Load JPG	☒
23	06/08/19 18:48	General View		Load JPG	☒
24	06/08/19 18:48	General View		Load JPG	☒
25	06/08/19 18:48	General View		Load JPG	☒
26	06/08/19 18:48	General View		Load JPG	☒
27	06/08/19 18:48	General View		Load JPG	☒
28	06/08/19 18:48	General View		Load JPG	☒
29	06/08/19 18:48	General View		Load JPG	☒
30	06/08/19 18:48	Odometer Reading		Load JPG	☒
31	06/08/19 18:48	Chassis Number		Load JPG	☒
32	06/08/19 18:48	General View		Load JPG	☒
33	06/08/19 18:48	General View		Load JPG	☒
34	06/08/19 18:48	General View		Load JPG	☒
35	06/08/19 18:48	General View		Load JPG	☒

Photos/Images			3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	06/08/19 18:48	General View	 Load JPG	☒
37	06/08/19 18:48	General View	 Load JPG	☒
38	06/08/19 18:48	General View	 Load JPG	☒
39	06/08/19 18:48	General View	 Load JPG	☒
40	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
41	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
42	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
43	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
44	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
45	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
46	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
47	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
48	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
49	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
50	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
51	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
52	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
53	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
54	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
55	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
56	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
57	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
58	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
59	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
60	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
61	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
62	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
63	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
64	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
65	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
66	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
67	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
68	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
69	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
70	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
71	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
72	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
73	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
74	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
75	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
76	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
77	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
78	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
79	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
80	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
81	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
82	06/08/19 18:49	Photographs of Damaged Items	 Load JPG	☒
83	06/08/19 18:49	Photographs of Damaged Items	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	06/08/19 18:49	Photographs of Damaged Items	Load JPG	☒
85	06/08/19 18:49	Photographs of Damaged Items	Load JPG	☒
86	13/08/19 18:27	Photo After Spray	Load JPG	☒
87	13/08/19 18:27	Photo After Spray	Load JPG	☒
88	13/08/19 18:27	Photo After Spray	Load JPG	☒
89	13/08/19 18:27	Photo After Spray	Load JPG	☒
90	13/08/19 18:27	Photo After Spray	Load JPG	☒
91	13/08/19 18:27	Photo After Spray	Load JPG	☒
92	13/08/19 18:27	Photo After Spray	Load JPG	☒
93	13/08/19 18:27	Photo After Spray	Load JPG	☒
94	13/08/19 18:27	Photo After Spray	Load JPG	☒
95	13/08/19 18:27	Photo After Spray	Load JPG	☒
96	13/08/19 18:27	Photo After Spray	Load JPG	☒
97	13/08/19 18:27	Photo After Spray	Load JPG	☒
98	13/08/19 18:27	Photo After Spray	Load JPG	☒
99	13/08/19 18:27	Photo After Spray	Load JPG	☒
100	13/08/19 18:27	Photo After Spray	Load JPG	☒
101	13/08/19 18:27	Photo After Spray	Load JPG	☒
102	13/08/19 18:27	Photo After Spray	Load JPG	☒
103	13/08/19 18:27	Photo After Spray	Load JPG	☒
104	13/08/19 18:27	Photo After Spray	Load JPG	☒
105	13/08/19 18:27	Photo After Spray	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119013730/ECF3S2

Date: 21/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCSN15138519044

Claimant Vehicle No: PA9485E Insured Vehicle No: GBD388L

Date of Loss: 01/08/2019 Nature of Claim: TP Claim No: SNM19D203608C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA9485E

Make & Model: TOYOTA HIACE, 3.0 D Commuter (M) Engine No: 1KD1986349

Reg. Date: 05/04/2010 (Man. Year: 2010) Chassis No: JTFJT02P800001314

Colour: White Odometer: 273547 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/08/2019

Date Inspected: 06/08/2019 Inspected At: Eng Soon Painting Services (HQ)
393J WOODLANDS ROAD
Singapore 677978

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Aug 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D Commuter (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9485E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >