



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2019 HONDA FREED 1.5 (SMM640E)

Date of Loss 31 July 2019

Time of Loss 9.30

Loss Description SMM640E (INSD) C/W SJB8378D (TP)

Comment

Workshop Details

Total Rebate Amount 48550

Nett Loss Amount \$57,450.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details


Vehicle Registration#	SMM640E	Purchase Date	<input type="text" value="dd/mm/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="14/06/2019"/>
Mileage	<input type="text" value="2695"/>	Age of Vehicle	0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2019	<input type="text" value="2019"/>
Make	HONDA	<input type="text" value="HONDA"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	NG LIANG PHING	<input type="text"/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Model	FREED 1.5	<input type="text" value="FREED HYBRID 1.5G AI"/>
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	GB71094620	<input type="text" value="GB71094620"/>
Engine No	LEB5634213	<input type="text" value="LEB5634213"/>
Engine Capacity		<input type="text" value="1496"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="106000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	1 March 1983	<input type="text" value="dd/mm/"/>
Age	36	
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	8	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		<input type="text" value="dd/mm/"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<div>dd/mm/yy</div> <div></div>
Address	8 CHOA CHU KANG GROVE, #04-20, 688206, Singapore	<div></div>
Address type	Residential	<div></div> <div>▼</div>
Gender	Female	<div></div> <div>▼</div>
Marital status	Married	<div></div> <div>▼</div>
Identification #	S8381245A	<div></div>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

07/08/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

300

Young/Inexperienced/
Unnamed Driver
Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

-- none --



Tyre Condition

Age of Tyres

Front Tyre Size

185/65R15

Front left side

YOKOHAMA9mm

Front right side

YOKOHAMA9mm

Spare wheel

Rear Tyre Size

185/65R15

Rear left side

YOKOHAMA9mm

Rear right side

YOKOHAMA9mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts















Add















Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT LH DOOR (WCP) (10%)	Buckled	0	715	No					715	Reviewing
		0	1		FRONT LH DOOR LOCK (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FRONT LH WEATHER STRIP (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FRONT LH SIDE GARNISH (BLACK) (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		FRONT LH REGULATOR GEAR (WCP) (10%)	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
			0	1		FRONT LH REGULATOR MOTOR (WCP) (10%)	Serviceable	0	0	No				0	Deny
			0	1		FRONT LH TRIM BOARD (WCP) (10%)	Serviceable	0	0	No				0	Deny
			0	8		FRONT LH TRIM BOARD CLIP (WCP) (10%)	Serviceable	0	0	No				0	Deny
			0	1		FRONT LH OUTER HANDLE (WCP) (10%)	Serviceable	0	0	No				0	Deny
			0	1		FRONT LH CENTRE PILLAR (WCP) (10%)	Repair	0	0	No				0	Deny
			0	1		FRONT LH CENTRE PILLAR TOP GARNISH (WCP) (10%)	Serviceable	0	0	No				0	Deny
			0	8		FRONT LH CENTRE PILLAR TOP GARNISH CLIP (WCP) (10%)	Serviceable	0	0	No				0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT LH CENTRE PILLAR BOTTOM GARNISH (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	8		FRONT LH CENTRE PILLAR BOTTOM GARNISH CLIP (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		REAR LH DOOR (WCP) (10%)	Bent	0	616	No					616	Reviewing
		0	1		REAR LH DOOR LOCK (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		REAR LH DOOR WEATHER STRIP (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		REAR LH DOOR SIDE GARNISH (BLACK) (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		REAR LH DOOR REGULATOR GEAR (WCP) (10%)	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		REAR LH DOOR REGULATOR MOTOR (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		REAR LH DOOR TRIM BOARD (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	8		REAR LH DOOR TRIM BOARD CLIP (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		REAR LH OUTTER HANDLE (WCP) (10%)	Serviceable	0	0	No					0	Deny
		0	1		REAR LH RIMS CAP (WCP) (10%)	Cut	0	88	No					88	Reviewing

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		LABOUR CHARGE	0	400	0	0	Reviewing	
		0		SPRAY PAINTING	0	800	0	0	Reviewing	
		0		ANTI RUST	0	0	0	0	Deny	
		0		REWIRE	0	0	0	0	Deny	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		TRANSFER ALL PART TO NEW DOOR	0	120	0	0	Reviewing	
		0		UPHOLSERY	0	0	0	0	Deny	
		0		WHEEL ALIGNMENT	0	60	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$2,499.00		
CATEGORY		ESTIMATE		ADJUSTED				
Spare Parts		\$0.00		\$1,419.00				
Labour		\$0.00		\$1,380.00				
Excess				-\$300.00				

Submit for Review