

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19013764/KBB3Q2

Date: 08/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800133369

Claimant Vehicle No : SLK3551G **Insured Vehicle No :** SDG8309Z

Date of Loss: 02/08/2019 Nature of Claim: TP Claim No: 9925940402SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3551G	Engine No:	2ZRR991507
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU003544141
Reg. Date:	13/01/2017 (Man. Year: 2016)	Odometer:	172500 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,826.21	13,398.01	4,428.20	24.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,022.42	2,389.25	633.17	20.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,848.63	15,787.26	5,061.37	24.28
+ GST 7.00/7.00% (S\$)	1,459.40	1,105.11	354.29	24.28
Nett Amount (S\$)	22,308.03	16,892.37	5,415.66	24.28
+ Car Rental (12.0 x S\$69.94/day) (S\$)		839.28		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		17,739.10		

INSPECTION

Date of Assignment: 05/08/2019

Date Inspected: 05/08/2019 Inspected At: Esteem Performance Pte Ltd - Sin Ming (HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/F BUMPER COVER	Serviceable	25.70 FL	*- FL
2	1		*R/F BUMPER COVER	Serviceable	25.70 FL	*- FL
3	1		*FRONT BUMPER	Buckled	450.80 FL	*450.80 FL
4	1		*FRT BUMPER REINF	Repair	711.50 FL	*- FL
5	1		*L/F BUMP REINF BRKT	Repair	107.20 FL	*- FL
6	1		*R/F BUMP REINF BRKT	Repair	107.20 FL	*- FL
7	1		*FRT BUMPER ABSORBER	Serviceable	462.70 FL	*- FL
8	1		*FRONT GRILLE	Serviceable	321.90 FL	*- FL
9	1		*FRONT MANUFACT BADGE	Necessary	87.10 FL	*87.10 FL
10	1		*BONNET	Bent	812.40 FL	*812.40 FL
11	1		*R/F HINGE	Distorted	57.80 FL	*57.80 FL
12	1		*RIGHT HEADLAMP ASSY	Mtg Broken	2,531.60 FL	*2,531.60 FL
13	1		*R/F WING	Bent	868.70 FL	*868.70 FL
14	1		*R/F WING BADGE	Necessary	44.17 FL	*44.17 FL
15	1		*R/F WHEELHOUSE COVER	Cracked	185.64 FL	*185.64 FL
16	1		*AIR CHANNEL GUIDE	Serviceable	285.40 FL	*- FL
17	1		*R/F PANEL SUPPORT	Bent	89.20 FL	*89.20 FL
18	1		*L/F WHEELHOUSE CPL	Repair	995.80 FL	*- FL
19	1		*WINDSCREEN	Cracked	1,815.50 FL	*1,815.50 FL
20	1		*WINDSCREEN BOND KIT	Necessary	20.00 FL	*20.00 FL
21	1		*FRT SCREEN MNTG KIT (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*FRT SCREEN SUPPORTS (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*FRONT SCREEN SPACER (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*WINDSCREEN SEAL	Necessary	78.50 FL	*78.50 FL
25	1		*UPP WINDSCREEN MLDG (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*WASHER CONTAINER	Dented	195.60 FL	*195.60 FL
27	1		*WASH RESERVOIR TUBE	Serviceable	89.80 FL	*- FL
28	1		*RIGHT FRONT DOOR	Bent	1,121.75 FL	*1,121.75 FL
29	1		*L/UPPER DOOR HINGE	Bent	78.30 FL	*78.30 FL
30	1		*L/LOWER DOOR HINGE	Repair	78.30 FL	*- FL
31	1		*R/F DOOR CHECK	Serviceable	156.79 FL	*- FL
32	1		*R/F WINDOW REGULATOR	Serviceable	255.78 FL	*- FL
33	1		*R/F WINDOW MOTOR	Serviceable	563.25 FL	*- FL
34	1		*R/F OUT WINDOW SEAL	Dented	151.75 FL	*151.75 FL
35	1		*R/DOOR MIRROR ASSY	Mtg Cracked	1,374.20 FL	*1,374.20 FL
36	1		*R/ DOOR MIRROR COVER	Repair	87.50 FL	*- FL
37	1		*R/SILL PANELLING	Dented	721.50 FL	*721.50 FL
38	1		*R/OUTER DRIVE SHAFT	Bent	1,452.70 FL	*1,452.70 FL
39	1		*R/F LOWER AXLE ARM	Bent	492.65 FL	*492.65 FL
40	1		*R/F CPL SPRING STRUT	Bent	462.70 FL	*462.70 FL
41	1		*R/F STEERING KNUCKLE	Bent	476.75 FL	*476.75 FL
42	1		*R/F STRUT BEARING	Not Necessary	573.20 FL	*- FL
43	1		*R/S -ABSORB BOOT	Serviceable	37.02 FL	*- FL
44	1		*R/F WHEEL	Dented	1,555.10 FL	*1,555.10 FL
45	1		*R/TIE ROD BALL JOINT	Bent	116.40 FL	*116.40 FL
46	1		*FRONT LWR ENGINE CVR	Serviceable	198.30 FL	*- FL
47	1		*FRT BMP CLIP	Necessary	40.00 FL	*40.00 FL
48	1		*LOWER GRILLE	Serviceable	148.60 FL	*- FL
49	1		*FRONT BUMPER	Serviceable	89.81 FL	*- FL
50	1		*FRONT BUMPER	Serviceable	135.70 FL	*- FL
51	1		*FOG LAMP RH	Cracked	910.70 FL	*910.70 FL
52	1		*LWR FRT BUMPER	Repair	245.30 FL	*- FL
53	1		*RH FRT FENDER	Missing	122.70 FL	*122.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*RH BONNET	Cracked	195.65 FL	*195.65 FL
55	1		*RH FRONT WS	Distorted	118.50 FL	*118.50 FL
56	1		*LH S.SKIRT CLIP	Necessary	40.00 FL	*40.00 FL
57	1		*BMP RETAINER L	Serviceable	107.20 FL	*- FL
58	1		*BMP RETAINER RH	Missing	107.20 FL	*107.20 FL
59	1		*TOW COVER L	Serviceable	35.70 FL	*- FL
60	1		*TOW COVER RH	Serviceable	35.70 FL	*- FL
61	1		*PHV DECAL PHV DECAL	Necessary	20.00 FS	*20.00 FS
62	1		*IU BRACKET IU BRACKET	Necessary	24.00 FS	*24.00 FS
63	1		*RH FRONT TYRE RH FRONT TYRE (90%)	Punctured	350.00 FS	*315.00 FS
64	1		*FRONT WHEEL BEARING RH	Necessary	577.80 FL	*577.80 FL
65	1		*FRONT BRAKE HOSE RH	Punctured	144.45 FL	*144.45 FL
66	1		*FRONT ABS SENSOR RH	Shorted	449.40 FL	*449.40 FL
67	1		*FRONT STABILIZER LINK RH	Distorted	208.65 FL	*208.65 FL
68	1		*FRONT SUPPORT SIDE PANEL BRACKET RH	Repair	100.70 FL	*- FL
69	1		*FRONT SUPPORT SIDE BRACE PANEL RH	Repair	294.25 FL	*- FL
70	1		*SPARE TANK	Dented	176.55 FL	*176.55 FL
71	1		*R/F INN W-HOUSE EXT	Necessary	294.75 FL	*294.75 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	25,297.16	18,986.16
- List Item Discount on L Items 30.00/30.00% (\$)	7,470.95	5,588.15
Total Parts (\$)	17,826.21	13,398.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	365.0 WU 50.00 SGD/H	New	1,825.00	1,340.00
2	MEASURING WORK	New	60.00	0.00
3	FIXED RATE	New	120.00	120.00
4	LABOUR COST 135.0 WU X 50.00 SGD/H	New	675.00	615.00
5	MATERIAL COSE	New	282.42	264.25
6	TOWING TOWING	New	60.00	50.00
Gross Labour Cost (\$)			3,022.42	2,389.25

Report was unsubmitted during this print-out.

< END OF ESTIMATES >