

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19013774/GQF3E2

Date: 28/08/2019

REFERENCE

Insured/Claimant:	BRENDA YIP WEI GAN	Policy No:	PNPV2018-00004643-01
Date of Loss:	02/08/2019	Nature of Claim:	OD
		Claim No:	1201900022805

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC2722M		
Make & Model:	MERCEDES-BENZ C180, 1.8 (A)	Engine No:	27182030101020
Reg. Date:	20/10/2010 (Man. Year: 2010)	Chassis No:	WDD2040492A419673
Colour:	Black	Odometer:	144860 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	S\$35,500.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,358.00	5,677.00	5,681.00	50.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	2,870.00	1,080.00	27.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,308.00	8,547.00	6,761.00	44.17
Approved Total (Overridden) (\$\$)		6,850.00		
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	15,308.00	6,250.00	9,058.00	59.17
+ GST 7.00/7.00% (\$\$)	1,071.56	437.50	634.06	59.17
Nett Amount (\$\$)	16,379.56	6,687.50	9,692.06	59.17

INSPECTION

Date of Assignment: 06/08/2019
Date Inspected: 07/08/2019 Inspected At:

22 TAMPINESE STREET 92
Repairer : ETHOZ Protect Pte Ltd (Bukit Batok)

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2019)

Parts: M1-COUPE MERCEDES-BENZ C180 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGC2722M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,050.00 F	*- F
2	10		*FRONT BUMPER RIVET	Necessary	40.00 F	*40.00 F
3	1		*FRONT BUMPER CHROME MOULDING RH	Necessary	115.00 F	*45.00 F
4	1		*FRONT BUMPER CHROME MOULDING LH	Necessary	115.00 F	*45.00 F
5	1		*FRONT FENDER RH	Bent	780.00 F	*420.00 F
6	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	150.00 F	*- F
7	1		*FRONT FENDER EMBLEM RH	Necessary	68.00 F	*33.00 F
8	1		*FRONT FENDER CHROME MOULDING RH	Necessary	70.00 F	*19.00 F
9	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 F	*40.00 F
10	1		*FRONT DOOR RH	Bent	1,400.00 F	*860.00 F
11	1		*FRONT DOOR GLASS OUTER CHROME MOULDING RH	Not Necessary	160.00 F	*- F
12	1		*FRONT DOOR WEATHERSTRIPS RH	Necessary	220.00 F	*138.00 F
13	1		*FRONT DOOR LOWER WEATHER STRIPS RH	Necessary	80.00 F	*26.00 F
14	1		*FRONT DOOR LOCK RH	Not Necessary	255.00 F	*- F
15	1		*FRONT DOOR HINGE RH (UPPER)	Not Necessary	150.00 F	*- F
16	1		*FRONT DOOR HINGE RH (LOWER)	Not Necessary	150.00 F	*- F
17	1		*SIDE MIRROR COVER RH	Missing	380.00 F	*180.00 F
18	1		*SIDE MIRROR RH	Distorted	720.00 F	*502.00 F
19	1		*SIDE MIRROR MOTOR & GLASS RH	Distorted	950.00 F	*695.00 F
20	1		*REAR DOOR RH	Bent	1,350.00 F	*1,015.00 F
21	1		*REAR DOOR GLASS OUTER MOULDING RH	Not Necessary	160.00 F	*- F
22	1		*REAR DOOR WEATHERSTRIPS RH	Necessary	220.00 F	*138.00 F
23	1		*REAR DOOR LOWER WEATHERSTRIPS RH	Not Necessary	80.00 F	*- F
24	1		*REAR DOOR LOWER CHROME MOULDING RH	Necessary	95.00 F	*46.00 F
25	1		*ROCKER PANEL RH	Buckled	520.00 F	*295.00 F
26	1		*SIDE SKIRT RH	Cracked	480.00 F	*260.00 F
27	1		*REAR FENDER RH (NPA)	Repair	-	-
28	1		*REAR BUMPER (NPA)	Repair	-	-
29	1		*B-PILLAR RH (NPA)	Repair	-	-
30	1		*FRONT SPORT RIM RH	Cut	780.00 F	*440.00 F
31	1		*REAR SPORT RIM RH	Cut	780.00 F	*440.00 F
Total Parts (S\$)					11,358.00	5,677.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILIATE REPAIR	New	1,800.00	1,100.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New	1,700.00	1,440.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	20.00
4	TO RUST PROOF ON AFFECTED AREAS	New	100.00	80.00
5	TO REMOVE & REFIT FRONT DOOR COMPONENT RH	New	120.00	80.00
6	TO REMOVE & REFIT REAR DOOR COMPONENT RH	New	120.00	80.00
7	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	80.00	70.00
Gross Labour Cost (S\$)			3,950.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >