Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19013776/T1GA3N2

Date: 22/05/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant Insured Vehicle No: SHD3565B SKR1843C

Vehicle No:

Date of Loss: 01/08/2019 Nature of Claim: ΤP Claim No: MCT19080750

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SKR1843C** Reg No:

Make & Model: TOYOTA PICNIC, 2.0 (A) Engine No: 1AZ5443368

Chassis No: Reg. Date: 11/08/2006 (Man. Year: 2006) JTEGH23B500022104

Colour: Odometer: 201739 km Black

**Engine Capacity:** 1998 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

Yes Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm Front Right Side: Rear Right Side: Falken 6 mm Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	489.22	0.00	489.22	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	400.00	200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,089.22	400.00	689.22	63.28
+ GST 7.00/7.00% (S\$)	76.25	28.00	48.25	63.28
Nett Amount (S\$)	1,165.47	428.00	737.47	63.28
+ Loss of Use (1.0 v S	(22) (vch/00 0012	100.00		

+ Loss of Use (1.0 x S\$100.00/day) (S\$) 100.00

> **Nett Liability (S\$)** 528.00 Global Sum Settlement (S\$) 500.00

**INSPECTION** 

06/08/2019 Date of Assignment:

Date Inspected: 08/08/2019 Inspected At: Charn's Customcraft (HQ)

Block 1010 Bukit Merah Lane 3, #01-

Singapore 159724

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference			
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)	
Parts:	M1-MPV	TOYOTA PICNIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	: (Unsubmitted, no print-code for SKR1843C)		
Validity:	ty: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	652.30 FL	*-FL
F=Fra	anchise	part. L=ListItem	Disc.			
				Sub Total (S\$)	652.30	0.00
			- List Item Discount on L Items 25.00/25.00% (S\$)		163.08	0.00
				Total Parts (S\$)	489.22	0.00
			Report was u	nsubmitted during this print-ou	t.	

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	LABOUR TO JACKING PANEL BEATING ,REPAIR AND STRAIGHTEN REAR INNER PANEL AND INSTALLING REAR BUMPER	New	300.00	200.00	
2	PUTTY AND RESPRAY REAR INNER PANEL AND REAR BUMPER	New	300.00	200.00	
	Gross Labour Cost (S\$)		600.00	400.00	
	Report was unsubmitted during this print-out.				

< END OF ESTIMATES >