

Case Details

Case Reference Number : TAX/08/19/2007

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-7931-ID

Accident Date and Time : 02/08/2019 06:15 AM

Vehicle Registration Number : SHC4484A

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 54

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	✓ MC
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾	✗ R
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▾	✓ MC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▾	✓ MC
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	✓ MC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	✓ MC
One Time Key In	Main		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check ▾	✗ MC
Standard	Main	BODY RH	6505528	DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair ▾	✗ R

Standard	Main	BODY RH	6505486	DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair ▾	✗ R
Standard	Main	BODY RH	6505606	MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair ▾	✗ R
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair ▾	✓ R
Total Spare Part Cost									3,091.43	Surveyor Total				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									2,473.14	Final Sur Total				
										20				
										167.52				

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
2	Main	TO RESPRAY RH REAR DOOR	378.00	200	
3	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	150	
4	Main	TO RESPRAY REAR FENDER RH	378.00	200	
5	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			1,692.00	950.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	NA
2	Main	TO TRANSFER DOOR MECHANISM	240.00	0	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	NA
4	Main	TO REPLACE SUNDRY PARTS	100.00	20	NA
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			580.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,473.14	167.52
Total Labour Cost	845.00	300.00
Total Spray Painting	1,692.00	950.00
Other	580.00	60.00
Overall Total	5,590.14	1,477.52
Lump Sum Repair Option	☒	☒
Lump Sum Total	5,600.00	1,500.00

Surveyor Approved Amount	1,500.00
No of Repair Days*	6
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name	STEVE CHEN
Signature	
Survey Date	05/08/2019
Save Clear	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: