

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Total Labour :	12,912.00
Total Parts :	13,255.15
Total Labour & Parts :	26,167.15
GST @7%:	1,831.70
Grand Total :	<u>27,998.85</u>

	OD	3RD PARTY	DATE	WEEKEND DAYS
FAX TO FAX NO		Taufik LKK	18/10/19	11
FAX TO FAX NO				
FAX TO FAX NO				
CONFIRMED DATE				
PLEASE FINALISE BY _____				

LOSS OF USE = \$100 x 15 days
MEDICAL FARE - \$402.43
LTA SEARCH FEE - \$7.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52230**
Date Estimated : **05/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Oh Sze Ching (Hu SiQin)
132 Punggol Walk
#12-17

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 828777

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	WBA2B32000V9259	28/06/2017	216d CAT	0
DESCRIPTION	ACCOUNT:	ORIGINAL PRICE	DISC. %	NETT
To tow accident vehicle to PML workshop.		195.00	0	195.00
To replace rear bumper and attachments, rear boot lid and attachments, both tail lamps, tail end panel exterior & interior etc including to pull and straighten both rear chassis, to make good trunk floor panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.		4,250.00	0	4,250.00
To respray rear bumper, tail end panel, rear left fender, rear right fender, boot lid, boot compartment and both roof frames etc		4,470.00	0	4,470.00
To carry out body cavity preservation.		100.00	0	100.00
To carry out body cavity preservation. (For cut panel).		451.00	0	451.00
To replace front exhaust pipe catalyst silencer including align exhaust system and conduct checks for leak.		451.00	0	451.00
To replace rear exhaust silencer, chrome pipe and clamping bush etc including to align system and check for leak.		451.00	0	451.00
To replace each diesel particulate filter including alignment and conduct checks for leak.		564.00	0	564.00
To remove and install boot compartment carpet and garnish to facilitate repairs.		230.00	0	230.00
To conduct water leak tests.		75.00	0	75.00
To remove and install rear windscreen glass to transfer from old to new boot lid		574.00	0	574.00
To replace bootlid smart opener control unit including to conduct checks for proper function.		350.00	0	350.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking		451.00	0	451.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

system for proper function.

To check electrical wiring systems and lightings at the rear section for proper function. 150.00 0 150.00

Sundries. 150.00 0 150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# BLIND RIVET NUT M6	2.55	4.00	0	10.20
CLAMPING BUSH	54.30	1.00	0	54.30 ?
# V BAND CLAMP	42.85	1.00	0	42.85
# GASKET	8.25	1.00	0	8.25
EXCHANGE EXHAUST PIPE CATALYST	1,694.80	1.00	0	1,694.80
REAR SILENCER	1,167.45	1.00	0	1,167.45 ?
EXCH DIESEL PARTICULATE FILTER EU5	3,727.75	1.00	0	3,727.75
HOLDER EXHAUST SYSTEM	27.90	1.00	0	27.90 ?
HOLDER EXHAUST SYSTEM	27.90	1.00	0	27.90 ?
TAILPIPE TRIM BLACK CHROME	110.55	1.00	0	110.55 ?
# STEERING BOX HEAT RESISTANT PLATE	61.25	1.00	0	61.25
TRUNK LID	1,204.35	1.00	0	1,204.35 ?
INTERIOR TAIL TRIM	279.10	1.00	0	279.10 ?
TAIL PANEL	355.20	1.00	0	355.20 ?
REAR BUMPER PANEL PRIMED (PDC)	1,045.45	1.00	0	1,045.45
# EXPANDING NUT	1.00	2.00	0	2.00
RR BUMPER LH SIDE GUIDE	61.35	1.00	0	61.35 ?
REAR BUMPER CARRIER	458.10	1.00	0	458.10 ?
SUPPORT	45.30	1.00	0	45.30 ?
RR BUMPER LH INNER SIDE GUIDE	61.35	1.00	0	61.35 ?
RR BUMPER RH INNER SIDE GUIDE	61.35	1.00	0	61.35 ?
GROMMET	0.75	2.00	0	1.50 ?
PLAQUE 74MM	71.25	1.00	0	71.25 ?
# BUMP STOP	3.50	8.00	0	28.00
# HOOK AND LOOP FASTENER	2.85	8.00	0	22.80
CONTROL UNIT SMART OPENER	494.60	1.00	0	494.60 ?
# SNAP LOCKING COUPLING	1.00	3.00	0	3.00
RR LH LIGHT IN THE TRUNK LID	255.65	1.00	0	255.65 ?
RR RH LIGHT IN THE TRUNK LID	255.65	1.00	0	255.65 ?
RR LH LIGHT IN THE SIDE PANEL	365.20	1.00	0	365.20
ULTRASONIC SENSOR MINERALWEISS(WA96	368.80	1.00	0	368.80 ?
BLIND RIVET AVIBVLB	0.55	60.00	0	33.00 ?
SCREW (SF PLUS M5X15)	0.55	5.00	0	2.75 ?
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1.00	0	326.80 ?
PUNCH RIVET N4	0.55	40.00	0	22.00 ?
(DG) BODYWORK ADHESIVE K5A (50ML)	112.70	1.00	0	112.70 ?
(DG) CLEANER R1 (100ML)	26.15	1.00	0	26.15 ?
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0	263.10 ?
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	0	27.85 ?
(S/L) SEAM SEAL 300ML	33.80	2.00	0	67.60 ?
#				
#				

SUPPLEMENTARY ITEMS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52230**
Date Estimated : **05/08/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Oh Sze Ching (Hu SiQin)
132 Punggol Walk
#12-17

Singapore 828777

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ811U	WBA2B32000V9259	28/06/2017	216d CAT	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# BLIND RIVET NUT M6	2.55	4.00	0	10.20
# V BAND CLAMP	42.85	1.00	0	42.85
# GASKET	8.25	1.00	0	8.25
# STEERING BOX HEAT RESISTANT PLATE	61.25	1.00	0	61.25
# EXPANDING NUT	1.00	2.00	0	2.00
# BUMP STOP	3.50	8.00	0	28.00
# HOOK AND LOOP FASTENER	2.85	8.00	0	22.80
# SNAP LOCKING COUPLING	1.00	3.00	0	3.00

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	178.35
Total Labour & Parts :	178.35

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz 

Worldwide Partners

Date: 3/8/19 Time: 15:50
 Technician Name: wei
 Reg. No: SLA811U Job No: _____
 Odometer Reading (Customer Vehicle): _____
 KM Travelled by Assistance Vehicle: _____ (1 way)
 Fault Reported: _____
 Fault Found: accident (rear hit)
 How was vehicle repaired? _____



Customer Name: 011 52E (HIN)
 Customer Telephone: 96899337
 Make/Model: BMW 216i
 Location: Boundary Close
 Time on Scene: 16:40
 Time Job Completed: _____
 Repaired at Breakdown Scene: Y/N
 VIN No: _____

Hubcaps Y/N
 Spare Wheel Y/N
 Tools Y/N
 Audio System Y/N
 Keys + Remote Y/N
 Aerial Y/N
 Cashcard Y/N

Fuel

E		F
---	--	---

Interior Condition : _____
 Front Seats _____
 Rear Seats _____
 Floor Covering _____
 Headlining _____



Day/Night Wet/Dry Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent

Delivery to Dealership / Date and Time: Next

Vehicle received in the above condition YES/NO

If not stated as above specify difference: Lot 24

CUSTOMER DECLARATION

- I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
- I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
- In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
- I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customer Name & Signature (green copy)		Dealer/Workshop Signature, Name & Stamp (yellow copy)		Operators Signature (white & pink copy)	
--	---	---	--	---	---