



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6448D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	OFF SIDE RADIATOR SIDE ACCESS DOOR (CONSISTENT)	CRACKED	4,992.12	4,992.12
1	OFF SIDE REAR CORNER BUMPER (CONSISTENT)	CRACKED	1,119.27	1,119.27
1	OFF SIDE REAR TAIL LAMP ASSY (CONSISTENT)	CRACKED	901.96	901.96
1	OFF SIDE REAR LED TAIL LIGHT (CONSISTENT)	MISSING	120.00	120.00
1	PAINT MATERIAL (GREEN/WHITE/THINNER/LACQUER) (CONSISTENT)	NECESSARY	800.00	400.00
	LESS 10% DISCOUNT		-	-753.33
			7,933.35	6,780.02
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE AND REFIT OFF SIDE RADIATOR SIDE ACCESS DOOR, OFF SIDE REAR CORNER BUMPER, OFF SIDE REAR TAIL LAMP ASSY. LABOUR CHARGES TO REPAIR OFF SIDE REAR CORNER BUMPER FRAME AND BODY STRUCTURE.		2,400.00	1,600.00
	LABOUR CHARGES TO CHECK SYSTEM AND RECTIFY WIRING.		150.00	30.00
	LABOUR CHARGES TO RE-SPRAY AND POLISHING AFFECTED AREA.		2,400.00	800.00
			4,950.00	2,430.00
	GRAND TOTAL		12,883.35	9,210.02
	RECOMMENDED COST OF REPAIRS			9,210.02

Report Ref No. CC4/ASM19013848/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.