



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2007426
INV Date 05/11/2020
Reference CC3/CTI19013881/K1ka3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHB 8835A
Insured Veh. SLK 7611R
Claim No. SNM19D203671
Policy No. DMPCSN1708751902
Accident Date 04/08/2019
Inspection Date 06/08/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19013881/K1ka3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 05-11-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 7611R	Veh. Inspected	SHB 8835A
Policy No.	DMPCSN1708751902	Coverage (\$)	0.00
Claim No.	SNM19D203671	Excess (\$)	0.00
Assign From		Assign Date	06/08/2019

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5453467	Colour	SILVER
Odometer	782681	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	BRIDGESTONE	7 mm
L/H Front Tyre	205/65 R16	BRIDGESTONE	7 mm
R/H Rear Tyre	205/65 R16	BRIDGESTONE	7 mm
L/H Rear Tyre	205/65 R16	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/08/2019	Inspection Date	06/08/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8835A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET GRILLE	CRACKED	385.00	385.00
2	FRONT N/S & O/S HEAD LAMPS @ \$1028.00	SERVICEABLE	2,056.00	-
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER CENTER GRILLE	SERVICEABLE	174.00	-
1	FRONT BUMPER LOWER STIFFER	SERVICEABLE	134.00	-
1	FRONT BUMPER TOW HOOK COVER	SERVICEABLE	14.00	-
1	FRONT BUMPER INNER SPONGE	SERVICEABLE	110.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	328.00	-
2	FRONT BUMPER O/S & N/S SIDE RETAINER @ \$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S UPPER BRACKET @ \$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @ \$16.00	SERVICEABLE	32.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	1,119.00	-
1	BOOT LID LOCK	SERVICEABLE	99.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
2	BOOTLID HINGES @ \$66.00	SERVICEABLE	132.00	-
2	BOOTLID N/S & O/S REFLECTOR @ \$350.00	SERVICEABLE	700.00	-
2	REAR N/S & O/S TAIL LAMP @ \$421.00	SERVICEABLE	842.00	-
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL INNER GARNISH	SERVICEABLE	74.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @ \$29.00	CRACKED	58.00	58.00
2	REAR BUMPER REFLECTOR N/S & O/S @ \$46.00	SERVICEABLE	92.00	-

Report Ref No. CC3/CT19013881/K1ka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER STAY O/S & N/S @ \$53.00	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-950.40	-269.70
			8,553.60	2,427.30
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR NO. PLATE WITH CASING (SN)	SERVICEABLE	50.00	-
1	FRONT NO. PLATE WITH CASING (SN)	DENTED	50.00	35.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			768.00	451.00
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	50.00	-
	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.	NOT NECESSARY	80.00	-
	TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT / WELD & CUT THE PANEL. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FLOOR BOARD COMPARTMENT, ETC. INCLUSIVE OF THE REPAIR OF BOOT LID, BOOT LID LOWER GARNISH AND END PANEL.		1,800.00	800.00

Report Ref No. CC3/CT19013881/K1ka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL, FLOORBOARD COMPARTMENT, FRONT BUMPER.	NOT NECESSARY	1,200.00	900.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	-
			3,550.00	1,780.00
GRAND TOTAL			12,871.60	4,658.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CC3/CTI19013881/K1ka3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.