

12322001

ASS. REC. BY:

REP: CS/FCI19013911/Kqd3

Special Instruction:

Investor: Kenneth

ASSIGNMENT (Office)

From (Person): Henry Kao

of FCI

Date/Time: 12:27pm @ 8/8/19

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 48722

Insured: SHC 0767K

at Workshop n/s: V8 Motor Werkz

Tel: 97250880

of Blk 9 #01-44 Sin Mng Ind. Est. Sector C

Policy No:

Claim No: D1900512/MFSH

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 4/8/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 1:55pm @ 8/8/19

Person Contacted:

Mr. Chang

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimated	✓
	SKR 48722		
	SHC 0767K - CS/TMI18014588 / Klrd3n2		
15/8/19 @ 2:13pm	Informed Henry Kao, we are pending estimate from repairer		
28/8/19 @ 5:47pm	Mr Chang informed that they already sent estimate to Kenneth.		
02/9/19 @ 11:44am	revised to Henry Kao by email.		
30/8	11:20pm @ 2000 email & confirm (Red \$ 1888, 49% -)		

ASS. REC. BY:

REF: FCF

ASSIGNMENT

From: _____ Date: 14/8/19
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SKR 48722
 at Workshop m/s V8 Motor
 of 9 Sin Ming Ind. Est. Sec. C# 01-44
 Insured: _____ 0146
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKR 48722 Yr Regn: 01, 07
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or MPV
 Make: 1 Honda Stream C.C. 1799
 Colour: M-Black A/C: Insured / Std / NI / NA
 Sp. Reading: 368607 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RN6 . 1016017
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NII / Rim / STD A/Rim or
 Tyre Size: F: Dayton
Achilles ~~R. 750~~ 225/45ZR17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 4 mm R/Bal. 9 mm
 L/Bal. 4 mm L/Bal. 9 mm
 D.O.A. 4/8/19 D.O.I. 14/8/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Frt
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$19K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 04 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS up
01/22 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>Est not ready</u>
	<u>* MV = \$19K (est); LTA = \$12627; NV = \$6373.</u>
	<u>RECEIVED 02 SEP 2019</u>

Date/Time, File Pass to? : Preli. Report
02/9 RMISA : Final Report
 Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>130</u>
Transportation:	<u>50</u>
S + RS: SI	
Photos	<u>13</u>
Others	
TOTAL	<u>193</u>

Report Format: TR
 Lump Sum / I.B. / T.S. 2000



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005121MFSH

Date: 02 September 2019

Our Ref: CS/FC119013911/Kqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 4872Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/08/2019 at the premises of M/s V8 MOTOR WERKZ. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,888.00</u> .
Revised Estimate Amount	: S\$ <u>2,000.00 (Lump Sum)</u> .
“Check” Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	06-08-2019	Our Ref No. D19005121MFSH
Accident Date	04-08-2019	Claim Type. Third Party
Insured Vehicle	SHC0767K	Third Party Vehicle. SKR4872Z
Survey Location	BLK 9 #01-44 SIN MING INDUSTRIAL EST SECTOR C	
Contact Person.	MR. CHANG	
Contact No.	97250880/ 97250880	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	V8 MOTOR WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 2 September 2019 11:44 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005121MFSH/1
Attachments: CSFCI19013911Kqd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SKR 4872Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Thursday, 15 August 2019 2:13 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005121MFSH/1

Dear Henry,

Please be informed that we have inspected the vehicle SKR 4872Z on 14/08/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 8 August 2019 5:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005121MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 15 August 2019 2:13 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005121MFSH/1

Dear Henry,

Please be informed that we have inspected the vehicle SKR 4872Z on 14/08/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 8 August 2019 5:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005121MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 August 2019 12:26 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005121MFSH/1

Dear Sir/Mdm,

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 140G

Vehicle Details

Vehicle No.: SKR4872Z
Vehicle to be Exported: No
Intended Deregistration Date: 30 Aug 2019
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8 RSZ A
Primary Colour: Black
Manufacturing Year: 2006
Engine No.: R18A1718187
Chassis No.: RN61016017
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$18,787.00
Original Registration Date: 24 Jan 2007
First Registration Date: 24 Jan 2007
Transfer Count: 4
Actual ARF Paid: \$20,666.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Jan 2022
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$26,330.00
COE Rebate Amount: \$12,627.00
Total Rebate Amount: \$12,627.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Aug 2019.

OK

V8 MOTOR WERKZ PRIVATE LIMITED

9 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644
 TEL NO : 91442977
 EMAIL : V8MOTORWERKZ@GMAIL.COM
 ROC NO. : 201622378N

Not Attached
11 Sep 8 2000h
Recovery After Paint

DATE : 25/8/2019
 MAKE / MODEL : HONDA STREAM 1.8
 VEHICLE PLATE NUM : SKR4872Z

ESTIMATED COST :

No.	Description	QTY	Amount
1	FRONT BUMPER	<i>Bumper</i> 1	\$690.00 ✓
	FRONT BUMPER FOG LAMP COVER	<i>Br</i> 1	\$120.00 X
2	FRONT HEADLAMP	<i>Car</i> 1	\$620.00 ✓
3	FRONT SIDE FENDER	<i>R1</i> 1	\$370.00 ✓
4	FRONT SIDE BUMPER BRACKET	<i>M11</i> 1	\$140.00 ✓
5	FRONT SIDE FENDER COVERING	<i>Br</i> 1	\$148.00 X
6	FRONT HEADLAMP SUPPORT BRACKET	<i>R</i> 1	\$290.00 X
7	MUD GUARDS CLIP	<i>m</i> 1SET	\$50.00 ✓
8	BUMPER CLIP	<i>m</i> 1SET	\$60.00 ✓
9	SPORT RIM	<i>Red</i> 1	\$250.00 ✓
10	TO DISMANTLE/REPLACE/REFIT/FRONT BONNET, FRONT SIDE SIDE PANEL, PANEL LINER, HEADLAMP, UNDER CARRIAGE, ETC.	1	\$550.00 ✓
11	TO PUTTY AND SPRAY PAINT ON FRONT BUMPER, FRONT RIGHT SIDE PANEL INNER / OUTER	1	\$600.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3888



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013911/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 767K	Veh. Inspected	SKR 4872Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005121MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	08/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	RN61016017	Colour	METALLIC BLACK	
Odometer	368607	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 ZR17	DAYTON	4 mm	
L/H Front Tyre	225/45 ZR17	DAYTON	4 mm	
R/H Rear Tyre	225/45 ZR17	ACHILLES	9 mm	
L/H Rear Tyre	225/45 ZR17	ACHILLES	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/08/2019	Inspection Date	14/08/2019	
Survey held at	V8 MOTOR WERKZ PTE LTD 9 SIN MING INDUSTRIAL EST SECTOR C #01-44 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 4872Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED / DENTED	690.00	690.00
1	FRONT BUMPER FOG LAMP COVER	SERVICEABLE	120.00	-
1	FRONT HEADLAMP	CUT	620.00	620.00
1	FRONT SIDE FENDER	BENT	370.00	370.00
1	FRONT SIDE BUMPER BRACKET	DISTORTED	140.00	140.00
1	FRONT SIDE FENDER COVERING	SERVICEABLE	148.00	-
1	FRONT HEADLAMP SUPPORT BRACKET	TO REPAIR SEE LABOUR	290.00	-
1	SET MUD GUARDS CLIP	NECESSARY	50.00	50.00
1	SET BUMPER CLIP	NECESSARY	60.00	60.00
	LESS 20% DISCOUNT		-	-386.00
			2,488.00	1,544.00
	<u>SPECIAL NETT ITEMS</u>			
1	SPORT RIM (SN)	DENTED	250.00	250.00
			250.00	250.00
	<u>LABOUR</u>			
	TO DISMANTLE/REPLACE/REFIT/FRONT BONNET,FRONT SIDE SIDE PANEL,PANEL LINER,HEADLAMP,UNDER CARRIAGE,ETC.INCLUSIVE OF THE REPAIR OF FRONT HEADLAMP SUPPORT BRACKET.		550.00	400.00
	TO PUTTY AND SPRAY PAINT ON FRONT BUMPER,FRONT RIGHT SIDE PANEL INNER/OUTER.		600.00	400.00
			1,150.00	800.00
	GRAND TOTAL		3,888.00	2,594.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CS/FCI19013911/Kqd3n2

MARKET VALUE: \$19,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,627.00=NETT VALUE: \$6,373.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.