INS. CASE OWNER	Winie Ho cc 4, Asm 190 13	913, (0 4 109 4	DAC: 130732	S
1.	OUS ASSIGNMENT	h	Date / Time :	8/8/19	
Surveyor:		1	Registered in Merime	n:	_
Pre-assign / CCU /	CTM XC2 E		Sam	01 WD6	
Insured Vehicle No	[MANUMENCT (1201)	Claim No. :			i .
Name of Insured		Policy No. :			(v+
Insured Tel No.	118/2010	Make / Model :			
Excess Sec II :S\$ Is driver the owner?		Place of Accident			
If NO, Driver Nam	_	OLGIA PEPOPT	VEQ / NO · TP GI	A REPORT: NO	
Driver Tel N		Insured Liability		inal? Yes/No	
GBF 981	o P	1			
Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:	
Date/ Time	GRV 98181-X	Is	TAGE	DATE / PIC	
	m & (37 m /m 100 20 37 6 1 4	n Arr	Non-Reporting ltr (1st):		
	1112210 CALLANO (20 102) VI Col.		Non-Reporting ltr (2nd) Non-Reporting ltr (Fina		
sula.	Small with Clending OIELA WA	,	lotification ltr (if non-		
6/1	Pendina mandate approval.		Call OI:	7 3419119	
7// -	offer Eds 46850 (Vending acceptance).		Ocumentation Check		
231) -			Notification ltr (if non-p	oickup)	
3/2 -	Settle @ GIS #6050 DV send cherding Dr		After call ltr to OI:		=
1	Rental adviencent in).	R	telease Voucher:		
4/2 /	DV & RENTAL Agrichment in Chindry	P WA) F	inal Repair Bill:		
	WAM, ALL PAGS ME to close.		ar Rental Invoice: 4 P	ALLEMENT	=
			TA / GIA :		=
	***		Medical Bill:	X	_
		P	IR:	K I	
		N	// Aandate/Reject Instru	oction:	
			.OD		
PRELIMINARY ADVICE	Date/Time: Sent By:		Payment Breakdown : Post-Repair Photos:	Form:	=
TRELIMINARY ADVICE	Date Time. Start by.		Others:	X	
FINALIZATION	Date/Time: Confirm with:		Confirm by: W\	28CMI-	
Repair Cost:	The state of the s	% 64		mail Call	
FINAL SETTLEMENT	Date/Time: 3111 2020 - Confirm with Mid		Email Call		
Final Liability: Repair Cost:	% \00 (Agreed / Assessed) BOLA S/N No. :)?	1	f NO or B 28, Ass. L	ia;	
Repair Cost: (MAS) Loss of Rental (LOR):	S\$ 513.60 (6 days) x \$85.60	-		N OFNST	
Loss of Use (LOU):	S\$ - (\$ x days)		(PUBLEA	POLETICAL	
Loss of Income (LOI):	S\$ (\$ x days)		900	7)020	
LOR only LOU only	LOR + LOU LOR + LOI Tick only one				-
GIA/LTA Search	\$\$ 3.00				
Medical:	SS -			nal/Reject/Private Settle	
Disbursement: Legal Cost	S\$ — (e.g. Tow/ Independent)) Report Format:) Survey fee:	\$350.	
Total:	S\$ 1982.86 Global Sum SS: 5950.0		,	100	
FINAL PAYMENT	Date/Time: Confirm with:		mail Call		
Payee 1:	S\$ 6950.00 Name 1: Think one Au	Mocare Pte	Ltd .		
Payce 2: (Strike if N.A.)	S\$ Name 2:				
Payee 3: (Strike if N.A.)	S\$ Name 3:				

108/11/13; • Wel REF:	AXA /
ASS. REC. 61.7 7-7-7	ASSIGNMENT
From: Date: Estimated Cost:	Veh No: GBF SSIOP Yr Regn:
To Inspect Vehicle No: 637 98107	Make: Truck/Trailer or CA/ Make: Truck/Trailer or CA/ Lique Super G. 2987 Colour White A/C: Insured/Std/NI/NA
at Workshop m/s Think one	TID - Stor Income of I Stof I NI I NI A
of Insured:	Eng/No:
	C/No: KDH2010203930
Policy No.	Gen. Cond. Good / Fair / Poor / Burnt
Claims No.	Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	
(Client's Record)	
Make of Veh:	Modi: (Nil I)S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: /95-1/5
Remark: The veh had commenced its	BS / DUN / EXNOVA / GY / FS / LIZA / MIC) OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. / mm R/Bal. / mm
Consistent? : Yes or No	L/Bal. 7 mm L/Bal. mm
Est. Repairs: 15 days Res.: Yes or No	D.O.A. 6/8/18 D.O.I. 8/8/18
Lum Sum: \-\% 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction 214 2004	
V	p \$6587.32 (Red \$11,735.78/64.1.)
2017 1	and the same of th
	20-34/8/8
(\$200 \$1.5 × 1.1 × 1860 = 100 \$25 H 100 H 100 H 100	· y = 2.5.7-
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
: Final Report	Resurvey No. of Trip: Survey rec.
Date/Time, File Return to?	Add Fee: : Site Insp (\$)_s+Rs,_si
2)	
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$

TOTAL

AVA J

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522 Not Albert The shistosehorepary. Str. # 6587.32

	_	P TOYOTA HIACE KDH2010203	930			8/2019 AMOUNT S\$
No Q)ty	PARTICULAR TAIL GATE	2/01/		Soula	
2	1	TAIL GATE TAIL GATE PILLAR LH	2/01.1	0	300	2 425.00 &
3	1	TAIL GATE TRIM BOARD		ARA		11 428.00 X
4		TAIL GATE AUTO LOCK	CUE	3 (300.00)	00/	7~ 1.255.00
5	î	AUTO LOCK COVER	7 10 11	Cydd de l	5 62	71.1 95.00
6	î	TAIL GATE AUTO LOCK SEN	ISOR			17 855.00 X
7	1	TAIL GATE LOCK MECHANI				Jm 509.20
8	i	TAIL GATE INNER LOCK HA			3	1 125.00 ×
9	2	TAIL GATE DAMPER	54 C 1995 Mile 1995		269.8	an 539.60 x
10	ĩ	TAIL GATE LOCK CATCH				1 68.00 X
11	î	TAIL GATE (HIACE) EMBLE	M 75.	23		M 125.00
12	1	TAIL GATE (LOGO) EMBLEN				n 165.00
13	1	TAIL GATE CHROME		•		10 425.00 X
14	4	TAIL GATE RUBBER STOPPI	ER		20.00	11 80.00 X
15	1	REAR FLOOR PANEL				A 899.00 X
16	1	REAR FLOOR PANEL GARNI	ISH			11 855.00 ¥
17	1	REAR END PANEL GARNISH	I	10.62.0		298.00 ?
18	1	REAR END PANEL INNER		MAN		1,288.00 X
19	1	REAR END PANEL OUTER	919.10	30.00	130	Jso 1358.00
20	1	REAR BUMPER	660.00	(480.08)	0	- J 1,280.00 -
21	1	REAR BUMPER FOOT STEP 2	and			Sel 221.00 -
22	2	REAR BUMPER SIDE RETAINE	R		121.50	17 243.00 ×
23	1	TAIL LAMP ASSY RH				11 786.00 X
24	1	TAIL LAMP LOWER PANEL RI	I			145.00 X
25	1	EXHUAST PIPE ASSY				√ 955.00 V
26	2	REAR FENDER INNER GARNIS	SH R+L	2	652.00	nn 1,304.00 ×
		1.1.	10	00012/		\$ 16,942.80
		Tailgote weatherstring	Twi	299.13 LESS	25%	\$ 4,235.70
		: · · · · · · · · · · · · · · · · · · ·				\$ 12,707.10
				1.8022-9		

No	Qty	PARTICULAR	SPECAIL NETT	100	AMO	UNT SS_
1	1	REAR WINDSCRE	EN GLASS SEALANT		Mu	90.00 40
2	1	REAR WINDSCRE	EN GLASS INNER SEAL		M	135.00 3-2
3	1	REAR WINDSCRE	EN SUN-X FILM		11	250.00 🗶
4	1	TAIL GATE (1000)	(G) EMBLEM		su	85.00 SV
5	1	TAIL GATE (HIAC	E) EMBLEM		re	145.00 60
6	1	TAIL GATE (SUPE	ER GL) EMBLEM		ru	135.00
7	1	TAIL GATE (LOG	O) EMBLEM		ru	165.00 50
8	1	70 KM/H STICKE	ER		ner	25.00 /0
9	1	REAR NUMBER	PLATE (PAINT)		11	40.00 ≪
10	8	TAIL GATE TRI	M BOARD CLIP	6.0	0 11	48.00 X
11	18	REAR FENDER IN	NER GARNISH CLIP	6.0	0 11	108.00 💢
12	1	JOINT SEAL			11	120.00 ×
13	1	REVERSE SENS	OR		CNL	250.00 200
					\$	1,596.00

	LABOUR & MISCELLANEOUS:	
1	To remove damaged body parts with all necessary components/attach- ments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,800,00 Bos
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	1,200.00 900
3	To transfer tail gate components with all necessary attachments	250.00 60
4	To remove, refix rear windscreen glass and water test	250.00 /00
5	To remove, refix rear interior garnishes upholstery	na 200.00 X
6	To remove, replace rear exhuast pipe with all necessary attachments	∧ 120.00 ×
7	To install reverse sensor and test funtion	100.00 50
8	Apply anti rust solution on affected areas	100.00 65 \$ 4,020.00

LKK Auto Consultants hence notify the Repairer of the following:

- the Repairer of the following:

 To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No flegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K18 334 10

1-5503.1 252 P-4127.32 S.N 490.00 L 1970.00 L 1970.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
wner ID Type:	Business
Owner ID:	988K
ehicle Details	Western Granden and and a
'ehicle No.:	GBF9810P
ehicle to be Exported:	No
ntended Deregistration Date:	10 Sep 2019
ehicle Make:	TOYOTA
/ehicle Model:	HIACE 3.0 SUPER GL DARK PRIME AT
Primary Colour:	White
Manufacturing Year:	2016
ingine No.:	1KD2643439
Chassis No.:	KDH2010203930
Maximum Power Output:	(F#s)
Open Market Value:	\$45,864.00
Original Registration Date:	18 May 2017
First Registration Date:	18 May 2017
Fransfer Count:	0
Actual ARF Paid:	\$2,294.00
ntended PARF Rebate Details	0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-
PARF Eligibility:	No
PARF Eligibility Expiry Date:	5
PARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
COE Expiry Date:	17 May 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,029.00
COE Rebate Amount:	\$20,004.00
Total Rebate Amount:	\$20,004.00

The information contained herein is correct as at 13 Aug 2019

ОК

SGCARMART.COM

Login 5

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

SPARKOKARIS@\$350

F



SGCARMART SEE YOU @ BOOTH 2!

31 Aug & 1 Sep | 10am - 8pm Downtown East Carpark B

1 Essential Services 1 Grooming (worth \$2

Plus Many Other Benefits!

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

.

Make

Ways of Selling

Mercedes-Benz E250 2 Door Coupe Going For \$84,988!



Only \$8.6k Depreciation To Own An E250 Coupe, Superb Condition, View To Believe!

HIN LUNG A Ho Bee Group

> One Stop Ca Finance, Insurance New and Used Can

Sort by Date Posted

Advanced Search

Browse by Category

2 vehicles

Hiace 3.0A Super GL

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Search Selection

Hiace 3.0A Super GL

Anv

Any

2017

Any

Any

Toyota Hiace 3.0A Super GL **Dark Prime**

\$67,800

\$8,480 /yr

11-Aug-2017

2.982 cc

52,640 km

Fuel Type: Diesel

100% Loan Welcome. Immediate Delivery. No Adblue Needed! Reliable Engine/Gearbox. Super GL Dark Prime Unit With Factory Fitted Rear Aircon. Genuine Low Mileage Done, Original Paintwork. Accident Free Unit. Look Like Brand New Vehicle With High End Accessories

Posted: 12-Aug-2019 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0A Super GL **Dark Prime**

\$81,800

\$10,610 /yr

28-Apr-2017

2,982 cc

55,000 km

Enjoy Low Interest Bank Rate. Highest Specification Toyota Hiace. Comes With 5 Years Engine Warranty. Luxurious 8 Rear Seater Bus With Plenty Of Leg Room For Adult Passenger. Conditions As Good As New. Vehicle Is Lowered To 1.9m To Enter Most Of The Carpark...

Euro Performance Asia Pte Ltd

Posted: 22-Jul-2019

Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resource

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, truc cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage car insurance. Find buy used Hiace 3.0A Super GL, Hiace 3.0A Super GL Singapore, used Hiace 3.0A Super GL Singapore, used Hiace 3.0A Super GL, used vehicles 5 3.0A Super GL Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lis promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discu & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliab that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accurate

Follow sgCarMart.com

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Not Allow I when the solveply. Str. 8/18 P/25

GBF9810P TOYOTA HIACE KDH2010203930		P TOYOTA HIACE KDH2010203930	DATE	7/8/2019
No	Qty	PARTICULAR		AMOUNT S\$
1	1	TAIL GATE	Sed	1AD 2,236.00
2	1	TAIL GATE PILLAR LH	-	Z 425.00 &
3	1	TAIL GATE TRIM BOARD		428.00 >
4	1	TAIL GATE AUTO LOCK	20	/ym 1,255.00
5	1	AUTO LOCK COVER		71.1 95.00
6	1	TAIL GATE AUTO LOCK SENSOR		855.00 ?
7	1	TAIL GATE LOCK MECHANISM		509.20 ?
8	1	TAIL GATE INNER LOCK HANDLE		125.00 €
9	2	TAIL GATE DAMPER	269.8	U7 539.60 X
10	1	TAIL GATE LOCK CATCH		△
11	1	TAIL GATE (HIACE) EMBLEM		M 125.00_
12	1	TAIL GATE (LOGO) EMBLEM		ser 165.00
13	1	TAIL GATE CHROME		11 425.00 X
14	4	TAIL GATE RUBBER STOPPER	20.00	80.00
15	1	REAR FLOOR PANEL		~ 899.00 ×
16	1	REAR FLOOR PANEL GARNISH		855.00 ?
17	1	REAR END PANEL GARNISH		298.00 ?
18	1	REAR END PANEL INNER		1,288.00 ?
19	1	REAR END PANEL OUTER	/	502/00 1,358.00
20	1	REAR BUMPER		つ・」 1,260.00 -
21	1	REAR BUMPER FOOT STEP pan		Sel 221.00 -
22	2	REAR BUMPER SIDE RETAINER	121.50	17 243.00 X
23	1	TAIL LAMP ASSY RH		786.00 ?
24	1	TAIL LAMP LOWER PANEL RH		145.00 ?
25	1	EXHUAST PIPE ASSY		√ 955.00 √
26	2	REAR FENDER INNER GARNISH R+L	652.00	n1 1,304.00 €
				\$ 16,942.80
			LESS 25%	\$ 4,235.70
				\$ 12,707.10

No	Qty	PARTICULAR SPECAIL NETT		AMO	UNT S\$
1	1	REAR WINDSCREEN GLASS SEALANT		m	90.00 40
2	1	REAR WINDSCREEN GLASS INNER SEAL		m	135.00 30
3	1	REAR WINDSCREEN SUN-X FILM		11	250.00 🗶
4	1	TAIL GATE (1000KG) EMBLEM		su	85.00 SV
5	1	TAIL GATE (HIACE) EMBLEM		su	145.00 60
6	1	TAIL GATE (SUPER GL) EMBLEM		ru	135.00 572
6 7	1	TAIL GATE (LOGO) EMBLEM		ru	165.00 SV
8	1	70 KM/H STICKER		ner	25.00 10
9	1	REAR NUMBER PLATE (PAINT)		11	40.00 🗙
10	8	TAIL GATE TRIM BOARD CLIP	6.00	11	48.00 X
11	18	REAR FENDER INNER GARNISH CLIP	6.00	11	108.00 🗴
12	1	JOINT SEAL		11	120.00 🗴
13	1	REVERSE SENSOR		one	250.00 200
				\$ 1	,596.00

	LABOUR & MISCELLANEOUS:		
1.	To remove damaged body parts with all necessary components/attach- ments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments		1,800.00 fos
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials		1,200.00 900
3	To transfer tail gate components with all necessary attachments		250.00 65
4	To remove, refix rear windscreen glass and water test		250.00 /00
5	To remove, refix rear interior garnishes upholstery		200.00 ?
6	To remove, replace rear exhuast pipe with all necessary attachments	11	120.00 🗶
7	To install reverse sensor and test funtion		100.00 50
8	Apply anti rust solution on affected areas		100.00 65

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

4,020.00

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DISCHARGE \ SATISFACTION VOUCHER

we . ALEX COFFEE	NRIC/ ROC 53360988 K
Cacil	
ereby state that the repairs to vehicle no	have been carried out to my/our entire
atisfaction and I/We agree that the discharge to the a	eccount of Think One Auto Care Pte Ltd
shall be in full discharge of all claims under policy no	· 2019-VEIBRYZZ-VCV-RECI
with regards to the damage to my/our vehicle as a res	sult of accident which occurred on HALL TURN RHAW JUKENG EASTS 11 13.60
(date)	(time)
Vehicle Own	ner
Name	KHEO YONG HWA
NRIC	\$7931928 6
Address	65 LOWLAND RCHIS
	SINGAPORG 547464
	- M

(with company stamp if applicable)

Menu

P. Michael T. 9.490.m



Service Request Details

Claim

S9M01WD6

Reference

None 🥒

Loss Date

August 6, 2019

Report Date

Aug 8, 2019 9:11:00 AM

Request Date

August 8, 2019

Due Date

August 19, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBF9810P

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu

Model

HIACE 3.0 SUPER GL

Service Address

Primary Contact/Insured

CRONIMET SINGAPORE PTE LTD 27 JALAN BUROH, 619483, Singapore 62253946 PATEL.MAHIAR@CRONIMET.SG

Claim Handler

HO Winnie 6568804833

winnie.ho@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From:

michaelng@thinkone.com.sg

Sent:

Wednesday, 7 August, 2019 5:21 PM

To:

SG AXA Insurance SM AXA SGP - Motor Survey

Subject:

[EXTERNAL] ACC BTW GBF9810P & SJY853E DOA.6.8.2019

Importance:

High

Categories:

Mateen

Dear Sirs,

We would like to arrange for survey our client vehicle GBF9810P

Vehicle stall at No 18 Defu Lane Avenue 2

Thank You

Michael ng 97938472



CRONIMET SINGAPORE PTE, LTD. · No. 27 Jalan Burch - Singapore 619483

Date 2nd September 2019.

To AXA Insurance Pte Ltd.

8 Shenton Way, #24-01 AXA Tower, Singapore 068811.

Dear Sir,

This is to inform you that our company car number SJY 853E Mercedes Benz S350 is being used by Mr. Patel Mahiar Rustom S7268766C our company Managing Director. He is the authorized driver of the vehicle for several years now, which is insured by AXA Singapore and he is also authorized to claim under the policy. The insurance policy also mentions his name on it as the authorise driver.

Do contact us of you have any questions.

Yours faithfully,

Authorised Signatory



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date:

16/1/2020

Survey Details:

Date of loss	6-Aug-19	
Date of appointment	8-Aug-19	
Date of survey	8-Aug-19	
Location of survey	THINK ONE AUTOCARE PTE LTD	

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM		
Vehicle number	GBF9810P		
Make and Model	TOYOTA HIACE 3.0 SUPER GL		
Date of registration	18-May-17		
Parf Rebate			
Market Value \$		65,000.00	
Parf Rebate	\$ 20,235.0		
Nett Loss	\$ 44,765.00		

Repair details:

Initial Estimate	\$ 18,323.10

Proposed/Revised repair cost:

Parts	\$ 4,617.32
Check items (estimate)	\$
Labour	\$ 1,970.00
Total	\$ 6,587.32
Lump Sum(if applicable)	\$

Number of days for repair	5



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Remarks:

05 RECOMMENDED REPAIR DAYS + 1PRS = 6 DAYS	

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 7,048.43	W/GST
Loss of use	\$	
Loss of rental (W/GST)	\$ 385.20	6days x \$107
Loss of income	\$ \ •	
LTA search fees	\$ 2.00	
Others	\$ 1371	
Proposed Total	\$ 7,692.43	



<MANDATE IA> - S9M01WD6 {ACCIDENT INVOLVING SJY 853E (OI) & GBF 9810P (TP) ON 06/08/2019}

Type

Q Question

Message

LIABILITY: 100% BOLA \$27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE, AGREED TO SETTLE AT BEST, WE SEEK YOUR MANDATE AT \$7692.43 (CLAIMING LOR), MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 16/01/2020

Reply



THINK ONE AUTOCARE PTE LTD

RCB:201322501G GST:201322501G No.18 Defu Lane Avenue 2 Singapore 539522 Tel:(65)6844 3300 Fax:(65)6842 4988 Email:enquiry_autocare@thinkone.com.sg

BIII To : AXA INSURANCE SINGAPORE PTE LTD

Address: 8 SHENTON WAY

#01-21/22 AXA TOWER SINGAPORE 068811

Invoice Ref

:J0201908-0135

Date

: 23 AUG 2019

Vehicle No Make/Model :GBF9810P

Mileage(km)

:TOYOTA HIACE

Staff ID

NSP

Remarks/Ref

Description S/N COST OF REPAIR Amount S\$

6,587.32

SUB TOTAL 5,300.00 E & O.E. \$ **GST 7%** \$ 461.11 TOTAL SGD \$ 7,048.43

> mink One Autocare Pte Lto(18 Defu Lane Avenue 2 Singapore 539522 Tel: 6844 3300 Fax: 6842 4988



<MANDATE IA> - S9M01WD6 {ACCIDENT INVOLVING SJY 853E (OI) & GBF 9810P (TP) ON 06/08/2019}

Туре

Question

Message

Hi Cecilia, pls propose global \$6950 to \$7000 (all in). Tks



THINK ONE AUTOCARE PTE LTD

RCB: 201322501G GST: 201322501G No 18 Defu Avenue 2, Singapore 539522 Tel: (65)6844 3300 Fax: (65)6842 4988 Email: enquiry_autocare@thinkone.com.sq

Our Ref

: GBF 9810P

Your Ref

Date

: 23.08.2019

AXA INSURANCE SINGAPORE PTE LTD 8 SHENTON WAY #01-21/22 AXA TOWER SINGAPORE 068811

Dear Sirs,

Accident Involving GBF9810P along JURONG TOWN HALL TURN RH JURONG EAST ST11 on 6.8.2019
13.00hrs

We are authorized by the owner **THINK ONE LEASING PTE LTD** of vehicle **GBF9810P** to claim damages and loses against your insured in connection with the above road traffic accident.

Our client's vehicle was damaged and our client has been put to loss and expenses, particular of which are as follows:

Cost of Repair (inc 7%gst)

\$7,048.43

Loss of Rental (\$120 x 06.00days) inc 7%gst

\$770.40

LTA SERACH FEE

\$2.00

Total

\$7,820.83

We enclose herewith the supporting documents for your perusal.

Please let us have your cheque payment made in favour of 'Think One Autocare Pte Ltd'

Yours Faithfully

18 Defu Lane Avenue 2 Singapore 539522

Michael Ng Claim Advisor HP: 91288488 DID: 68443300

michaelng@thinkone.com.sg



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

U.S.		Affiliated to Federation Internation	nale Des Experts En Automob	ile
AXA	INSURANCE PTE	LTD	Ref : CC4/ASM1901391	13/Uga3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: WINNIE HO		Date: 10-02-2020 Code: ASM		
1.		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	SJY 853E	Veh. Inspected	GBF 9810P
	Policy No.	GA117014	Coverage (\$)	0.00
	Claim No.	S9M01WD6	Excess (\$)	0.00
	Assign From	WINNIE HO	Assign Date	08/08/2019
2.	Contract of the second	Vehicle Partic	culars & Condition	CONTRACTOR OF
	Make & Model	TOYOTA HIACE SUPER GL (A)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KDH2010203930	Colour	WHITE
	Odometer	92671	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195 R15	MICHELIN	7 mm
	L/H Front Tyre	195 R15	MICHELIN	7 mm
	R/H Rear Tyre	195 R15	MICHELIN	7 mm
	L/H Rear Tyre	195 R15	MICHELIN	7 mm
4.		Description	on of Damages	THE PARTY OF THE PARTY.
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.			Information	
	Accident Date	06/08/2019	Inspection Date	08/08/2019
	Survey held at	THINK ONE AUTOCARE PTE L	TD	
		NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a.	11. 11. 11. 11. 11. 11. 11. 11. 11. 11.	Re	emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		
5b.		Estimate	Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9810P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE (CONSISTENT)	BADLY DENTED	2,236.00	2,101.10
1	TAIL GATE PILLAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	425.00	-
1	TAIL GATE TRIM BOARD (CONSISTENT)	NOT NECESSARY	428.00	
1	TAIL GATE AUTO LOCK (CONSISTENT)	DENTED / JAMMED	1,255.00	545.10
1	AUTO LOCK COVER (CONSISTENT)	TORN	95.00	95.00
1	TAIL GATE AUTO LOCK SENSOR (CONSISTENT)	NOT NECESSARY	855.00	-
1	TAIL GATE LOCK MECHANISM (CONSISTENT)	JAMMED	509.20	509.20
	TAIL GATE INNER LOCK HANDLE (CONSISTENT)	NOT NECESSARY	125.00	-
2	TAIL GATE DAMPER @ \$269.80 (CONSISTENT)	NOT NECESSARY	539.60	-
1	TAIL GATE LOCK CATCH (CONSISTENT)	NOT NECESSARY	68.00	-
1	TAIL GATE (HIACE) EMBLEM (CONSISTENT)	NECESSARY	125.00	75.00
1	TAIL GATE (LOGO) EMBLEM (CONSISTENT)	NECESSARY	165.00	78.50
1	TAIL GATE CHROME (CONSISTENT)	NOT NECESSARY	425.00	
4	TAIL GATE RUBBER STOPPER @ \$20.00 (CONSISTENT)	NOT NECESSARY	80.00	
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	899.00	1-2
1	REAR FLOOR PANEL GARNISH (CONSISTENT)	NOT NECESSARY	855.00	
1	REAR END PANEL GARNISH (CONSISTENT)	NOT NECESSARY	298.00	
1	REAR END PANEL INNER (CONSISTENT)	TO REPAIR SEE LABOUR	1,288.00	
1	REAR END PANEL OUTER (CONSISTENT)	BADLY DENTED	1,358.00	919.10
1	REAR BUMPER (CONSISTENT)	DISTORTED	1,260.00	660.00
1	REAR BUMPER FOOT STEP PANEL (CONSISTENT)	BENT	221.00	221.00
2	REAR BUMPER SIDE RETAINER @\$121.50 (CONSISTENT)	NOT NECESSARY	243.00	-
1	TAIL LAMP ASSY RH (CONSISTENT)	NOT NECESSARY	786.00	77.
1	TAIL LAMP LOWER PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	145.00	-
1	EXHAUST PIPE ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	955.00	
2	REAR FENDER INNER GARNISH R+L @ \$652.00 (CONSISTENT)	NOT NECESSARY	1,304.00	1.5

Report Ref No. CC4/ASM19013913/Uga3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TAILGATE WEATHERSTRIP (CONSISTENT)	TWISTED	299.10	299.10
95	LESS 25% DISCOUNT		-4,310.48	-1,375.78
			12,931.42	4,127.32
	SPECIAL NETT ITEMS	{		
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	90.00	40.00
1	REAR WINDSCREEN GLASS INNER SEAL (SN) (CONSISTENT)	NECESSARY	135.00	30.00
1	REAR WINDSCREEN SUN-X FILM (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	TAIL GATE (1000KG) EMBLEM (SN) (CONSISTENT)	NECESSARY	85.00	50.00
1	TAIL GATE (HIACE) EMBLEM (SN) (CONSISTENT)	NECESSARY	145.00	60.00
1	TAIL GATE (SUPER GL) EMBLEM (SN) (CONSISTENT)	NECESSARY	135.00	50.00
1	TAIL GATE (LOGO) EMBLEM (SN) (CONSISTENT)	NECESSARY	165.00	50.00
1	70 KM/H STICKER (SN) (CONSISTENT)	NECESSARY	25.00	10.00
1	REAR NUMBER PLATE (PAINT) (SN) (CONSISTENT)	NOT NECESSARY	40.00	
8	TAIL GATE TRIM BOARD CLIP @ \$6.00 (SN) (CONSISTENT)	NOT NECESSARY	48.00	i-
18	REAR FENDER INNER GARNISH CLIP @ \$6.00 (SN) (CONSISTENT)	NOT NECESSARY	108.00	
1	JOINT SEAL (SN) (CONSISTENT)	NOT NECESSARY	120.00	8-
1	REVERSE SENSOR (SN) (CONSISTENT)	CRACKED	250.00	
			1,596.00	490.00
	LABOUR	1		
	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR, RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. INCLUSIVE OF THE REPAIR OF TAIL GATE PILLAR LH, REAR FLOOR PANEL, REAR END PANEL INNER, TAIL LAMP LOWER PANEL RH AND EXHAUST PIPE ASSY.		1,800.00	
	TO SPRAY PAINT REPLACED / REPAIRED BODY PARTS INCLUSIVE OR PREPARATORY WORKS AND PAINTING MATERIALS.		1,200.00	900.00
	TO TRANSFER TAIL GATE COMPONENTS WITH ALL NECESSARY ATTACHMENTS.		250.00	60.00

Report Ref No. CC4/ASM19013913/Uga3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE, REFIX REAR WINDSCREEN GLASS AND WATER TEST.		250.00	100.00
	TO REMOVE, REFIX REAR INTERIOR GARNISHES UPHOLSTERY.	NOT NECESSARY	200.00	45
	TO REMOVE, REPLACE REAR EXHAUST PIPE WITH ALL NECESSARY ATTACHMENTS.	NOT NECESSARY	120.00	
	TO INSTALL REVERSE SENSOR AND TEST FUNCTION.		100.00	50.00
	APPLY ANTI RUST SOLUTION ON AFFECTED AREAS.		100.00	60.00
			4,020.00	1,970.00
	GRAND TOTAL		18,547.42	6,587.32

RECOMMENDED COST OF REPAIRS	6,587.32

Report Ref No. CC4/ASM19013913/Uga3s2

CHUA KANG SENG

Licensed Appraiser