



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003064
INV Date 09/04/2020
Reference CC3/CTI19013930/K1ea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SJL 9013Y
Insured Veh. PA 7197A
Claim No. SNM19D203641
Policy No. DMB1SN3080021800
Accident Date 02/08/2019
Inspection Date 07/08/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19013930/K1ea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 09-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 7197A	Veh. Inspected	SJL 9013Y
Policy No.	DMB1SN3080021800	Coverage (\$)	0.00
Claim No.	SNM19D203641	Excess (\$)	0.00
Assign From		Assign Date	07/08/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	KMH DU41BR8U633040	Colour	SILVER
Odometer	154812	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	HANKOOK	7 mm
L/H Front Tyre	195/65 R15	HANKOOK	7 mm
R/H Rear Tyre	195/65 R15	HANKOOK	7 mm
L/H Rear Tyre	195/65 R15	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/08/2019	Inspection Date	07/08/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 9013Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	452.00	452.00
1	FRONT BUMPER REINFORCEMENT	BENT	279.00	279.00
1	FRONT BUMPER SPONGE	TORN	124.00	124.00
1	FRONT BUMPER N/S SIDE BRACKET	CRACKED	20.50	20.50
1	FRONT BUMPER N/S FOG LAMP	CRACKED	150.00	150.00
1	FRONT BUMPER CENTRE GRILLE	CRACKED	167.50	167.50
1	FRONT BUMPER LOWER LIP	CRACKED	50.00	50.00
1	N/S HEADLAMP	CRACKED	456.60	456.60
1	SUPPORT PANEL	CRACKED	791.30	791.30
1	BONNET	BUCKLED	992.00	992.00
2	BONNET HINGE	TO REPAIR SEE LABOUR	128.00	-
1	BONNET GRILLE	SERVICEABLE	366.00	-
1	FRONT N/S FENDER	BUCKLED	477.60	477.60
1	FRONT N/S FENDER INNER SHIELD	TORN	47.50	47.50
1	FRONT N/S WHEEL HOUSING	BUCKLED	464.00	464.00
1	FRONT N/S WHEEL COVER	CRACKED	104.00	104.00
1	FRONT N/S TYRE (NPA)	SERVICEABLE	-	-
1	FRONT N/S LOWER ARM	BENT	297.00	297.00
1	FRONT N/S SHOCK ABSORBER	BENT	349.60	349.60
1	FRONT N/S WHEEL HUP	SERVICEABLE	192.80	-
1	FRONT N/S KNUCKLE ARM	SERVICEABLE	376.40	-
1	FRONT N/S BEARING (NPA)	SERVICEABLE	-	-
1	FRONT N/S DOOR	TO REPAIR SEE LABOUR	1,258.00	-
1	BONNET LOCK (ADDITIONAL)	BENT	49.30	49.30
1	AIRCON CONDENSOR (ADDITIONAL)	BENT	847.60	847.60
1	RADIATOR ASSY (ADDITIONAL)	BENT	568.00	568.00
1	AIR DUCT (ADDITIONAL)	CRACKED	82.70	82.70
1	BLOWER ASSY (ADDITIONAL)	CRACKED	419.30	419.30
1	FRONT N/S FENDER INSULATOR (ADDITIONAL)	TORN	50.00	50.00

Report Ref No. CC3/CTI19013930/K1ea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,912.14	-1,447.90
			7,648.56	5,791.60
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	SET FRONT FENDER CLIPS (SN)	NECESSARY	28.00	28.00
1	BATTERY (SN)	CRACKED	150.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			263.00	183.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO CHECK HEADLAMP WIRING.		40.00	20.00
	TO TOP UP AIR CON.		120.00	80.00
	TO CHECK WHEEL ALIGNMENT.		80.00	60.00
	TO LIFT ENGINE TO FACILITATE REPAIR ON THE FRONT N/S WHEEL HOUSING.		450.00	150.00
	TO DISMANTLE DASHBOARD TO FACILITATE REPAIR ON THE FRONT N/S WHEEL HOUSING.	NOT NECESSARY	450.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT / WELD AND CUT OFF THE FRONT N/S WHEEL HOUSE. INCLUDING KNOCK -OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT N/S CHASSIS MEMBER. INCLUSIVE OF THE REPAIR OF BONNET HINGE AND FRONT N/S DOOR.		1,800.00	1,000.00
	TO PUTTY AND SPRAY PAINTING ON THE FRONT BUMPER, BONNET, FRONT N/S FENDER, FRONT N/S FENDER WHEEL HOUSE, FRONT N/S DOOR, FRONT N/S CHASSIS MEMBER.		1,500.00	1,080.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	50.00
	-		-	-
	-		-	-
	-		-	-
			4,740.00	2,490.00
	GRAND TOTAL		12,651.56	8,464.60



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,750.00
---	--	--	-----------------

Report Ref No. CC3/CTI19013930/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.