

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19013937/KGA3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100360946
Claimant Vehicle No :	GU5466M	Insured Vehicle No :	SFM2020P
Date of Loss:	06/08/2019	Nature of Claim:	TP
		Claim No:	8331273227SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GU5466M	Engine No:	HIDDEN
Make & Model:	NISSAN P/UP D/CAB, 2.7 D (M)	Chassis No:	JN1CHGD22Z0042627
Reg. Date:	01/03/2001 (Man. Year: 2001)	Odometer:	541937 km
Colour:	Blue/Silver		
Engine Capacity:	2664 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185 R15X8	Rear Tyre Size:	185 R15X8
Front Left Side:	Falken 8 mm	Rear Left Side:	VANMAX 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	VANMAX 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,533.80	1,378.11	1,155.69	45.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	720.00	880.00	55.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,133.80	2,098.11	2,035.69	49.25
Approved Total (Overridden) (S\$)		1,650.00		

Nett Amount (S\$)	4,133.80	1,650.00	2,483.80	60.09
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,897.49		

INSPECTION

Date of Assignment: 08/08/2019

Date Inspected: 13/08/2019

Estimated Period of Repair: 3.0 days

Inspected At:

Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming Autocare
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	980.00 FL	*980.00 FL
2	1		*REAR BUMPER TOP METAL PLATE	Serviceable	457.00 FL	*- FL
3	2		*REAR BUMPER SIDE PROTECTOR	Dented / Cut (1 PCS ONLY)	360.00 FL	*180.00 FL
4	1		*REAR BUMPER INNER BRACKET	N/S Bent / O/S Repair	298.20 FL	*149.10 FL
5	1		*REAR LH NUMBER PLATE LAMP	Serviceable	110.00 FL	*- FL
6	1		*LH TAILLAMP	Scratched	188.80 FL	*188.80 FL
7	1		*REAR END PANEL	Repair	388.00 FL	*- FL
8	1		*REAR TAILGATE LH 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
9	1		*REAR TAILGATE RH 6PAX EMBLEM	Necessary	15.00 FS	*15.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	2,812.00
					- List Item Discount on L Items 10.00/10.00% (\$)	278.20
					Total Parts (\$)	2,533.80
						1,527.90
						149.79
						1,378.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE /REFIT ,PANEL BEATING ,CUTTING WELDING AND REPLACEMENT OF DAMAGES	New	800.00	500.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	700.00	200.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	60.00	0.00
Gross Labour Cost (\$\$)			1,600.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >