

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GU5466M

No.	Qty	List Items			
1	1	Rear bumper	\$	Bz	980.00 ✓
2	1	Rear bumper top metal plate	\$	sn	457.00 X
3	2	Rear bumper side protector		Bd / 1/2	360.00 ✓
4	2	Rear bumper inner bracket		N/S Bz	\$ 0.18 X
5	1	Rear LH number plate lamp	\$	sn	110.00 X
6	1	LH taillamp	\$	sn	188.80 ✓
7	1	Rear end panel	\$	n	388.00 X
			\$		2,782.00
			Less 10%	\$	278.20
			Total :	\$	2,503.80

		Special Nett Items			
8	1	Rear tailgate LH "70km/h" sticker	\$	nn	15.00 ✓
9	1	Rear tailgate RH "6pax" emblem	\$	nn	15.00 —
			Total :	\$	30.00

		Labour			
1		Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$		800.00 500
2		To putty and spray Spray Paintings charges.	\$		700.00 200
3		To check wirings and lightings.	\$		40.00 20
4		To apply anti rust treatment	\$	nn	60.00 X
			Total :	\$	1,600.00

Total Parts and Labour : \$ 4,133.80

*Not Authorized
L1 Ling & 7650k
Resurvey After Paint
3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: