## 源摩哆廠 **GUAN MOTOR WORKS**

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

## **REPAIR ESTIMATE FOR GU5466M**

No.	Qty				
	<u>List Items</u>		0		
1	1 Rear bumper	\$	121	980.00	
2	1 Rear bumper top metal plate	, \$	52	457.00	X
3	2 Rear bumper side protector	150	,	360.00	4
4	2 Rear bumper inner bracket MIM	\$	Old V	298.20	XT
5	1 Rear LH number plate lamp	\$	Sim	110.00	X
6	1 LH taillamp	\$	Sin	188.80	
7	1 Rear end panel	\$	n	388.00	X
		\$	2	,782.00	<b>3</b> ,00
	Less 10%	\$		278.20	
	Total:	\$	2	,503.80	-
					-
	Special Nett Items				
8	1 Rear tailgate LH "70km/h" sticker	\$	M	15.00	
9	1 Rear tailgate RH "6pax" emblem	\$	Ner	15.00	
	Total:	\$		30.00	-
					_
	<u>Labour</u>				
1	Labour Charges for remove/refit, panel beating, cutting	\$		800.00	5001
	welding and replacement of damages.				
2	To putty and spray Spray Paintings charges.	\$		700.00	2001
3	To check wirings and lightings.	\$ \$		40.00	20%
4	To apply anti rust treatment	\$	nn	60.00	X
» <b>•</b> :	Total:	\$		,600.00	-
	,			•	-

Total Parts and Labour: \$ 4,133.80

Not Nothanker

Uling & 1650k

Berony After Pains

3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: