Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19013948/ABA3Q2

Date: 15/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322

Claimant Vehicle No: Insured Vehicle No: SME6039U

Date of Loss: 08/08/2019 Nature of Claim: TP Claim No: 0194060181SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD910K

 Make & Model:
 HONDA VEZEL, 1.5 X CVT (A)
 Engine No:
 L15B4030691

 Reg. Date:
 02/06/2016 (Man. Year: 2015)
 Chassis No:
 RU11110687

 Colour:
 Maroon
 Odometer:
 83707 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm
Front Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,611.70	4,905.36	1,706.34	25.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,280.00	820.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,711.70	6,185.36	2,526.34	29.00
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	8,711.70	4,900.00	3,811.70	43.75
+ GST 7.00/7.00% (S\$)	609.82	343.00	266.82	43.75
Nett Amount (S\$)	9,321.52	5,243.00	4,078.52	43.75
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 08/08/2019

Date Inspected: 08/08/2019 Inspected At: Chew Motor Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #01-11/41,

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*FRONT BUMPER	Deformed	880.00 F	*880.00 FL		
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL		
3	1		*FRONT BUMPER SIDE HOLDER LH	Necessary	23.60 F	*23.60 FL		
4	1		*FRONT BUMPER LOWER GARNISH	Torn	351.00 F	*351.00 FL		
5	1		*HEADLAMP LH	Cracked	1,859.10 F	*1,859.10 FL		
6	1		*HEADLAMP LOWER BRACKET LH	Cracked	45.00 F	*45.00 FL		
7	1		*FRONT LH FENDER	Distorted	580.00 F	*580.00 FL		
8	1		*FRONT LH FENDER ARC GARNISH	Cut	153.00 F	*153.00 FL		
9	1		*FRONT LH FENDER ARC GARNISH CLIPS	Necessary	20.00 F	*20.00 FL		
10	1		*FRONT LH FENDER INNER SHIELD	Deformed	132.00 F	*132.00 FL		
11	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	25.00 F	*25.00 FL		
12	1		*FRONT LH WHEEL RIM	Cut	800.00 FS	*480.00 FS		
13	1		*FRONT LH TYRE	Not Necessary	280.00 FS	*- FS		
14	1		*FRONT LH LOWER ARM	Bent	358.00 F	*358.00 FL		
15	1		*FRONT LH SHOCK ABSORBER	Bent	495.00 F	*495.00 FL		
16	1		*FRONT LH KNUCKLE ARM	Damaged	390.00 F	*390.00 FL		
17	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	190.00 F	*190.00 FL		
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.					
				Sub Total (S\$)	6,611.70	6,011.70		
	- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,106.34							
				Total Parts (S\$)	6,611.70	4,905.36		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	50.00
5	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	220.00
6	TO PERFORM WHEEL ALIGNMENT TEST	New	150.00	80.00
		Gross Labour Cost (S\$)	2,100.00	1,280.00
	Report was un	submitted during this print-out		

< END OF ESTIMATES >