

SLD910K.
Honda Vezel
RU11110687

Front Bumper	Deformed	880	✓
Front Bumper Clips	Nec	30	✓
Front Bumper Side Holder LH	Nec	23.60	✓
Front Bumper Lower Garnish.	torn	351.	✓
Headlamp LH	Cracked	1859.10	✓
Headlamp Lower Bracket LH.	Cracked	45	✓
Front LH Fender	Distorted	580	✓
Front LH Fender Arc Garnish.	Lt	153	✓
Front LH Fender Arc Garnish Clips.	Nec	20	✓
Front LH Fender Inner Shield	Deformed	132	✓
Front LH Fender Inner Shield Clips.	Nec	25	✓
Front LH Wheel Rim.	Lt	800(SN) 480(SN)	
Front LH Tyre.	Nbl Me	280(SN)	X

SLD910K.

Front LH Lower Arm. Bent 358 ✓

Front LH Shock Absorber Bent 495 ✓

Front LH Knuckle Arm. Damaged 390 ✓

Front LH Wheel Hub c/w Bearing^{Damaged} 190 ✓

5531.70

S.N: 480

4425.36

Panel Beating.

Spray Painting.

Wiring.

To spray tuff coat.

To dismantle front undercarriage

To perform wheel alignment test.

~~800~~ 500

~~600~~ 400

~~50~~ 30

~~150~~ 50

1280

~~350~~ 220

~~150~~ 80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6185.36

4/5: 4.9K.

05 Days.