

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19013972/R1VD3E2
Date: 30/08/2019

REFERENCE

Insured/Claimant:	ZHENG TIANYUAN	Policy No:	1900070756	
Date of Loss:	06/08/2019	Nature of Claim:	OD	Claim No: 3777435242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6814Y		
Make & Model:	AUDI A3, 999cc TFSI (A)	Engine No:	CHZC26336
Reg. Date:	15/03/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V6K1020197
Colour:	Grey	Odometer:	7411 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,956.00	9,388.00	5,568.00	37.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,352.00	3,452.00	2,900.00	45.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,308.00	12,840.00	8,468.00	39.74
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	21,008.00	12,540.00	8,468.00	40.31
+ GST 7.00/7.00% (\$\$)	1,470.56	877.80	592.76	40.31
Nett Amount (\$\$)	22,478.56	13,417.80	9,060.76	40.31

INSPECTION

Date of Assignment:	13/08/2019	
Date Inspected:	13/08/2019	Inspected At: Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2 Singapore 159938
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/30/2019

Adjuster Report

Kindly be informed that the customer (Mr. Zheng TianYuan) decided to proceed the repair at other workshop.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4,288.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,830.00 FS
2	1		*FRONT BUMPER FIXING PART	* Check	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	* Check	35.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	488.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	270.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	148.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER ADAPTER - LH	* Check	34.00 FS	*- FS
9	1		*RADIATOR GRILLE	Scratched	1,301.00 FS	*1,301.00 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	* Check	174.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	171.00 FS	*171.00 FS
12	1		*FRONT BUMPER IMPACT BAR	* Check	660.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	* Check	172.00 FS	*- FS
14	1		*IMPACT BEAM COVER	* Check	111.00 FS	*- FS
15	1		*AIR CON STICKER	Not Necessary	7.00 FS	*- FS
16	1		*CAUTION STICKER	Not Necessary	13.00 FS	*- FS
17	1		*FRONT FENDER - LH	Bent	778.00 FS	*778.00 FS
18	1		*POP RIVET	Necessary	15.00 FS	*15.00 FS
19	1		*FENDER ATTACHMENT PARTS	* Check	65.00 FS	*- FS
20	1		*FENDER BRACKET - LH	Necessary	35.00 FS	*35.00 FS
21	1		*FENDER SUPPORT	* Check	88.00 FS	*- FS
22	1		*WHEEL HOUSING LINER SEAL STRIP - LH	Necessary	31.00 FS	*31.00 FS
23	1		*WHEEL HOUSING LINER - LH	Deformed	158.00 FS	*158.00 FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	* Check	81.00 FS	*- FS
25	1		*LED HEADLIGHT - LH	Broken	5,029.00 FS	*5,029.00 FS
26	1		*MAIN LIGHT POWER MODULE	* Check	693.00 FS	*- FS
27	1		*LIGHT CONTROL MODULE	* Check	508.00 FS	*- FS
28	1		*LED UNIT - LH	* Check	666.00 FS	*- FS
29	1		*HEADLIGHT HOSE	* Check	36.00 FS	*- FS
30	1		*LIFT CYLINDER - LH	* Check	128.00 FS	*- FS
31	1		*LIFT CYLINDER HOSE	* Check	61.00 FS	*- FS
32	1		*LIFT CYLINDER PUMP	* Check	147.00 FS	*- FS
33	1		*WINDSCREEN WASHER PUMP	* Check	118.00 FS	*- FS
34	1		*WINDSCREEN WATER RESERVOIR	Not Necessary	189.00 FS	*- FS
35	1		*STRAINER	* Check	19.00 FS	*- FS
36	1		*RESERVOIR CAP	Not Necessary	19.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE - LH	* Check	22.00 FS	*- FS
38	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
39	1		*SUNDRIES	* Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,956.00** **9,388.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET. TO INSPECT FRONT LOCK CARRIER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER	New	3,000.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,352.00	3,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >