

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014007/APA3Q2
Date: 30/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	MID35415	Insured Vehicle No :	SDB5301R
Date of Loss:	26/06/2019	Nature of Claim:	TP
		Claim No:	1388255839SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	MID35415		
Make & Model:	MERCEDES-BENZ MB100D, 2.9 D (M)	Engine No:	HIDDEN
Reg. Date:	26/01/2009 (Man. Year: 2009)	Chassis No:	0
Colour:	Grey	Odometer:	60777 km
Engine Capacity:	2750 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	7.50 R16C	Rear Tyre Size:	7.50 R16C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,137.42	3,308.70	4,828.72	59.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,330.00	400.00	23.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,867.42	4,638.70	5,228.72	52.99
Approved Total (Overridden) (S\$)		3,700.00		

Nett Amount (S\$)	9,867.42	3,700.00	6,167.42	62.50
Liabe Amount (50.00%) (S\$)		1,850.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,857.45		
Global Sum Settlement (S\$)		1,850.00		

INSPECTION

Date of Assignment: 08/08/2019

Date Inspected: 08/08/2019

Estimated Period of Repair: 5.0 days

Inspected At:

Chin Meng Motors (HQ)
 1 Kaki Bukit Ave 6 #01-40/63, Autobay @ Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,328.60 FL	*2,328.60 FL
2	1		*REAR TAILGATE BRACKET (SPARE TYRE)	Not Necessary	688.90 FL	*- FL
3	1		*REAR TAILGATE WEATHERSTRIP	Necessary	223.50 FL	*223.50 FL
4	1		*REAR TAILGATE INNER BOARD	Not Necessary	322.50 FL	*- FL
5	1		*REAR TAILGATE INNER LOCK	Not Necessary	228.90 FL	*- FL
6	1		*REAR END PANEL	Dented	456.80 FL	*456.80 FL
7	1		*REAR END PANEL REFLECTOR R/H	Not Necessary	65.50 FL	*- FL
8	1		*TAILLAMP R/H	Not Necessary	333.80 FL	*- FL
9	1		*REAR TAILLAMP R/H BRACKET (WIREMESH)	Not Necessary	150.00 FL	*- FL
10	1		*REAR BUMPER SIDE	O/S Bent	911.20 FL	*455.60 FL
11	1		*REAR BUMPER SIDE BRACKET	O/S Bent	397.00 FL	*198.50 FL
12	2		*REAR BUMPER GARNISH	Not Necessary	191.20 FL	*- FL
13	1		*REAR EXHAUST MUFFLER	Repair	899.60 FL	*- FL
14	1		*FUEL TANK	Not Necessary	886.30 FL	*- FL
15	1		*REAR CENTRE TOW BAR	Not Necessary	850.00 FS	*- FS
16	1		*REAR TAILGATE STICKER	Necessary	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,945.80	3,675.00
- List Item Discount on L Items 10.00/10.00% (\$)	808.38	366.30
Total Parts (\$)	8,137.42	3,308.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	900.00	700.00
2	TO RESPRAY AFFECTED PART	New	800.00	600.00
3	TO CHECK WIRINGS	New	30.00	30.00
Gross Labour Cost (S\$)			1,730.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >