



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711  Contact No	Cust No/Name	LCV06646/Mr Ng Boon Ngan (huang Wenyan)
	Reg No/Reg Date	SME2595G / 25/09/2018
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5015113
	Engine No	G4FGJH707258
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLK / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000036	Credit	13/08/2019/ 08:42		218 / MarsLer	30238			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING						✓ 250.00
S	MIPNT88088	TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS						80 100.00
S	MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS						300 600.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS						100? 200.00
S	MIPNT88088	TO REPLACE REAR BUMPER, REINFORCEMENT, END PANEL, ETC TO REPAIR REAR BOOT STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS						1200 3000.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						1260 1680.00
S	MIPNT88088	REVERSE SENSOR SET						✓ 280.00
M	SUNDRY	C & C LOGO						✓ 50.00
M	KS 86611 M6 000	COVER-RR BUMPER			1.00	688.00	0.00	688.00
M	KS 86612 M6 000	LWR COVER-RR BUMPER			1.00	197.00	0.00	197.00
M	KS 86675 M6 000	LH COVER-RR BUMPER U			1.00	33.00	0.00	33.00
M	KS 86661 M6 000	LH COVER-RR BUMPER F			1.00	19.00	0.00	19.00
M	KS 86662 M6 000	RH COVER-RR BUMPER F			1.00	19.00	0.00	19.00
M	KS 92305 M6 000	LH LAMP ASSY-SIDE T/			1.00	181.00	0.00	181.00
M	KS 92306 M6 000	RH LAMP ASSY-SIDE T/			1.00	181.00	0.00	181.00
M	KS 0G032 50 037A	CLIP- BUMPER			10.00	2.00	0.00	20.00
M	KS 86651 M6 000	LH BRACKET ASSY-RR B			1.00	25.00	0.00	25.00
M	KS 86652 M6 000	RH BRACKET-ASSY RR B			1.00	31.00	0.00	31.00
M	KS 86631 M6 200	BEAM - REAR BUMPER			1.00	318.00	0.00	318.00
M	KS 86633 M6 200	LH BRACKET-RR BEAM U			1.00	9.00	0.00	9.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711  Contact No	Cust No/Name	LCV06646/Mr Ng Boon Ngan (huang Wenyan)
	Reg No/Reg Date	SME2595G / 25/09/2018
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5015113
	Engine No	G4FGJH707258
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLK / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000036	Credit	13/08/2019/ 08:42		218 / MarsLer	30238

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M KS 86634 M6 200 RH BRACKET-RR BEAM U	1.00	9.00	0.00	9.00
M KS 86636 M6 200 CTR BRACKET-RR BEAM	1.00	6.00	0.00	6.00
M KS 86637 M6 200 BRACKET-RR BEAM LWR	2.00	6.00	0.00	12.00
M KS 95420 S6 200 ANTENNA ASSY-SMARTKE	1.00	46.00	0.00	46.00
M KS 86641 M6 200 LH STAY - REAR BUMPE	1.00	65.00	0.00	65.00
M KS 86642 M6 200 RH STAY - REAR BUMPE	1.00	65.00	0.00	65.00
M KS 69100 M6 000 PANEL ASSY-BACK	1.00	324.00	0.00	324.00
M KS 85770 M6 000W K TRIM ASSY-RR TRANSVE	1.00	41.00	0.00	41.00
M KS 92401 M6 100 LH LAMP ASSY-REAR CO	1.00	675.00	0.00	675.00
M KS 92403 M6 150 LH LAMP ASSY - REAR	1.00	608.00	0.00	608.00
M KS 92409 M6 300 LAMP ASSY-CENTER GAR	1.00	690.00	0.00	690.00
M KS 81021 M6 000 W/STRIP-TRUNK LID OP	1.00	100.00	0.00	100.00
M KS 81230 M6 010 LATCH ASSY-TRUNK LID	1.00	112.00	0.00	112.00
M KS 86311 M6 000 LOGO ASSY-KIA SUB	1.00	32.00	0.00	32.00
M KS 86310 M6 100 EMBLEM-CERATO	1.00	28.00	0.00	28.00

**Z NOTES**

ACCIDENT ON 08/08/2019 ALONG ECP TOWARDS CITY  
OWNER CLAIMING THIRD PARTY  
REQUIRED REPLACEMENT CAR  
TP# SHD6763B TP INS: I.I.I

5 Days.

Before paint photos.

Guo Qiang - 82880882

14/8/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

Parts	4,534.00
Labour	0.00
Standard Menu	0.00
Specialist Job	6,110.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	10,694.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.