

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info			
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05	Cust No/Name	LCV06646/Mr Ng Boon Ngan (huang Wenyan)		
	Reg No/Reg Date			
IOU BUILDING	Date In/Mileage	/ 0		
SINGAPORE 049711	Chassis No	KNAF3416MK5015113		
Contact No	Engine No	G4FGJH707258		
	Make/Model	KIA/CERATO 1.6 A EX G333		
	Colour/Trim	KLG / WK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
F0000036	Credit	13/08/2019/ 08:42		218 / MarsLer		30238		
		Description of Goods	/ Services		Qty	Unit Price	Disc%	Amount
S MIPNT880								250.00
	IC/SCANNI	ING						
S MIPNT880								100.00
		G/WIRING SYSTEM ON RE	AR ACCIDEN	NT				
AFFECTED								
S MIPNT880								600.0
		STALL ALL CARPETS/TRI						
		R ON REAR ACCIDENT AF	FECTED ARE	EAS				
S MIPNT880		MIT ON NEW A DEDATE						200.0
IU APPLY	SEALANI	KIT ON NEW & REPAIR	PANELS					
S MIPNT880	CE DEAD E	NIMBED DETNICODOEMENTS	THE DANK!		JL			3000.0
TO DEDAT	D DEAD DO	BUMPER,REINFORCEMENT, OOT 1,ALIGN ON REAR ACCID	END PANEL	11/2019	17110			
STDATCHT	EN DEEDDM	A ALTON ON DEAD ACCED	ENT AFFEC					
AREAS	LN, KEFUKI	I, ALIGN ON KEAR ACCID	ENT AFTEC		2001	/		
S MIPNT980	188							1680.0
		REAR ACCIDENT AFFEC	TED AREAS					1000.0
S MIPNT880		. KENK MOOIDEN MITEO	TED TITLETO					280.0
	SENSOR SE	T						200.0
M SUNDRY								50.0
C & C LC	GO							
M KS 86611	M6 000	COVER-RR BUM	PER		1.00	688.00	0.00	688.0
M KS 86612	M6 000	LWR COVER-RR	BUMPER		1.00	197.00	0.00	197.0
M KS 86675		LH COVER-RR	BUMPER U		1.00	33.00	0.00	33.0
M KS 86661		LH COVER-RR	BUMPER F		1.00	19.00	0.00	19.0
M KS 86662		RH COVER-RR			1.00	19.00	0.00	19.0
M KS 92305		LH LAMP ASSY			1.00	181.00	0.00	181.0
M KS 92306		RH LAMP ASSY	The state of the s		1.00	181.00	0.00	181.0
	50 037A	CLIP- BUMPER			10.00	2.00	0.00	20.0
M KS 86651		LH BRACKET A			1.00	25.00	0.00	25.0
M KS 86652		RH BRACKET-A			1.00	31.00	0.00	31.0
M KS 86631		BEAM - REAR			1.00	318.00	0.00	318.0
M KS 86633	M6 200	LH BRACKET-R	R BEAM U		1.00	9.00	0.00	9.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info			
INDIA INTERNATIONAL INSURANCE SINGA	Cust No/Name	LCV06646/Mr Ng Boon Ngan (huang Wenyan)		
64 CECIL STREET #04-05	Reg No/Reg Date	SME2595G / 25/09/2018		
IOU BUILDING	Date In/Mileage	/ 0		
SINGAPORE 049711	Chassis No	KNAF3416MK5015113		
	Engine No	G4FGJH707258		
Contact No	Make/Model	KIA/CERATO 1.6 A EX G333		
	Colour/Trim	KLG / WK		

Account No T	erms	Date/Time Printed	CSE	Operator	-	WIP No			
0000036	redit	13/08/2019/ 08:42		218 / MarsLer		30238			
		Description of Good	s / Services		Qty	Unit Price	Disc%	Amount	
1 KS 86634 M		RH BRACKET-I	RR BEAM U		1.00	9.00	0.00	9.00	
4 KS 86636 M	200	CTR BRACKET-	-RR BEAM		1.00	6.00	0.00	6.00	
M KS 86637 M	200	BRACKET-RR I	BEAM LWR		2.00	6.00	0.00	12.00	
1 KS 95420 S		ANTENNA ASS	Y-SMARTKE		1.00	46.00	0.00	46.00	
M KS 86641 M		LH STAY - RI	EAR BUMPE		1.00	65.00	0.00	65.00	
1 KS 86642 M		RH STAY - RI			1.00	65.00	0.00	65.00	
KS 69100 M	000	PANEL ASSY-I	BACK		1.00	324.00	0.00	324.00	
1 KS 85770 M	000W				1.00	41.00	0.00	41.00	
1 KS 92401 M		LH LAMP ASS			1.00	675.00	0.00	675.00	
1 KS 92403 M		LH LAMP ASS'			1.00	608.00	0.00	608.00	
1 KS 92409 M	300	LAMP_ASSY-CI			1.00	690.00	0.00	690.00	
M KS 81021 M	000	W/STRIP-TRU		1800	L 1.00	100.00	0.00	100.00	
KS 81230 M	010	LATCH ASSY		III G	1.00	112.00	0.00	112.00	
KS 86311 M		LOGO ASSY-K			1 (1.00	32.00	0.00	32.0	
1 KS 86310 M	5 100	EMBLEM-CERA	TO TO		1.00	28.00	0.00	28.0	
NOTES		2/2019 ALONG ECP TOW							
REQUIRED RI		TP INS: I.I.	I						
Confirm & accepted by				Parts Labour Standard M Specialist Others(Lub	Job		4,534. 0. 0. 6,110. 0.		
						GST)		10,694.0	
Authorized signatory and company stamp				Others(Lub Sundry Total(w/o			10,		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.