

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014022/KKA3Q2
Date: 12/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100440143
Claimant
Vehicle No : SML9486E **Insured Vehicle No :** SDJ3535D
 Date of Loss: 08/08/2019 Nature of Claim: TP Claim No: 1599227576SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML9486E**
 Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B6002687
 Reg. Date: 12/06/2019 (Man. Year: 2019) Chassis No: GK82002282
 Colour: Metallic Grey Odometer: 18728 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,464.32	4,207.76	256.56	5.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,200.00	400.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,064.32	5,407.76	656.56	10.83
+ GST 7.00/7.00% (S\$)	424.50	378.54	45.96	10.83
Nett Amount (S\$)	6,488.82	5,786.30	702.52	10.83
+ Car Rental (7.0 x S\$90.00/day) (S\$)		630.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		6,424.30		

INSPECTION

Date of Assignment: 13/08/2019
 Date Inspected: 13/08/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.60 FL	*1,193.60 FL
2	1		*TAILGATE EMBLEM -SHUTTLE	Necessary	55.00 FL	*55.00 FL
3	1		*TAILGATE OUTER GARNISH WITH MOULDING	Cracked	383.10 FL	*383.10 FL
4	1		*TAILGATE LOGO	Necessary	27.40 FL	*27.40 FL
5	1		*TAILGATE INNER LOCK	Dented	157.80 FL	*157.80 FL
6	1		*TAILGATE INNER BOARD	Serviceable	320.70 FL	*- FL
7	2		*TAILGATE REFLECT	Cut	790.00 FL	*790.00 FL
8	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	131.80 FL	*131.80 FL
9	1		*REAR BUMPER	Buckled	1,156.60 FL	*1,156.60 FL
10	6		*REAR BUMPER CLIP	Necessary	23.40 FL	*23.40 FL
11	2		*TAILLAMPS	Cut	1,041.00 FL	*1,041.00 FL
12	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,520.40	5,199.70
- List Item Discount on L Items 20.00/20.00% (\$)	1,056.08	991.94
Total Parts (\$)	4,464.32	4,207.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO REMOVE AND REFIX TAILGATE ASSY ,REAR SPOILDER ,REAR WIPER ASSY ,TAILLAMPS AND TAILGATE REFLECTORS ,KNOCK AND REPAIR REAR PANEL AND REALIGN TO SAME	New	700.00	500.00
3	TO PUTTY AND RESPRAY ON REAR PANEL ,TAILGATE ,REAR BUMPER	New	700.00	500.00
4	RUSTPROOFING	New	30.00	30.00
5	TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	New	50.00	50.00
Gross Labour Cost (\$\$)			1,600.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >