

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014037/AEA3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMD1530E **Insured Vehicle No :** SMG5774B

Date of Loss: 07/08/2019 **Nature of Claim:** TP **Claim No:** 3236200566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD1530E		
Make & Model:	TOYOTA VELLFIRE, 2.5 CVT (A)	Engine No:	2ARJ078418
Reg. Date:	03/08/2018 (Man. Year: 2018)	Chassis No:	AGH300190625
Colour:	White	Odometer:	14304 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,187.32	7,909.30	3,278.02	29.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,610.00	3,000.00	1,610.00	34.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,797.32	10,909.30	4,888.02	30.94
Approved Total (Overridden) (S\$)		8,700.00		
(S\$)	15,797.32	8,700.00	7,097.32	44.93
+ GST 7.00/7.00% (S\$)	1,105.81	609.00	496.81	44.93
Nett Amount (S\$)	16,903.13	9,309.00	7,594.13	44.93
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		10,396.49		
Global Sum Settlement (S\$)		10,390.00		

INSPECTION

Date of Assignment: 08/08/2019

Date Inspected: 08/08/2019 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,955.80 FL	*1,955.80 FL
2	1		*BOOT LID LOGO	Not Necessary	99.70 FL	*- FL
3	1		*BOOT LID VELLFIRE EMBLEM	Necessary	88.40 FL	*88.40 FL
4	1		*BOOT LID LAMP LH	Cracked	629.70 FL	*629.70 FL
5	1		*BOOT LID LAMP RH	Not Necessary	629.70 FL	*- FL
6	1		*BOOT LID LOCK	Damaged	763.00 FL	*763.00 FL
7	1		*BOOT LID LOCK CHECKER	Not Necessary	69.90 FL	*- FL
8	1		*BOOT LID OUTER OPENING SENSOR	Not Necessary	119.20 FL	*- FL
9	1		*BOOT LID INNER CLOSING SENSOR	Damaged	489.70 FL	*125.00 FL
10	1		*BOOT LID RUBBER	Not Necessary	368.00 FL	*- FL
11	1		*BOOT LID TRIM	Cracked	673.00 FL	*673.00 FL
12	1		*REAR WINDSCREEN RUBBER	Necessary	178.00 FL	*178.00 FL
13	2		*BOOT LID SHOCK ABSORBERS	Not Necessary	661.20 FL	*- FL
14	1		*REAR ANTENNA SENSOR	Cracked	169.90 FL	*169.90 FL
15	1		*REAR PANEL	Dented	690.90 FL	*690.90 FL
16	1		*REAR PANEL TRIM	Deformed	172.30 FL	*172.30 FL
17	1		*REAR PANEL INNER SPONGE	Not Necessary	497.20 FL	*- FL
18	1		*SPARE TYRE SPONGE LH	Not Necessary	289.70 FL	*- FL
19	1		*REAR FENDER INNER TRIM LH	Deformed	886.40 FL	*886.40 FL
20	1		*TAIL LAMP LOWER FENDER LH	Deformed	388.90 FL	*388.90 FL
21	1		*TAIL LAMP LOWER FENDER RH	Not Necessary	388.90 FL	*- FL
22	1		*REAR BUMPER	Deformed	1,920.30 FL	*1,875.80 FL
23	2		*REAR BUMPER BRACKETS	Not Necessary	296.40 FL	*- FL
24	2		*REAR BUMPER SIDE RETAINERS	Necessary	259.00 FL	*259.00 FL
25	1		*REAR BUMPER REFLECTOR -LH	Cracked	86.90 FL	*86.90 FL
26	1		*REAR BUMPER TOWING COVER	Not Necessary	28.80 FL	*- FL
27	4		*REVERSE SENSORS	Damaged (3 PCS ONLY)	1,513.60 FL	*1,144.80 FL
28	1		*SET BOOTLID TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
30	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*40.00 FS
31	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*20.00 FS
32	1		*SET REAR FENDER INNER TRIM CLIPS LH	Necessary	40.00 FS	*30.00 FS
33	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
34	1		*REAR LH LOWER GARNISH	Deformed	204.60 FL	*204.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,817.10 10,482.40
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,629.78 2,573.10

Total Parts (\$\$) 11,187.32 7,909.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,500.00	1,100.00
2	TO SPRAY PAINTING	New	1,500.00	1,200.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO REMOVE AND REFIT BOOT LID EMBLEM SEAT CUSHION	New	400.00	120.00
5	TO CHECK WIRING	New	50.00	30.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	100.00	60.00
7	TO REMOVE AND REFIT REVERSE CAMERA	New	100.00	60.00
8	TO SPRAY UNDERSEAL	New	180.00	80.00
9	TO RESET AND PROGRAM REAR AUTO BOOT LID	New	280.00	150.00
10	TO TRANSFER REAR AND REFIX BOOT LID MECHANISM	New	380.00	80.00
Gross Labour Cost (\$\$)			4,610.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >