Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19014045/ABA3Q2

Date: 13/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700068222 Claimant SMD6042P Insured Vehicle No: SLT3056Y Vehicle No:

Date of Loss: 07/08/2019 Nature of Claim: ΤP Claim No: 8583155902SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMD6042P Reg No:

Engine No: Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) CHZ461168

Chassis No: WAUZZZGA4JA089581 Reg. Date: 28/08/2018 (Man. Year: 2018)

Colour: White Odometer: 14509 km

Engine Capacity: 999 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,516.00	4,084.40	3,431.60	45.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,412.00	5,262.00	4,150.00	44.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,928.00	9,346.40	7,581.60	44.79
+ GST 7.00/7.00% (S\$)	1,184.96	654.25	530.71	44.79
Nett Amount (S\$)	18,112.96	10,000.65	8,112.31	44.79
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc	/Search Fee (S\$)	2.00		

INSPECTION

Date of Assignment: 15/08/2019

15/08/2019 Inspected At: Premium Automobiles Pte Ltd (UBI) Date Inspected:

Nett Liability (S\$)

55 Ubi Road 1

10,362.65

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,074.00 FS	*859.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	70.00 FS	*- FS
3	1		*REAR BUMPER SPOILER LH	Deformed	259.00 FS	*207.20 FS
ļ	1		*REAR BUMPER TOWING COVER	Not Necessary	39.00 FS	*-FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	54.00 FS	*-FS
3	1		*REAR BUMPER CARRIER	Not Necessary	501.00 FS	*- FS
7	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	24.00 FS	*-FS
3	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	98.00 FS	*- FS
9	1		*REAR PARKING AIR SENSOR -INNER	Not Necessary	462.00 FS	*-FS
10	4		*SEAL RING	Not Necessary	12.00 FS	*- FS
11	1		*REAR LID	Dented	2,195.00 FS	*1,756.00 FS
12	1		*REAR LID ATTACHMENT PARTS	Not Necessary	109.00 FS	*- FS
13	1		*LOCK STRIKER	Not Necessary	265.00 FS	*- FS
14	1		*FLAP GASKET	Not Necessary	106.00 FS	*-FS
15	1		*LID LOCK	Not Necessary	227.00 FS	*-FS
16	1		*BONNET LOCK COVER	Not Necessary	11.00 FS	*- FS
17	1		*AUDI EMBLEM	Necessary	113.00 FS	*90.40 FS
18	1		*Q2 INSCRIPTION	Necessary	87.00 FS	*69.60 FS
19	1		*TFSI INSCRIPTION	Necessary	87.00 FS	*69.60 FS
20	1		*REAR WINDOW	Necessary	711.00 FS	*568.80 FS
21	1		*PRIMER	Necessary	19.00 FS	*14.80 FS
22	1		*REAR CROSS PANEL TRIM	Not Necessary	141.00 FS	*- FS
23	1		*REAR NO PLATE	Not Necessary	40.00 FS	*-FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
25	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
26	1		*REAR WHEEL ARCH TRIM COVER RHS	Necessary	156.00 FS	*124.40 FS
27 ==Ers	1	part. S=Spcl	*REAR WHEEL ARCH TRIM COVER LHS	Necessary	156.00 FS	*124.40 FS
-110	ai ioi iio c	ран. 0-оро	voii.	Total Parts (S\$)	7,516.00	4,084.40

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPAIR END PANELLING	New	1,200.00	500.00
2	TO RESPRAY END PANELLING	New	1,200.00	550.00
3	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	400.00
4	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
5	TO REMOVE AND TRANSFER REAR LIDS CONVENIECE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
6	TO RENEW REAR WINDSCREEN	New	480.00	480.00
7	TO DISMANTLE AND RENEW BUMPER AND REAR LID TO INSPECT END PANELLING .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED) New	2,400.00	1,000.00
8	TO RESPRAY REAR BUMPER AND REAR LID	New	2,500.00	1,100.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	OWNERS PAINT COATING SEE INVOICE ATTACHED	New	280.00	280.00
	Gross Labour Cost (S\$)		9,412.00	5,262.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.