

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	SUHaida BINTE SAPIEE
NRIC/Passport Number	S8314689C
Contact Number	91006554/98475570
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may, are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the **Personal Information** and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **Purposes**);
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time 31/5/19 12:04 PM

Reporting Centre Personnel's Signature
Name
NRIC / ID No.

Scanned with CamScanner

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving^(h) at Lane 1 of PIE (towards chungi), the traffic is moving. I was in the car with my friend. Suddenly a car ~~in front~~ (which is 2 car before mine) e-brake, causing the car before me to have a sudden e-brake. I also did a e-brake, but due to ~~not~~ insufficient of time & false signal, ~~into~~ my car skid and hit the rear of B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time 31/5/19 12.49pm

Reporting Centre Personnel's Signature
Name
NRIC/Photo

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



S K AUTO CONSULTANTS

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference: TP/019/0205SK

Your Reference: TBA

Date: 15/6/2019

TO: KHAI RAMBO CONSULTANCY
C/o AMA Autocare Pte Ltd
Enterprise Hub #01-36
36 Toh Guan Road East
Singapore 608580

Assessment of Vehicle No : SMG 1566L

Date of Accident : 29/05/2019

Date of Inspection : 31/05/2019

We have carried out a physical assessment of SMG 1566L at AMA Autocare Pte Ltd according to your instructions on 31/05/2019 and are pleased to submit our report as follows;

1.VEHICLE PARTICULARS

Registration No.	:	SMG 1566L
Make & Model	:	HONDA FREED HYBRID
Year of Registration	:	6/12/2018 (SEE NOTE IN NEXT PAGE)
Engine Capacity (cc)	:	1496
Chassis No.	:	GB71071507
Engine No.	:	LEB5605807
Colour	:	White
Mileage (km)	:	13817

2.VEHICLE CONDITION

Body Paint:	:	Good
Steering	:	Serviceable
Foot Brake	:	Serviceable
Parking Brake	:	Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size	:	Yokohama 185/65R15 - 80%
LH Make/Size	:	Yokohama 185/65R15 - 80%

Rear

RH Make/Size	:	Yokohama 185/65R15 - 80%
LH Make/Size	:	Yokohama 185/65R15 - 80%

Note: % denotes the remaining percentage of the tyre

S K AUTO CONSULTANTS


Our Reference TP/019/0205SK
Vehicle No. SMG 1566L

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the REAR portion

Please see attached schedule for details.



NOTE: The date of registration of SMG 1566L is 6 Dec 2018
As at the date of accident the car was about 6 months old

Estimated Amount : S\$11,402.68
Adjusted Amount : S\$8,600/-
Estimated Repair Days : 8 days

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 Days** from the date hereof, this report shall be treated as correct

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **S K AUTO CONSULTANTS** for any reliance on this report by any third party.

S K AUTO CONSULTANTS

Page No. 3

Our Reference TP/019/0205SK
Vehicle No. SMG 1566L

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	OUR ASSESSMENT(S\$)
PARTS (LIST ITEMS)				
1	Rear bumper	Deformed	1450.00	1450.00
2	Rear bumper side retainer @ \$62	Necessary	124.00	124.00
2	Rear bumper side reflectors @94.50	Refix	189.00	0.00
1	Rear tailgate	Distorted	1650.00	1650.00
1	Rear tailgate inner lock	Damaged	378.00	378.00
1	Rear tailgate inner trimboard	Deformed	528.00	528.00
2	Rear tailgate dampers @294.00	Dmg./Stiffened	588.00	588.00
1	Rear tailgate FREED emblem	Necessary	72.00	72.00
1	Rear tailgate Honda badge	Necessary	48.00	48.00
1	Rear tailgate HYBRID emblem	Necessary	78.00	78.00
1	Rear tailgate centre garnish	Refix	392.00	0.00
1	Rear tailgate weatherstrip	Deformed	211.60	211.60
1	Rear end panel	Distorted	978.00	978.00
1	Rear end panel top garnish	Deformed	378.00	378.00
1	Rear floor panel	Distorted	1245.00	1245.00
			8309.60	7728.60
			less 20%	20%
			1661.92	1545.72
			6647.68	6182.88
SPECIAL NETT ITEMS				
1set	Reverse sensor	Damaged	280.00	250.00
1	Reverse camera	Damaged	380.00	380.00
1set	Rear bumper clips	Necessary	60.00	50.00
1	Rear end panel sealant	Necessary	100.00	80.00
1	Rear number plate	Damaged	75.00	50.00
1set	Rear end panel top garnish clips	Necessary	60.00	40.00
1	Rear windscreen sealant	Necessary	100.00	80.00
1	Rear end panel sealant	Necessary	100.00	80.00
TOTAL PARTS			7802.68	7192.88

2822
20%
2257.60

770
XSVL
SVCX
969
242
X?SVL
X?SVL
65
62
XSVL
120
430
116
XSVL
200
XSVL
30
40
XSVL
20
60
Xrepeated
350

S K AUTO CONSULTANTS

Page No. 4

Our Reference TP/019/0205SK

Vehicle No. SMG 1566L

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00	1200.00 600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	1000.00 600
3	To remove, refix wiring system at accident damaged areas and check for proper function	250.00	180.00 X 200
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	250.00	180.00 60
5	To remove and replace reverse sensors and reverse camera and check for proper function	150.00	120.00 60
6	To remove and refix rear windscreen	140.00	120.00
7	To perform anti-rust treatment on affected areas	210.00	150.00 80
	Labour Total :	3600.00	2950.00 1520
	TOTAL (PARTS & LABOUR):	11402.68	10142.88

Note: (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements.

The final adjusted cost of repairs amount is Lump Sum contract amount of S\$8,600/-


S. Kumanan
Motor Surveyor

2257.60
350.00
1520.00
4127.60
202
3302.08
413-3,300
6 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2019		31 May 2019 15:58	S\$3,300.00 Edit Adj Rpt	S\$3,300.00 Edit Estimates		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	RIDE NOW PTE LTD, Co. Reg. No.: 201628643D			[Created by insurer]	
Main Claimant:	KHAI RAMBO CONSULTANCY				
Vehicle Reg. No.:	SMG1566L	Date of Loss:	29/05/2019 00:00 - :59 [5 Months and 23 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 595037	Policy/Cover Note No.:	29032696TMC (Third Party Only) Coverage: 27/10/2018 - 26/10/2019		
Vehicle Reg. No. (Insured):	SGS3283Y	Policy No. (Claimant):			
		Excess:			
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:				
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/08/2019]				
Adj Asg. Remarks:	on WP. Liab: Dispute (OI NR) TP Disagree on SJE- assign LKK Auto Consultants. Contact: Mr Melvin @ 8778 3636				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (13/08/2019): Report Send Back Alerts - SMG1566L (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMG1566L (595037)**
[SGS3283Y]

TP

KHAI RAMBO CONSULTANCY

May 29 2019 12:00AM

[RIDE NOW PTE LTD]

Ama Autocare Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	04/06/19 13:15	Accident Statement From: SC - Reg. No: SGS3283Y, Claimant: RIDE NOW PTE LTD		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	13/06/19 18:43	General View		Load JPG	☒
2	13/06/19 18:43	General View		Load JPG	☒
3	13/06/19 18:43	General View		Load JPG	☒
4	13/06/19 18:43	General View		Load JPG	☒
5	13/06/19 18:43	General View		Load JPG	☒
6	13/06/19 18:43	General View		Load JPG	☒
7	13/06/19 18:43	General View		Load JPG	☒
8	13/06/19 18:43	General View		Load JPG	☒
9	13/06/19 18:43	General View		Load JPG	☒
10	13/06/19 18:43	General View		Load JPG	☒
11	13/06/19 18:43	General View		Load JPG	☒
12	13/06/19 18:43	General View		Load JPG	☒
13	13/06/19 18:43	General View		Load JPG	☒
14	13/06/19 18:43	General View		Load JPG	☒
15	13/06/19 18:43	General View		Load JPG	☒
16	13/06/19 18:43	General View		Load JPG	☒
17	13/06/19 18:43	General View		Load JPG	☒
18	13/06/19 18:43	General View		Load JPG	☒
19	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
20	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
21	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
22	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
23	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
24	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
25	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
26	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
27	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
28	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
29	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
30	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒
31	13/06/19 18:45	Photographs of Damaged Parts		Load JPG	☒

Assessment Reports			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	13/06/19 18:45	Photo After Spray	 Load JPG	✓
33	13/06/19 18:45	Photo After Spray	 Load JPG	✓
34	13/06/19 18:45	Photo After Spray	 Load JPG	✓
35	13/06/19 18:45	Photo After Spray	 Load JPG	✓
36	13/06/19 18:45	Photo After Spray	 Load JPG	✓
37	13/06/19 18:45	Photo After Spray	 Load JPG	✓
38	13/06/19 18:45	Photo After Spray	 Load JPG	✓
39	13/06/19 18:45	Photo After Spray	 Load JPG	✓
40	13/06/19 18:45	Photo After Spray	 Load JPG	✓
41	13/06/19 18:45	Photo After Spray	 Load JPG	✓
42	13/06/19 18:45	Photo After Spray	 Load JPG	✓
43	13/06/19 18:45	Photo After Spray	 Load JPG	✓
44	13/06/19 18:45	Photo After Spray	 Load JPG	✓
45	13/06/19 18:45	Photo After Spray	 Load JPG	✓
46	13/06/19 18:45	Photo After Spray	 Load JPG	✓
47	13/06/19 18:45	Photo After Spray	 Load JPG	✓
48	13/06/19 18:45	Photo After Spray	 Load JPG	✓
49	13/06/19 18:45	Photo After Spray	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/05/19 18:14	TP PRI	 Load PDF	
2	31/05/19 08:21	TP disagree on SJE	 Load PDF	
3	10/08/19 11:54	TP SMG1566L E-file report	 Load PDF	
4	10/08/19 12:00	Survey report & Photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/19 14:35	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset Save Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

 (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

 Our File No: CS3/MSG19009681/R1QF3S2-1
 Date: 29/08/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29032696TMC
Claimant Vehicle No :	SMG1566L	Insured Vehicle No :	SGS3283Y
Date of Loss:	29/05/2019	Nature of Claim:	TP
		Claim No:	595037

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG1566L	Engine No:	LEB5605807
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71071507
Reg. Date:	06/12/2018 (Man. Year: 2018)	Odometer:	13817 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,802.68	2,607.60	5,195.08	66.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,520.00	2,080.00	57.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,402.68	4,127.60	7,275.08	63.80
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	11,402.68	3,300.00	8,102.68	71.06
+ GST 7.00/7.00% (S\$)	798.19	231.00	567.19	71.06
Nett Amount (S\$)	12,200.87	3,531.00	8,669.87	71.06

INSPECTION

Date of Assignment:	31/05/2019	
Date Inspected:	03/06/2019	Inspected At: Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36 Singapore 608580
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=828686&extid=305700&CFID=58246989&C... 1/4

8/29/2019

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2019)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG1566L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,450.00 FL	*770.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Serviceable	124.00 FL	*- FL
3	2		*REAR BUMPER SIDE REFLECTORS	Serviceable	189.00 FL	*- FL
4	1		*REAR TAILGATE	Distorted	1,650.00 FL	*969.00 FL
5	1		*REAR TAILGATE INNER LOCK	Damaged	378.00 FL	*242.00 FL
6	1		*REAR TAILGATE INNER TRIMBOARD	Serviceable	528.00 FL	*- FL
7	2		*REAR TAILGATE DAMPERS	Serviceable	588.00 FL	*- FL
8	1		*REAR TAILGATE FREED EMBLEM	Necessary	72.00 FL	*65.00 FL
9	1		*REAR TAILGATE HONDA BADGE	Necessary	48.00 FL	*48.00 FL
10	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	78.00 FL	*62.00 FL
11	1		*REAR TAILGATE CENTRE GARNISH	Serviceable	392.00 FL	*- FL
12	1		*REAR TAILGATE WEATHERSTRIP	Deformed	211.60 FL	*120.00 FL
13	1		*REAR END PANEL	Distorted	978.00 FL	*430.00 FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	378.00 FL	*116.00 FL
15	1		*REAR FLOOR PANEL	Serviceable	1,245.00 FL	*- FL
16	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
17	1		*REVERSE CAMERA	Serviceable	380.00 FS	*- FS
18	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
19	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
20	1		*REAR NUMBER PLATE	Serviceable	75.00 FS	*- FS
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
23	1		*REAR END PANEL SEALANT	Repeated	100.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	9,464.60	3,172.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,661.92	564.40

Total Parts (\$\$)	7,802.68	2,607.60
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.	New	1,400.00	600.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED .	New	1,200.00	600.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION.	New	250.00	0.00
4	TO REMOVE / REFIX INNER TRIMS, FITTINGS, GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR.	New	250.00	60.00
5	TO REMOVE AND REPLACE REVERSE SENSORS AND REVERSE CAMERA AND CHECK FOR PROPER FUNCTION.	New	150.00	60.00
6	TO REMOVE AND REFIX REAR WINDSCREEN.	New	140.00	120.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	New	210.00	80.00
Gross Labour Cost (S\$)			3,600.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >