

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SLF493L

MODEL : VOLKSWAGEN GOLF 1.4 TSI

POLICY NO : MA005101

CHASSIS NO : WVVZZZAUZGW089662

MANUFACTURE OF YEAR : 2015

DATE/TIME OF ACCIDENT: 12/08/2019 Time: 0800Hrs at MALAYSIA CUSTOMS TOWARDS SINGAPORE.

THIRD PARTY VEHICLE NO: SFX66M

Not Withheld

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 15/08/2019

Acknowledged by Repairer

Page : 1 of 2

Signature:

Date:

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price S\$	Condition	Amount S\$
1 Rear bumper	1	739.50	Dented	739.50
2 Rear bumper side retainer LH	1	27.30	Necessary	27.30
3 Rear bumper side retainer RH	1	27.30	Necessary	27.30
4 Rear bumper clip	12	1.60	Necessary	19.20
5 Rear bumper centre bracket	1	47.60	Broken	47.60
6 Rear bumper sensor	6	118.00	Malfunction	708.00
7 Rear bumper sensor ring	6	1.50	Necessary	9.00
8 Rear bumper sponge	3	80.00	Torn	240.00
9 Rear bumper reinforcement	1	322.00	Dented	322.00
10 Rear bumper lower garnish	1	221.00	Cut	221.00
11 Rear number plate lamp LH	1	16.80	Cracked	16.80
12 Rear number plate lamp RH	1	16.80	Cracked	16.80
13 Rear end panel	1	366.00	Dented	366.00
14 Rear end panel top garnish	1	89.80	Kinked	89.80

Sub-Total: 2,850.30

Less: 10% discount - 285.03

Total Parts after 10% discount: 2,565.27

Special Nett Items

1 Anti-rust coating	1	80.00	80.00
2 Rear number plate with casing	1	100.00	100.00
3 Rear end panel seal	1	120.00	120.00
			300.00

Total Parts: 2,865.27

Labour Charges For Rear Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,000.00
2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	750.00

- | | | | |
|---|--|--------|-----|
| 3 | Provide skill labour to disconnect and check electrical wiring | 60.00 | 101 |
| 4 | Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs | 150.00 | X |
| 5 | Provide skill labour to remove and replace bumper sensors | 80.00 | 7 |

Total Labour:

2,040.00

Total Parts & Labour:

4,905.27

GST 7%

343.37

Grand Total:

5,248.64

Estimate Repair Duration

~~08~~ days

ACCIDENT VEHICLE OF : SLF493L

Page : 2 of 2

1-2 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kennerly
Company : CLC
Date : 16/8/19
Time : 12pm
Contact No : 96910683
Email : _____