

22/07/2002

REF: CS / MSG 19014127 / DSf312 | Special Instruction:

ASS. REC. BY:

Meriman

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Zhang Han Yang of MSG Date/Time: 14.8.19 15.07 PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 87753 Insured: SLJ 26935

at Workshop m/s Chunni Tel: 65425119

of BIK 10 701-05 / 06

Policy No: 29114752 MKF Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 10.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS mpv^b H.O.D. Endorsement:

Date/Time: 14.8.19 3.52 PM Person Contacted: Lynn Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 87753 - CC6/III 16020877 / Geb 392 D.O.A - 29/10/2016
	SLJ 26935 - x
20/8/19	Send preli revised via meriman

Bryant Bryan

REF:

ASSIGNMENT

COB 2023 Dec

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHC 8775 J Yr Regn: Dec 2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai I40 C.C. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 707672 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDU504281
 C/No: KMHLB41UMGU080757
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205 / 60 R 16
 R: — 11 —

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Henkook

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 87 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 10/08/2019 D.O.I. 15/08/2019
 Survey held at Chunni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG BLJ26938
12/09/19	Final report 2/5 6250/- with 8 days of repair
	(\$ 9,283.68 red - 60%)
RECEIVED 13 SEP 2019	

Date/Time, File Pass to? 13/09/19
 1) Typist : Preli. Report : Final Report
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 8
 Resurvey No. of Trip: 2

Report Format :
 Lump Sum / I.B.I: (\$) 6,250/- 2/5

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee: _____
 Transportation: 200
 Photos: 11
 Others: _____
 TOTAL: 211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Zheng Hanyang

Date: 20 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLJ2693S	Accident Date	: 10/08/2019
TP Vehicle No	: SHC8775J	Assignment Date	: 14/08/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 7
Date of Inspection	: 15/8/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,538.68
Revised Amount	:S\$	7,012.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,012.28

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2019 11:20		14 Aug 2019 15:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC8775J	Date of Loss:	10/08/2019 17:00 - :59 [44 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLJ2693S	Policy No. (Claimant):	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Zheng Hanyang - 6594 2547]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian (Insured):	CHENG KIM MENG (/ Male), NRIC: S8004839D Email:		
Adj Asg. Remarks:	on WPO. OI:Grab. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene @ 6542 5119 / 6542 7162.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

MCD610105430 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 13/08/2019 15:21
 SUBMITTED BY: Catherine Par May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/08/2019 15:21
Date Of Accident	10/08/2019 17:30
Exact Location Of Accident	BLK 18 BEDOK SOUTH RD C/PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8775J
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD (COMPANY)
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	NG SIEW TIANG
NRIC No	S0054013G
Date Of Birth	20/12/1953
Occupation	OUTDOOR
Date Of Driving Pass	02/12/1974
Driving Experience	44 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98202767
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 18 #09-61 BEDOK SOUTH ROAD
 Postcode 460018
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLJ2693S
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRT RHT
 No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 13.08.2019 @ 1030HRS

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8775J

DATE : 13.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MRIC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>distorted / broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>NI</i>			\$ 99.20	X
	Front Bumper Reinforcement <i>NI</i>			\$ 402.10	X
	Front Bumper Grille (LH) <i>NI</i>			\$ 93.60	X
	Front Bumper Grille Airduct (LH) <i>NI</i>			\$ 26.20	X
	Front Bumper Bracket Top (LH) <i>NI</i>			\$ 22.40	X
	Front Bumper Bracket (LH) <i>broken</i>			\$ 24.60	✓
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	✓
	Headlamp (LH) <i>broken</i>			\$ 1,388.00	✓
	Front Fender (LH) <i>Buc</i>			\$ 566.30	✓
	Front Fender Apron Panel (LH) <i>& Dent</i>			\$ 637.00	✓
	Front Fender Shield (LH) <i>deformed</i>			\$ 174.90	✓
	Front Wheel Rim (LH) <i>NI</i>			\$ 325.30	X
	Front Wheel Hub Cap (LH) <i>cut</i>			\$ 107.10	✓
	Front Wheel Bearing <i>& Down</i>			\$ 540.50	✓
	Front Shock Absorber (Assy) (LH) <i>& distorted</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (LH) <i>NI</i>			\$ 108.80	X
	Front Drive Shaft (LH) <i>NI photo taken</i>			\$ 1,030.80	X
	Rack & Pinion Assy <i>photo taken Down</i>			\$ 969.60	✓
	STG Tie End <i>& distorted</i>			\$ 62.60	✓
	Front Suspension Lower Arm (LH) <i>& distorted</i>			\$ 529.30	✓
	Knuckle Arm (LH) <i>& distorted</i>			\$ 552.00	✓
	ABS Sensor <i>NI</i>			\$ 234.00	X
	Wiring-Engine <i>NI photo taken</i>			\$ 3,326.00	X
			7853.70		
			6282.96		
				\$ 13,522.10	
				\$ 2,704.42	
				\$ 10,817.68	
	Front Door Comfort Logo (LH) <i>NI</i>			\$ 75.00	Nett ✓
	Front Tyre (LH) <i>3/4</i>		75.00	\$ 216.00	Nett X
				\$ 291.00	

SHC 8775J

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,500.00 500/-
	Spray Painting Charge			S 1,000.00 500/-
	Wiring Charge			S 50.00 30/-
	Tuff Kote			S 50.00 40/-
	Towing Charge			S 50.00 20/-
	Remove/Refix Undercarriage (FRT)			S 200.00 150/-
	FRT Wheel Alignment			S 120.00 60/-
	Remove/Refix Aircon & Refill Gas			S 150.00 80/-
	Remove/Refix Dashboard		1510.00	S 450.00 200/-
	Remove/Refix Fuse Box			S 180.00 100/-
	Re-set Frt ABS System			S 200.00 150/-
	Diagnostic & Resetting To Erase Fault Code			S 480.00
	TOTAL LABOUR			S 4,430.00
	ESTIMATE TOTAL			S 15,538.68
	<p>15/08/2019 @ 0915hrs</p> <p>Not Actual</p> <p>1/sum 28 days</p> <p><u>nyau</u></p> <p>LKK Ando</p>		<p>7867.96</p> <p>1/56250/-</p>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 8775 J

Technician:

Mileage: 707672

Time Printed 15.8.19 9:56 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°39'		-3°00' 3°00'
3°51'		-0°19' 5°41'
-3°08'		-1°30' 1°30'
15°08'		
14°29'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°09'		-3°00' 3°00'
4°00'		-0°19' 5°41'
-0°45'		-1°30' 1°30'
17°47'		
16°37'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°30'		-3°00' 3°00'
-0°08'		-3°00' 3°00'
-2°39'		-3°00' 3°00'
-3°52'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°15'		-3°30' 2°30'
0°14'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°19'		-3°30' 2°30'
-0°11'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°05'		-3°00' 3°00'
0°03'		-3°00' 3°00'
0°13'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014127/DSF3N2

Date: 13/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29114756MKF
Claimant Vehicle No :	SHC8775J	Insured Vehicle No :	SLJ2693S
Date of Loss:	10/08/2019	Nature of Claim:	TP
		Claim No:	602587

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8775J	Engine No:	D4DFDU504281
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU080757
Reg. Date:	03/12/2015 (Man. Year: 2015)	Odometer:	707672 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	11,108.68	6,357.96	4,750.72	42.77	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,430.00	1,510.00	2,920.00	65.91	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	15,538.68	7,867.96	7,670.72	49.37	
Approved Total (Overridden) (S\$)		6,250.00			
	(S\$)	15,538.68	6,250.00	9,288.68	59.78
+ GST 7.00/7.00% (S\$)	1,087.71	437.50	650.21	59.78	
Nett Amount (S\$)	16,626.39	6,687.50	9,938.89	59.78	

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 15/08/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)
Blk 10 #01-05/06, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2019)
Parts: 143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8775J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Distorted/Broken	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*- FL
4	1		*FRONT BUMPER GRILLE (LH)	Not Necessary	93.60 FL	*- FL
5	1		*FRONT BUMPER GRILLE AIRDUCT (LH)	Not Necessary	26.20 FL	*- FL
6	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	22.40 FL	*- FL
7	1		*FRONT BUMPER BRACKET (LH)	Broken	24.60 FL	*24.60 FL
8	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
9	1		*HEADLAMP (LH)	Broken	1,388.00 FL	*1,388.00 FL
10	1		*FRONT FENDER (LH)	Buckled	566.30 FL	*566.30 FL
11	1		*FRONT FENDER APRON PANEL (LH)	Dented	637.00 FL	*637.00 FL
12	1		*FRONT FENDER SHIELD (LH)	Deformed	174.90 FL	*174.90 FL
13	1		*FRONT WHEEL RIM (LH)	Not Necessary	325.30 FL	*- FL
14	1		*FRONT WHEEL HUB CAP (LH)	Cut	107.10 FL	*107.10 FL
15	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
16	1		*FRONT SHOCK ABSORBER (ASSY)(LH)	Distorted	342.20 FL	*342.20 FL
17	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
18	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,030.80 FL	*- FL
19	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
20	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
21	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
22	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
23	1		*ABS SENSOR	Not Necessary	234.00 FL	*- FL
24	1		*WIRING-ENGINE	Not Necessary	3,326.00 FL	*- FL
25	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
26	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,813.10	7,928.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,704.42	1,570.74
Total Parts (\$\$)	11,108.68	6,357.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	500.00
2	SPRAY PAINTING CHARGE	New	1,000.00	500.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
9	REMOVE/REFIX DASHBOARD	New	450.00	0.00
10	REMOVE/REFIX FUSE BOX	New	180.00	0.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
12	RE-SET FRT ABS SYSTEM }	New	200.00	0.00
Gross Labour Cost (S\$)			4,430.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >