Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19014144/AGA3Q2

Date: 09/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: M495128/02

Claimant St W7163D Insured Vehicle No: SKK7040A

Vehicle No: SLW7163D Insured Vehicle No: SKK7040A

Date of Loss: 11/08/2019 Nature of Claim: TP Claim No: MCA190195

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW7163D

Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: HRA2565840A

Reg. Date: 28/02/2018 (Man. Year: 2017) Chassis No: SJNFEAJ11U2184392

Colour: Bronze Odometer: 145028 km

Engine Capacity: 1197 cc
Market Value/New Car
N/A

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: HIFLY 6 mm Rear Left Side: HIFLY 6 mm
Front Right Side: HIFLY 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,746.98	19,055.04	4,691.94	19.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	2,500.00	3,200.00	56.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,446.98	21,555.04	7,891.94	26.80
Approved Total (Overridden) (S\$)		18,000.00		
Nett Amount (S\$)	29,446.98	18,000.00	11,446.98	38.87
+ Loss of Use (10.0 x S\$6	60.00/day) (S\$)	600.00		
+ Doc/Search Fee (S\$)		7.45		
+ Ot	her Costs (S\$)	80.00		
Net	tt Liability (S\$)	18,687.45		
Global Sum S	Settlement (S\$)	19,000.00		

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 14/08/2019 Inspected At: Premium Carz Services Pte Ltd (HQ)

1 Kaki Bukit Ave 6 #01-90

Autobay@Kaki Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster Report Page 2 of 5

Adjuster: ADRIAN LING Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Feb 2020)

Parts: M1-SUV NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW7163D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	682.90 FN	*682.90 FN
2	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	48.00 FN	*48.00 FN
3	1		*FRONT BUMPER MUDFLAP RH	Cut	168.90 FN	*168.90 FN
4	1		*FRONT BUMPER REINFORCEMENT -TOP	Bent	775.40 FN	*591.00 FN
5	1		*FRONT BUMPER REINFORCEMENT TOP BRACKET RH	Bent	193.70 FN	*193.70 FN
6	1		*FRONT BUMPER REINFORCEMENT TOP BRACKET LH	Not Necessary	193.70 FN	*-FN
7	1		*FRONT BUMPER REINFORCEMENT LOWER	Bent	415.70 FN	*307.00 FN
8	1		*FRONT BUMPER SPONGE -TOP	Cracked	350.90 FN	*207.00 FN
9	1		*FRONT BUMPER SPONGE -BOTTOM	Cracked	200.90 FN	*200.90 FN
10	1		*TOW HOOK COVER	Not Necessary	30.10 FN	*-FN
11	1		*FRONT GRILLE BASE W/CHROME	Cracked	536.70 FN	*536.70 FN
12	1		*FRONT GRILLE NISSNA LOGO W/GARNISH	Necessary	89.30 FN	*89.30 FN
13	1		*FRONT NUMBER PLATE BASE	Deformed	254.20 FN	*254.20 FN
14	1		*FOG LAMP BRACKET RH	Bent	186.00 FN	*186.00 FN
15	1		*FOG LAMP TOP COVER RH	Cut	156.10 FN	*156.10 FN
16	1		*HEADLAMP LED RH	Cracked	3,243.00 FN	*2,864.40 FN
17	1		*HEADLAMP LOWER BRACKET RH	Cracked	75.00 FN	*75.00 FN
18	1		*BUZZER	Not Necessary	192.00 FN	*-FN
19	1		*FRONT WHEELHOUSE RH (NPA)	Repair	0.00 FN	*- FN
20	1		*FRONT FENDER RH	Distorted	783.90 FN	*783.90 FN
21	1		*FRONT FENDER WHEEL ARCH W/CLIP RH	Distorted	584.40 FN	*584.40 FN
22	1		*FRONT FENDER INNER SHIELD RH	Torn	158.40 FN	*158.40 FN
23	1		*FRONT LOWER ARM RH	Bent	349.60 FN	*349.60 FN
24	1		*FRONT LINKAGE RH	Bent	65.30 FN	*65.30 FN
25	1		*FRONT DRIVESHAFT RH	Bent	1,658.20 FN	
26	1		*CROSSMEMBER	Bent	739.40 FN	*739.40 FN
27	1		*CROSSMEMBER EXTENSION RH	Bent	280.00 FN	*280.00 FN
28	1		*FRONT CHASSIS RH (NPA)	Repair	0.00 FN	*-FN
29	1		*WIPER TANK W/MOTOR	Deformed	281.60 FN	*281.60 FN
30	1		*AIR DEFLECTOR RH	Cracked	262.90 FN	*98.00 FN
31	1		*AIR DEFLECTOR LH	Cracked	262.90 FN	*98.00 FN
32	1		*RADIATOR	Bent	792.90 FN	*792.90 FN
33	1		*RADIATOR LOWER CARNISH	Deformed	141.00 FN	*141.00 FN
34	1		*RADIATOR SDARE TANK	Deformed	146.00 FN	*146.00 FN
35	1		*RADIATOR SPARE TANK	Deformed	268.10 FN	*268.10 FN
36	1		*AIR-CON CONDENSER	Bent	743.20 FN	*743.20 FN
37	1		*INTER COOLER *CANISTER (CHARCOAL EILTER)	Dented Not		*2,121.60 FN * EN
38	1		*CANISTER (CHARCOAL FILTER)	Not Necessary	222.10 FN	*-FN
	Report was unsubmitted during this print-out.					

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge... 9/4/2020

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*BONNET	Dented	1,161.30 FN	*1,067.00 FN
40	1		*BONNET WEATHERSTRIP (LONG)	Not Necessary	269.30 FN	*- FN
41	1		*BONNET WEATHERSTRIP (SHORT)	Not Necessary	224.20 FN	*- FN
42	2		*BONNET HINGES	Not Necessary	110.00 FN	*-FN
43	1		*BONNET LOCK	Not Necessary	60.80 FN	*- FN
44	1		*BONNET STAND	Not Necessary	167.00 FN	*- FN
45	1		*BONNET STAND CLIP	Not Necessary	64.00 FN	*-FN
46	1		*SUPPORT PANEL	Repair	618.50 FN	*- FN
47	1		*ENGINE UNDER COVER	Cracked	398.00 FN	*398.00 FN
48	1		*FRONT SPORT RIM RH	Cut	1,781.50 FN	*1,231.90 FN
49	1		*FRONT NUMBER PLATE	Cracked	100.00 FS	*60.00 FS
50	1		*FRONT NUMBER PLATE CASING	Cracked	40.00 FS	*25.00 FS
51	1		*FRONT TYRE RH	Not Necessary	450.00 FS	*-FS
52	1		*FOG LAMP RH	Cracked	373.70 FS	*373.70 FS
53	1		*SET PARKING SENSOR	Damaged	220.00 FS	*200.00 FS
54	1		*HEADLAMP BULB RH	Not Necessary	35.00 FS	*-FS
55	1		*SIGNAL LAMP BULB RH	Not Necessary	15.00 FS	*-FS
56	1		*SMALL LIGHT BULB RH	Not Necessary	15.00 FS	*-FS
57	10		*RADIATOR GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
58	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
59	8		*FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*30.00 FS
60	1		*FRONT ABSORBER RH	Bent	660.30 FS	*547.50 FS
61	1		*FRONT KNUCKLE ARM RH	Damaged	667.00 FS	*534.00 FS
62	1		*FRONT WHEEL HUB BEARING RH	Damaged	448.60 FS	*354.00 FS
63	1		*AUTO OIL	Necessary	125.00 FS	*100.00 FS
64	1		*COOLANT	Necessary	60.00 FS	*40.00 FS
65 F=Fra	10 anchise	part. S=S	*ENGINE UNDER COVER CLIP SpcNett. N=NettItemDisc.	Necessary	50.00 FS	*30.00 FS
		•	•	Sub Total (S\$)	26,007.80	20,911.80
			- Nett Item Discount on N Ite		•	1,856.76

- Nett Item Discount on N Items 10.00/10.00% (\$\$) 2,260.82 1,856.76

Total Parts (S\$) 23,746.98 19,055.04

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	180.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,800.00	800.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,400.00	800.00
4	TO RESET HEADLAMP LED CONTROL UNIT RH	New	250.00	50.00
5	TO KNOCK AND RESHAPE FRONT CHASSIS RH	New	350.00	0.00
6	TO CHECK AND ALIGN WHEELS WITH COMPUTERIZED WHEEL ALIGNMENT	New	120.00	80.00
7	TO SPRAY ANTI-RUST UNDERCOAT	New	200.00	80.00
8	TO REMOVE AND REPLACE FRONT SUSPENSION AND UNDERCARRIAGE RH	New	450.00	280.00
9	TO CUT AND WELD ,TO KNOCK AND RESHAPE FRONT SUPPORT PANEL AND FRONT WHEELHOUSE RH	New	350.00	200.00
10	TO REMOVE AND REPLACE RADIATOR AND ELECTRIC FANS AND TO CONTROL PRESSURE TEST	New	250.00	60.00
11	TO REMOVE AND REPLACE DAMAGED AIR-CON CONDENSER, INTER COOLER, AND TO VACUUM, AIR-CON SYSTEM AND CHARGE UP AIR-CON GAS	New	350.00	120.00
	Gross Labor	ur Cost (S\$)	5,700.00	2,500.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >