

ASS. REC. BY:

REF: CS/MSG 19014181 / Dtf3n2

Special Instruction:

Survivor: Bryan

ASSIGNMENT (Office)

From (Person): Mhd Ashraf Madi

of

MSG

Date/Time: 15.8.19 11.18 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 33512

Insured: GR 669 D

at Workshop m/s SWH HOCK

Tel: 6542 5119

of BIK 10 Amr Indusian / Park 2A #01-05

Policy No: 290780 GIMV

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 15.8.19 11.35 a.m

Person Contacted:

Man

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 33512 - MBA1 MSG 19014181 / Y

D.O.A - 13/03/2019

GR 669 D MZA / MSG 19014181 / Y

D.O.A - 13/03/2019

23/8-

Pensed via menimen

REF:

ASSIGNMENT

05 Oct 2022

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 3351 L

Yr Regn:

Oct 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

c.c

1685

Colour:

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading:

531303

T/Radio:

Insured / Std / NI / NA

Eng/No:

D4FDFU539910

C/No:

KMHLB41UMB061630

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Ni / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

13/08/2019

D.O.I.

15/08/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S y Rnd

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSIG GR 669D

04/10/2019

Insured: 18967.46 / 5776

RECEIVED 67 OCT 2019

4/10/2019

Date/Time: File Pass to?



Preli. Report

1) 4/10 Typist



Final Report

Date/Time: File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

250

Photos

Others

TOTAL

261

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$) 4000/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 23 Aug 2019

Preliminary Advice

Insured Vehicle No	: GR6669D	Accident Date	: 13/08/2019
TP Vehicle No	: SHB3351L	Assignment Date	: 15/08/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 10.00
Date of Inspection	: 15/08/2019		
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,967.46
Revised Amount	:S\$	20,648.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,648.90

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2019		15 Aug 2019 11:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	POO GENERAL CONSTRUCTION, Co. Reg. No.: 53360315C		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHB3351L	Date of Loss:	13/08/2019 09:00 - :59 [57 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29078067TMV (Third Party Only) Coverage: 12/04/2018 - 11/04/2020
Vehicle Reg. No. (Insured):	GR6669D	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/08/2019]		
Driver/Custodian (Insured):	KHO BUN POO (60 / Male) , NRIC: S2558876B Email:		
Adj Asg. Remarks:	on WP. Liab:100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene at 6542 5119 / 6542 7162.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD619100333 / ComforDolGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 14/08/2019 10:40
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/08/2019 10:40
 Date Of Accident 13/08/2019 09:20
 Exact Location Of Accident PIE(TUAS) >>BUKIT BATOK EAST AVE 3
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB3351L
 Insured/Policyholder
 Name Of Registered Owner CITYCAB PTE LTD
 Co Reg No 199502839G
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI
 Model I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088937MFSH

Cover Note Number**Driver**

Name of Driver SOO HOO KA
 NRIC No S0770388J
 Date Of Birth 13/02/1948
 Occupation OUTDOOR
 Date Of Driving Pass 29/11/1967
 Driving Experience 51 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97869399
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 317 WOODLANDS STREET 31 #04-180
 Postcode 730317
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1

NAME: : -

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GR6669D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number 96229620
 Address
 Postcode
 Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLR4147Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	85791668
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SOO HOO KA
Approximate Age	71
Injuries Sustain	NECK SPRAIN / GIDDY
Injured person in which vehicle?	SHB3351L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	TAXI PASSENGER
Approximate Age	
Injuries Sustain	SPRAIN NECK
Injured person in which vehicle?	SHB3351L
Were seat bolts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839G


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 13.08.2019@ 1300HRS


Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PIE

Twds

On 13.08.2019 @ 0920hrs I was travelling along ~~Toh Tuck AVE~~ Twds Bukit Batok East AVE 3 with one male passenger onboard.

My vehicle stopped while waiting for green light. While waiting, suddenly veh(B) GR 6669D hit onto my vehicle and caused my vehicle to surge forward and hit onto veh(C) SLR 4147Y.

I have company video and photos at scene to support my claims.

After the accident my male passenger's neck was sprained.

I felt giddy and will consult a doctor later.

Veh(B) GR 6669D Male Driver HP: 9622 9620

Veh(C) SLR 4147Y Male Driver HP: 8579 1668

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 13.08.2019 @ 1300HRS

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 3351L

DATE : 13.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>broken</i>			\$ 251.00 ✓
	Radiator Grille H Emblem <i>NH</i>			\$ 27.50 X
	Front Bumper Cover <i>mondy broken</i>			\$ 544.50 ✓
	Front Bumper Sponge <i>SVC</i>			\$ 99.20 X
	Front Bumper Reinforcement <i>SVC</i>			\$ 402.10 X
	Front Bumper Centre Grille <i>NH</i>			\$ 178.60 X
	Front Bumper Bracket Top (LH/RH) <i>NH</i>		\$ 22.40	\$ 44.80 X
	Front Bumper Bracket (LH/RH) <i>NH</i>		\$ 24.60	\$ 49.20 X
	Headlamp Support Top Cover <i>NH</i>			\$ 222.60 X
	Headlamp Support Panel Assy <i>broken</i> <i>NH</i>			\$ 907.40 ✓ <i>broken</i>
	Headlamp (LH/RH) <i>mondy broken</i>		\$ 1,388.00	\$ 2,776.00 ✓
	Radiator <i>broken</i> <i>NH</i>			\$ 698.30 ✓ <i>broken</i>
	Radiator Fan Blade, Cowling, Motor Assy <i>NH</i>			\$ 792.95 X
	Radiator Bracket (RH/LH) <i>NH</i>		\$ 6.50	\$ 13.00 X
	Radiator Guard <i>SVC N/S 0/3 broken</i>		\$ 20.00	\$ 40.00 ✓
	Horn Unit (LH/RH) <i>0/3 broken N/S SVC</i>		\$ 73.80	\$ 147.60 ✓
	Aircon Condenser <i>broken</i> <i>NH</i>			\$ 927.50 ✓ <i>broken</i>
	Inter Cooler <i>broken</i> <i>NH</i>			\$ 1,032.50 ✓ <i>broken</i>
	Inter Cooler Mounting (2 PCS) <i>NH</i>			\$ 25.90 X
			3665.30	
			2932.24	
	SUB TOTAL			\$ 9,180.65
	LESS 20%			\$ 1,836.13
	DISCOUNTED TOTAL			\$ 7,344.52
	Front Number Plate <i>Crack</i>			\$ 25.00 ✓ <i>Crack</i>
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00 ✓ <i>broken</i>
			45.00	
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ -1,000.00 400/-
	Spray Painting Charge			\$ -250.00 200/-
	Wiring Charge			\$ 50.00 30/-
	Towing Charge			\$ 50.00 NH
	Remove/Refix Aircon & Refill Gas			\$ -150.00 87 NH
			630.00	
	TOTAL LABOUR			\$ 1,500.00

SHB 3351L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>gnc</i>			\$ 2,174.90
	Boot Lid Rubber <i>deformed</i>			\$ 96.50
	Boot Lid Hinge (LH/RH) <i>NH</i>		\$ 142.30	\$ 284.60
	Boot Lid Lock Upper <i>Down</i>			\$ 102.60
	Boot Lid Lock Lower <i>ray</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>NHC</i>			\$ 28.70
	Boot Lid CRDI Plate <i>NHC</i>			\$ 27.90
	Boot Lid Lamp (LH) <i>broken</i>			\$ 565.60
	Boot Lid Trimboard <i>deformed</i>			\$ 116.40
	Boot Lid Trimboard Clips (10pcs) <i>NHC</i>			\$ 11.00
	Bootlid Moulding <i>wt</i>			\$ 85.00
	Bootlid i40 Emblem <i>NHC</i>			\$ 27.90
	Bootlid Lower Garnish <i>wt</i>			\$ 227.90
	Rear Bumper <i>broken</i>			\$ 553.00
	Rear Bumper Reinforcement <i>broken</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>N/S</i>	<i>N/S</i>	<i>S O/S N/A</i> 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>NHC</i>			\$ 22.00
	Rear Bumper Bracket, LH <i>broken</i>			\$ 35.60
	Rear Bumper Sponge <i>broken</i>			\$ 118.40
	Rear Bumper Under Cover <i>broken</i>			\$ 228.00
	Rear Bumper Reflector Lamp (LH) <i>broken</i>			\$ 30.60
	Tail Lamp (LH) <i>broken</i>			\$ 697.80
	Tail Lamp Quarter Panel (LH) <i>Deformed</i>			\$ 226.50
	Rear Panel <i>BNC</i>			\$ 526.70
	Rear Panel Garnish <i>wt/deformed</i>			\$ 57.70
	Rear Panel Lower Panel <i>BNC</i>			\$ 495.50
	Spare Tyre Holder <i>broken</i>			\$ 223.10
	Spare Tyre Panel <i>Deformed</i>			\$ 852.80
	Spare Tyre Panel Cushion <i>NH</i>			\$ 209.05
	Rear Towing Hook <i>NH</i>			\$ 94.60
	Member Assy- Rear Floor Centre <i>NH</i>			\$ 570.40
	Panel Assy-Rear Floor Side (LH) <i>NH</i>			\$ 90.10
	Rear Floor Chassis Member (LH) <i>NH</i>			\$ 3,636.20
	Exhaust Pipe Insulator <i>NH</i>	\$	58.55	\$ 117.10
	Exhaust Silencer <i>N/S</i> <i>wt</i> <i>O/S</i> <i>NH</i>	\$	967.70	\$ 1,935.40
	Exhaust Pipe Hanger <i>NH</i>	\$	58.55	\$ 117.10
	Exhaust Pipe Centre <i>NH</i>			\$ 730.10
	Rear Fender With Housing (LH) <i>BNC</i>			\$ 4,736.80
	Rear Fender Inner Lining (LH) <i>NH</i>			\$ 169.30
	Rear Fender Air-Duct <i>NH</i>			\$ 225.60
	Rear Fender Trim Board (LH) <i>deformed</i>			\$ 188.75
	Rear Windscreen Moulding <i>NHC</i>			\$ 28.30
	Fuel Tank <i>NH</i>			\$ 962.90
	Fuel Tank Sub Hose <i>NH</i>			\$ 78.20
	Fuel Tank Upper Neck <i>NH</i>			\$ 221.10
	Fuel Lid Outer Garnish <i>NHC</i>			\$ 59.40
			14021.75	
			11217.40	
				\$ 22,607.80
				\$ 4,521.56
				\$ 18,086.24
	SUB TOTAL			\$ 22,607.80
	LESS 20%			\$ 4,521.56
	DISCOUNTED TOTAL			\$ 18,086.24

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014181/DTF3N2

Date: 10/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29078067
Claimant Vehicle No :	SHB3351L	Insured Vehicle No :	GR6669D
Date of Loss:	13/08/2019	Nature of Claim:	TP
		Claim No:	602955

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3351L	Engine No:	D4DFDU539910
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMEU061630
Reg. Date:	30/10/2014 (Man. Year: 2014)	Odometer:	531303 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	26,097.46	14,806.34	11,291.12	43.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,870.00	2,760.00	4,110.00	59.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,967.46	17,566.34	15,401.12	46.72
Approved Total (Overridden) (S\$)		14,000.00		
(S\$)	32,967.46	14,000.00	18,967.46	57.53
+ GST 7.00/7.00% (S\$)	2,307.72	980.00	1,327.72	57.53
Nett Amount (S\$)	35,275.18	14,980.00	20,295.18	57.53

INSPECTION

Date of Assignment:	15/08/2019	
Date Inspected:	15/08/2019	Inspected At: Chunni Motor Work Pte Ltd - Amk Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	10.0 days	

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3351L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	251.00 FL	*251.00 FL
2	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	27.50 FL	*- FL
3	1		*FRONT BUMPER COVER	Mounting Broken	544.50 FL	*544.50 FL
4	1		*FRONT BUMPER SPONGE	Serviceable	99.20 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Serviceable	402.10 FL	*- FL
6	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	178.60 FL	*- FL
7	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
8	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
9	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
10	1		*HEADLAMP SUPPORT PANEL ASSY	Not Necessary	907.40 FL	*- FL
11	2		*HEADLAMP (LH/RH)	Mounting Broken	2,776.00 FL	*2,776.00 FL
12	1		*RADIATOR	Not Necessary	698.30 FL	*- FL
13	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
14	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
15	1		*RADIATOR GUARD	O/s Broken/N/s Serviceable	40.00 FL	*20.00 FL
16	1		*HORN UNIT (LH/RH)	O/s Broken/N/s Serviceable	147.60 FL	*73.80 FL
17	1		*AIRCON CONDENSER	Not Necessary	927.50 FL	*- FL
18	1		*INTER COOLER	Not Necessary	1,032.50 FL	*- FL
19	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
20	1		*BOOT LID	Buckled	2,174.90 FL	*2,174.90 FL
21	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
22	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
23	1		*BOOT LID LOCK UPPER	Damaged	102.60 FL	*102.60 FL
24	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
25	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
26	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
27	1		*BOOT LID LAMP (LH)	Broken	565.60 FL	*565.60 FL
28	1		*BOOT LID TRIMBOARD	Deformed	116.40 FL	*116.40 FL
29	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
30	1		*BOOTLID MOULDING	Bent	85.00 FL	*85.00 FL
31	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
32	1		*BOOTLID LOWER GARNISH	Bent	227.90 FL	*227.90 FL
33	1		*REAR BUMPER	Broken	553.00 FL	*553.00 FL
34	1		*REAR BUMPER REINFORCEMENT	Broken	428.40 FL	*428.40 FL
35	1		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	N/s Bent/O/s Not Necessary	160.60 FL	*80.30 FL
36	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
37	1		*REAR BUMPER BRACKET,LH	Broken	35.60 FL	*35.60 FL
38	1		*REAR BUMPER SPONGE	Broken	118.40 FL	*118.40 FL
39	1		*REAR BUMPER UNDER COVER	Broken	228.00 FL	*228.00 FL
40	1		*REAR BUMPER REFLECTOR LAMP (LH)	Broken	30.60 FL	*30.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*TAIL LAMP (LH)	Broken	697.80 FL	*697.80 FL
42	1		*TAIL LAMP QUARTER PANEL (LH)	Dented	226.50 FL	*226.50 FL
43	1		*REAR PANEL	Buckled	526.70 FL	*526.70 FL
44	1		*REAR PANEL GARNISH	Bent/Deformed	57.70 FL	*57.70 FL
45	1		*REAR PANEL LOWER PANEL	Buckled	495.50 FL	*495.50 FL
46	1		*SPARE TYRE HOLDER	Broken	223.10 FL	*223.10 FL
47	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
48	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
49	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
50	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
51	1		*PANEL ASSY-REAR FLOOR SIDE (LH)	Not Necessary	90.10 FL	*- FL
52	1		*REAR FLOOR CHASSIS MEMBER (LH)	Not Necessary	3,636.20 FL	*- FL
53	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
54	1		*EXHAUST SILENCER	N/s Bent/O/s Not Necessary	1,935.40 FL	*967.70 FL
55	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
56	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
57	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
58	1		*REAR FENDER WITH HOUSING (LH)	Buckled	4,736.80 FL	*4,736.80 FL
59	1		*REAR FENDER AIR-DUCT	Not Necessary	225.60 FL	*- FL
60	1		*REAR FENDER TRIM BOARD (LH)	Deformed	188.75 FL	*188.75 FL
61	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
62	1		*FUEL TANK	Not Necessary	962.90 FL	*- FL
63	1		*FUEL TANK SUB HOSE	Not Necessary	78.20 FL	*- FL
64	1		*FUEL TANK UPPER NECK	Not Necessary	221.10 FL	*- FL
65	1		*FUEL LID OUTER GARNISH	Cracked	59.40 FL	*59.40 FL
66	1		*FRONT NO PLATE TRIM COVER }	Broken	30.00 FS	*45.00 FS
67	1		*FRONT NUMBER PLATE }	Cracked	25.00 FS	*- FS
68	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
69	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
70	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
71	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
72	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
73	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
74	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	32,455.15	18,343.75
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,357.69	3,537.41
Total Parts (\$\$)	26,097.46	14,806.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,000.00	1,400.00
2	SPRAY PAINTING CHARGE	New	1,750.00	1,000.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	50.00	0.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
6	TUFF KOTE	New	100.00	40.00
7	REAR CHASSIS ALIGNMENT CHARGE	New	400.00	0.00
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE/REFIX FUEL TANK	New	150.00	0.00
12	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
13	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
Gross Labour Cost (\$\$)			6,870.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >