

22/03/2003

ASS. REC. BY:

REF: CS/FCI 19014182/ D9f3n2

Special Instruction:

Surveyor Bryan

ASSIGNMENT (Office)

From (Person): Joanny of FCI Date/Time: 15.8.19 10.11a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 1802K Insured: SHC 8117J

at Workshop m/s Chummi Motor Tel: 65427162

of Soon Hock Motor #01-05706

Policy No: Claim No: D19005229 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 12.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15.8.19 10.30a.m Person Contacted: Lum Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 1802K - CCB/TM 16005199/ A26292 D.O.A. - 17/03/2016
	SHC 8117J - CS/FCI 18021667/ K15502 D.O.A. - 24/11/2018
20/8/19 @ 2.55pm	revised to Joanne Yong by email.


Bryan

REF:

ASSIGNMENT

02 July 2026

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 1802K Yr Regn: 2018 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Ioniq C.C. 1580
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 188642 T/Radio: Insured / Std / NI / NA
 Eng/No: G4LEJU045587
 C/No: KMHC851CVJU103412
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil S/Rim / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Davanti

Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 12/08/2019 D.O.I. 15/08/2019

Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHC 81175

12/09/19 Insured 2/3 7950/- with 7 days of rep
used 16530.28, 57%

RECEIVED 12 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) 12/9/2019
 Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 7950

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

13/9/19

Photos

Others

TOTAL

8x15=120

170+120
50
50+50
116
556



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005229MFSH
Our Ref: CS/FCI19014182/Dqf3

Date: 20 August 2019

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 1802K.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/08/2019 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 18,480.28 .
Revised Estimate Amount	: S\$ 8,436.76 .
"Check" Items Amount	: S\$ 290.88 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	14-08-2019	Our Ref No. D19005229MFSH
Accident Date	12-08-2019	Claim Type. Third Party
Insured Vehicle	SHC8117J	Third Party Vehicle. SHC1802K
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 20 August 2019 2:55 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005229MFSH/1
Attachments: CSFCI19014182Dqf3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 1802K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 15 August 2019 10:11 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005229MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 15 August 2019 9:48 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005229MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>NH</i>			\$ 1,227.50 X
	Front Bumper Cover <i>broken</i>			\$ 418.30 ✓
	Front Bumper Grille (LH) <i>Cut</i>			\$ 186.90 ✓
	Front Bumper Centre Moulding <i>broken</i>			\$ 188.00 ✓
	Front Bumper Bracket Top (LH) <i>NH</i>			\$ 35.00 X
	Front Bumper Bracket (LH) <i>broken NH</i>			\$ 28.00 X
	Front Bumper Clips 10 pcs <i>Nec</i>			\$ 22.00 ✓
	Headlamp Support Panel Assy <i>X broken</i>			\$ 949.30 Z ✓
	Headlamp (LH) <i>broken</i>			\$ 1,198.80 ✓
	Day Light, LH <i>X mostly broken</i>			\$ 642.50 Z ✓
	Front Fender (LH) <i>Buc</i>			\$ 490.70 ✓
	Front Fender Shield (LH) <i>distorted</i>			\$ 114.70 ✓
	Emblem-Blue Drive (LH) <i>Nec</i>			\$ 26.60 ✓
	Front Wheel Rim (LH) <i>Cut</i>			\$ 1,124.20 ✓
	Front Wheel Hub Cap (LH) <i>NB</i>			\$ 346.40 X
	Front Wheel Bearing <i>X Dam</i>			\$ 454.00 Z ✓
	Front Shock Absorber (Assy) (LH) <i>X distorted</i>			\$ 372.50 Z ✓
	Front Shock Absorber Mounting (LH) <i>NH</i>			\$ 206.90 X
	Front Drive Shaft (LH) <i>NH photo taken</i>			\$ 936.70 X
	Rack & Pinion Assy <i>NH photo taken</i>			\$ 887.40 X
	STG Tie End <i>X distorted</i>			\$ 94.70 Z ✓
	Front Suspension Lower Arm (LH) <i>X distorted</i>			\$ 296.80 Z ✓
	Knuckle Arm (LH) <i>X distorted mix</i>			\$ 363.60 Z ✓
	Engine Crossmember <i>NH photo taken distorted</i>			\$ 1,803.90 Z ✓
	Wiring Engine <i>NH photo taken</i>			\$ 3,474.00 X
	SUB TOTAL		8383.90	\$ 15,889.40
	LESS 20%		6767.12	\$ 3,177.88
	DISCOUNTED TOTAL			\$ 12,711.52
	Front Door Comfort Logo (LH) <i>Nec</i>			\$ 75.00 Nett ✓
	Front Tyre (LH) <i>S/C</i>		75.00	\$ 216.00 Nett X
				\$ 291.00

SHC 1802K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,000.00 500/-
	Spray Painting Charge			\$ 750.00 500/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Towing Charge			\$ 90.00 70/-
	Remove/Refix Undercarriage (FRT)			\$ 400.00 150/-
	Front Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Dashboard			\$ 450.00 70/-
	Remove/Refix Fuse Box			\$ 180.00 70/-
	Re-set Frt ABS System			\$ 200.00
	Diagnostic & Resceting To Erase Fault Code			\$ 480.00 320/-
	TOTAL LABOUR			\$ 3,920.00
	ESTIMATE TOTAL			\$ 16,922.52
	15/08/2019 @ 0930hrs NA Antenna 2/3hrs 7 days. ryan LKK Auto		1680.00 8462.12 1497.76 9959.88 457950/-	
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

FAX : 6542 6039

Page 1 of 1

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 1802 K

Technician:

Mileage: 188642

Time Printed 15.8.19 10:16 AM

HYUNDAI IONIQ

Front : Left

Actual	BEFORE	Specified Range
-0°11'		-3°00' 3°00'
4°48'		-0°19' 5°41'
-3°14'		-1°30' 1°30'
19°20'		
19°09'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°11'		-3°00' 3°00'
4°48'		-0°19' 5°41'
-0°15'		-1°30' 1°30'
18°10'		
16°59'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
1°00'		-3°00' 3°00'
0°00'		-3°00' 3°00'
1°10'		-3°00' 3°00'
-3°29'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°14'		-3°30' 2°30'
-0°14'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°44'		-3°30' 2°30'
-0°06'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°30'		-3°00' 3°00'
-0°19'		-3°00' 3°00'
-0°04'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014182/Dqf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8117J	Veh. Inspected	SHC 1802K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005229MFSH	Excess (\$)	0.00	
Assign From	JOANNEY	Assign Date	15/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHC851CVJU103412	Colour	BLUE	
Odometer	188642	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	5 mm	
L/H Front Tyre	195/65 R15	DAVANTI	5 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/08/2019	Inspection Date	15/08/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1802K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE	NOT NECESSARY	1,227.50	-
1	FRONT BUMPER COVER	BROKEN	418.30	418.30
1	FRONT BUMPER GRILLE (LH)	CUT	186.90	186.90
1	FRONT BUMPER CENTRE MOULDING	BROKEN	188.00	188.00
1	FRONT BUMPER BRACKET TOP (LH)	NOT NECESSARY	35.00	-
1	FRONT BUMPER BRACKET (LH)	NOT NECESSARY	28.00	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	949.30	949.30
1	HEADLAMP (LH)	BROKEN	1,198.80	1,198.80
1	DAY LIGHT,LH	MOUNTING BROKEN	642.50	642.50
1	FRONT FENDER (LH)	BUCKLED	490.70	490.70
1	FRONT FENDER SHIELD (LH)	DEFORMED	114.70	114.70
1	EMBLEM-BLUE DRIVE (LH)	NECESSARY	26.60	26.60
1	FRONT WHEEL RIM (LH)	CUT	1,124.20	1,124.20
1	FRONT WHEEL HUB CAP (LH)	NO SUCH PARTS	346.40	-
1	FRONT WHEEL BEARING	DAMAGED	454.00	454.00
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	372.50	372.50
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	206.90	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	936.70	-
1	RACK & PINION ASSY	NOT NECESSARY	887.40	-
1	STG TIE END	DISTORTED	94.70	94.70
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	296.80	296.80
1	KNUCKLE ARM (LH)	NOT NECESSARY	363.60	-
1	ENGINE CROSSMEMBER	DISTORTED	1,803.90	1,803.90
1	WIRING-ENGINE	NOT NECESSARY	3,474.00	-
1	FRONT DOOR (LH)(ADDITIONAL)	BENT	1,797.20	1,797.20
	LESS 20% DISCOUNT		-3,537.32	-2,036.22
			14,149.28	8,144.88
SPECIAL NETT ITEMS				
1	FRONT DOOR COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00

Report Ref No. CS/FCI19014182/Dqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE (LH)(SN)	SERVICEABLE	216.00	-
			291.00	75.00
	LABOUR			
	TRANSFER OF DOOR (ADDITIONAL).		120.00	60.00
	PANEL BEATING.		1,000.00	500.00
	SPRAY PAINTING CHARGE.		750.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	90.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	FRONT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE/REFIX DASHBOARD.	NOT NECESSARY	450.00	-
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	180.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	320.00
	RE-SET FRT ABS SYSTEM. }		200.00	-
			4,040.00	1,740.00
	GRAND TOTAL		18,480.28	9,959.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,950.00

Report Ref No. CS/FCI19014182/Dqf3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.