ASS. REC. BY:	cc3/7MI19014196/Kfd3 12
Senneth	ASSIGNMENT
From: Date:	Veh No: SHF 570U Yr Regn: 06, 14
Estimated Cost:	Veh No: JAF5 100 Yr Regn: 06, 14
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxl) Prime Mover / Truck / Traller or
To Inspect Vehicle No:	0 1.
at Workshop m/s Trans Cah	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
01	TO THE MAN TO THE
Insured: SKS 172 G	Sp.Reading 46/47 T/Radio: Insured / Std / NI / NA Eng/No:
Policy No.	THE RESERVE OF THE PROPERTY OF
Claims No.	Gen. Cond: Bood/Fair/Poor/Burnt
Sum Insured: Excess:	
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Carried Leaked, Burnt or
	Modl: MILI S/RIm / STD A/RIm or Tyre Size: F: 2(5//, R)/
(Policy Condition)	700116
Plemark: The veh had commenced Its N/S	O/S RS/DUN/EXNOVA (SV/55)
repair at the time of inspection.	OS BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
Bal. or Market Value: \$\Omega 42,30d	Ernol A
IDAC Accident Rport: Consistent? : Yes or No	Dred 7
GIA / PR Seen: Consistent?: Yes or No	L/Bal. P mm - R/Bal. Z mm
Est. Repairs: 05 days Res.: Yes or No	D.O.A. 10/8/19 D.O.I. 14/8/19
Lum Sum: 10 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN	110UT Rea ols
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction File pass To	
1/27 88200 CRED: 4	17436.231 2-03
SHE STOUT-(C3/A14/9000)	788 / Kden 3 (0) (0)
1 Syc122 a- x	
10/063.57am- to sent via lun	ail estimate / GIA / police report
The state of the s	CEIVED 1 9 AUG 2019
Onto/Time, File Pass 10? Prell. Report	Days Of Repair: 5
1918 TUPIST Final Report	Resurvey No. of Trip: Survey Fee:
Date/Fime, File Return 107	Transportation 250
Add	
TO	Interview (\$) Fixes
Report Format: TP	Tech Invs (\$), Others
ump (Sum / I.B.I: (S 0)2001-	Weekend (\$
	10744 261

Denise Tay (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Friday, 16 August 2019 8:37 AM

To:

Denise Tay (LKKAuto)

Subject:

FW: SHF 570U / TOKIO / DOA: 10/8/2019 -- AAD1908-078

Attachments:

SHF 570U ESTIMATE.pdf

Dear Denise

Amount confirmed \$ 8,200.00 (before GST).

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Thursday, 15 August, 2019 4:03 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHF 570U / TOKIO / DOA: 10/8/2019

Dear Wai Yin,

Lump sum \$8200 ok?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Thursday, 15 August 2019 3:57 PM

To:

Motor Claims

Cc: Subject:

SUR DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE

LTD, DOA: 10/8/2019, SHF 570U (TP VEHICLE), SKS 172G (OI VEHICLE)

Attachments:

SHF 570U POLICE REPORT.pdf; SHF 570U GIA.pdf; SHF 570U ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the SHF 570U at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 14/08/2019.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire F	PARF/COE	Rebate for	Registered	Vehicle
-----------	----------	------------	------------	---------

Vehicle Owner Particulars	
Öwner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHF570U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001450
Chassis No.:	VF1ABL15AUC278228
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Jun 2014
First Registration Date:	20 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2022
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$20,426.00
Total Rebate Amount:	\$29,174.00
Message	

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Aug 2019

MTCS19105362 / Trans-Cab Services Pte Ltd - HQ ENTRY DATE & TIME: 13/08/2019 14:49 SUBMITTED BY: Candy Kong Wai Kum

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	AND CONTROL OF THE PROPERTY OF	
	ACCIDENT STATEMENT	
Date Of Report	13/08/2019 14:49	
Date Of Accident	10/08/2019 22:40	
Exact Location Of Accident	PUNGGOL WAY SLIP ROAD TOWARDS PUNGGOL FIELD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	į
Vehicle Registration Number	SHF570U	
Insured/Policyholder		
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD	
Co Reg No	200303878K	
Email Address	CLAIMS@TRANSCAB.COM.SG	

Mobile Phone No

Email Address

Alternative Phone No OFFICE-62866666

Vehicle Particulars

RENAULT Manufacturer

LATITUDE-2.0 L (A) Model

Exact Purpose for which vehicle was being used at

time of accident

HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

THIRD PARTY Type Of Coverage

YES Fleet Policy

VFX/P1680520 Policy Number

Cover Note Number

Driver

YEO CHOON KIAT Name of Driver

S7347850B NRIC No 22/11/1973 Date Of Birth OUTDOOR Occupation 10/05/1994 Date Of Driving Pass

Driving Experience 25 YEARS AND 3 MONTHS

MALE Gender

(LOCAL) +65-96666900 Mobile Number

Fax Number

Contact Number

NOEMAIL EMail Address

Address

BLK 275D COMPASSVALE LINK

#11-238

Postcode

544275

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

SENGKANG NPC

ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: Police Station Address SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT: T/20190811/2031

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKS172G

Vehicle Make/Model/Colour

Details Of Properties Vehicle Category

PRIVATE CAR

Name of Driver

AARON

NRIC/Passport Number

Contact Number

90409314

Address

Postcode

Insurance Company Name

Page 2 of 17

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature (If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date & Time:

Sketch Plan #2 Pg. 1



Page 5 of 17

POLICE REPORT Pg. 1





Date of Expiry:

Police Station Of Origin: Sengkang N.P.C

2 Sengkang Square #01-02 SINGAPORE 545025

Taxi Driver

Tel No: 1800-343 8999

Report No. T/20190811/2031

1 of 3

REPORT	OF A TRAFFIC	CACCIDENT			
Date/Time Report Made: 11/08/2019 13:32			Vide Report No.:	Station Diary No.: 84	
Informa	nt's Partic	ulars			
Name of Informant: YEO CHOON KIAT			Address: APT BLK 323D SUMANG WALK #10-913 SINGAPORE 824323		
ID Type / ID No.: NRIC NO / S7347850B			Contact No.: Home/Office: Mobile: 96666900		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Age: Date of Birth: Male 45 22/11/1973			Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation:			Driving Licence Information:		

Class: 3A

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 10/08/2019 22:40	Type of Location: Y-Junction
Location: Along Road 1 PUNGGOL V PUNGGOL F Weather: Clear	VAY	Road Surface:		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled	19	Traffic Volume: Light
Type of Collis	sion: ving Vehicles - Head [*]	Го Rear		Anyone conveyed by ambulance: No

Vehicle No	Type -	Make The Park	Model -	Color,	Condition	No of Passenge
SHF570U	Trans Cab					0
SKS172G						0

Details of Person Involved	第300
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



T/20190811/2031

Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE Report No. T/20190811/2031

Tel No: 1800-343 8999

CONTINUATION OF REPORT

Name	YEO CHOON KIAT		ID No.		S7347850B	
Related Vehicle	SHF570U (Trans Cab)		Conta	ct No.	96666900	
Hospital/Clinic	NIL		Class Driving Licent Expiry	g ce &	Class: 3A Date of Expiry: NIL	
Date Treatment	NIL	Date Disc	narge	NIL		
No. of Days gran	ted Medical Leave NIL	Degree of	Injury	NIL		
Driver						
Name	Aaron .	15	ID No.	-	NIL	
Related Vehicle	SKS172G		Conta	ct No.	90409314	
Hospital/Clinic NIL			Class Driving Licent Expiry	g	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Disci	harge	NIL		
N	ted Medical Leave NIL	Degree of	Initiry	NII		

Brief Details.

On the 10/08/2019 at about 2230hrs, I was driving my vehicle which is a Trans Cab red in colour bearing registration number SHF570U along Punggol way towards Punggol Field. As I was driving, I turn left towards Punggol Field and stop my vehicle just before the zebra crossing to allow pedestrian to cross the road. As my vehicle was in a stationery position, there was a vehicle SKS172G which came from the rear and collided onto my vehicle. After the collision, both parties came out to exchange particulars and no one was injured. No police nor ambulance came to my scene. I made a check on my vehicle and discovered that the rear of my vehicle is damaged. I am lodging this report for insurance purpose.

POLICE REPORT Pg. 1





Police Station Of Origin: Sengkang N.P.C 2 Sengkang Square #01-02 SINGAPORE 545025 3 of 3 Report No. T/20190811/2031

Tel No: 1800-343 8999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: Signature Of Informant: Sgt 3 DALJIT SINGH Date/Time: Signature Of Interpreter: 11/08/2019 13:32 Not applicable Classification Of Case: Officer In Charge Of Case: SN 085 TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151 Authentication Stamp Singapore Police Force NP168

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G

SHF 570U

Not Nothair

AAD1908-078

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHF 570U

VF1ABL15AUC278228

RENAULT

LATITUDE

10.8.19

TOKIO MARINE

20/6/2014

		PART		LIST
1	1	BUMPER COVER REAR	\$	By 1,108.46
2	1	BUMPER LOWER REAR	\$	By 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$	01/ 113.47
4	1	BUMPER BRACKET SIDE RH REAR	\$	√ 135.97 x
5	1	BUMPER RETAINER RH REAR	\$	√ 44.99 X
6	1	BUMPER REFLECTOR RH	\$	Sen 43.61
7	1	BUMPER BRACKET SIDE LH REAR	\$	√ ₄ 135.97 x
8	1	BUMPER RETAINER LH REAR	\$	√ 44.99 X
9	1	BUMPER REFLECTOR LH	\$	√L 43.61 X
10	1	BUMPER BEAM REAR	\$	M 777.52 ~
11	1	BUMPER BEAM BRACKET LH REAR	\$	N 225.95 ★
12	1	BUMPER BEAM BRACKET RH REAR	\$	DIT 225.95
13	1	BOOT REAR	\$	R 2,872.68 —
14	1	BOOT FINISHER	\$	1 470.06 X
15	1	BOOT WHEATERSTRIP	161.52g~	6 323.05 50 lin
16	1	BOOT REFLECTOR LAMP LH	\$	√ 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	√∽ 493.35 x
18	1	BOOT BADGE 'RENAULT'	\$	1 225.36 —
19	1	BOOT BADGE	\$	Mac 225.36 ─
20	1	BOOT STRUT LH	\$	رم 276.08 <u>)</u>
21	1	BOOT STRUT RH	\$	√L 276.08
22	1	BOOT HINGE LH	\$	N 367.84
23	1	BOOT HINGE RH	\$	6 367.84 X
24	1	BOOT INNER TRIM	\$	586.45
25	1	BOOT SWITCH	\$	Ju 168.13
26	1	BOOT LOCK	\$	n 202.67
27	1	BOOT LOCK CATCH	\$	74.40
28	2	LICENCE PLATE LAMP	\$	50.52
29	2	BOOT RUBBER PLUG	\$	√L 221.81√

14 AUG 2019

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 570U

30	1	FENDER PANEL INNER TRIM REAR RH	\$ β _∽ 671.45 X
31	1	FENDER PANEL REAR RH	\$ √ 3,299.13 ✓
32	1	WHEELARCH REAR RH	\$ 5m 543.47 X
33	1	FENDER PANEL REAR LH	\$ √ 3,299.13 ★
34	1	FENDER PANEL INNER TRIM REAR LH	\$ Sh 671.45 ⊀
35	1	WHEELARCH REAR LH	\$ n 543.47 X
36	1	TAILLAMP RH	\$ Mgen 552.55
37	1	TAILLAMP PANEL RH	\$ N 986.70 X
38	1	TAILLAMP LH	\$ Sh 552.55 ⊀
39	1	TAILLAMP PANEL LH	\$ ✓ 986.70 ¥
40	1	OUTER PANEL REAR (End Panel)	\$ By 1,471.77 —
41	1	OUTER PANEL REAR (End Panel)TRIM	\$ DIY 404.56
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$ N 2,189.88 ★
43		SPARE WHEEL PANEL TRIM	\$ 54 612.21 X
44	1	EXHAUST REAR	\$ 7,489.05 <
45	8	EXHAUST CAP REAR	\$ A 230.49 L
45		FUEL FLAP	\$ <i>∧</i> 343.57 }
40	1	TOTAL	\$ 36,212.51
		10%	\$ 3,621.25
			\$ 32,591.26

		Special Nett		02
1	1SET	PARKING AID	\$	Shan 700.00 400sm
2	1SET	REAR BUMPER CLIP	\$	Ma 66.00 -
3		BUMPER BRACKET CTR CLIP	\$	14 33.00 W
4		BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00 x
5		BUMPER RETAINER RH CLIP RR	\$	~~ 20.00 X
6		BUMPER BRACKET SIDE CLIP LH RR	\$	~~ 10.00 X
7		BUMPER RETAINER CLIP LH RR	\$	~~ 20.00 X
2		BUMPER LOWER REAR RIVET	\$	~~ 22.00 x
0		BUMPER LOWER REAR CLIP	\$	M 66.00
10	1	EXHAUST MOUNTING REAR	\$	5 17.82 X
11	1 C E T	BOOT FINISHER CLIP	\$	€~ 24.20 X
11		BOOT STICKER "Trans-cab"	\$	May 30.00 -
12	1		ç	16 30.00 <u></u>
13	1	BOOT STICKER "6555-3333"	¢	10 45.00 x
14	1	BOOT INNER TRIM CLIP	¢	nn 35.00 X
15	0 7665	FENDER WHEELARCH REAR RH CLIP	\$	1 385.00 X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	2	303.00 /

AAD1908-078 Trans-cab Auto Services Pte Ltd No. 2 Ang Mo Kio Street 63 Singapore 569111 Fax No.: 6257 1330 Tel No.: 6287 6666 CO./GST Reg. No. 201019626G **SHF 570U** Sn 330.00 X \$ 1 SPARE TYRE 17 ~~ 28.00 X \$ 1 FENDER INNER TRIM CLIP RH 18 5.00 \$ 1 TAILLAMP CLIP RH 19 M 80.00 \$ 2 REAR WINDSCREEN SEALANT 20 100.00 \$ 1 WINDSCREEN MOULDING 21 \$ 100.00 1 REAR WINDSCREEN INNER SPONGE SEAL 22 5.00 \$ NA 23 1 TAILLAMP CLIP LH NA 28.00 1 FENDER INNER TRIM CLIP LH 24 MA 35.00 \$ 25 1SET FENDER WHEELARCH REAR LH CLIP Sh 330.00 1 Rear left tyre 26 Sa 380.00 Rear left tyre rim 27 Sh 330.00 \$ 1 Rear right tyre 28 √₄ 380.00 1 Rear right tyre rim 29 100.00 Rear Bumper Protector 30 3,745.02 TOTAL \$ TOTAL PARTS \$ 36,336.28 LABOUR 7,500.00 6601 Putty And Spray Painting Of The Affected Portion. \$ Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, 7,500.00 6001 \$ Adjust And Realign The Same To supply and re-do rear luggage floor panel 1 380.00 X \$ insulation padding. To transfer of bootlid fittings, attachments and 170.00 601 \$ perform water seepage test. To drop rear exhaust box, renew the same, to repair 2 170.00 X \$ and realign centre exhaust pipe. To transfer of rear end panel fittings, attachment and 170.00 601 \$ perform water seepage test.

To transfer of rear luggage floor panel fittings,

attachment and perform water seepage test.

NN 170.00 X

\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 570U

To check steering geometry and computer wheel alignment To repair and realign rear exhaust pipe. To transfer of tire, rim and on wheel balancing. To transfer of tire, rim and on wheel balancing. To reinstall rear bumper parking sensor. To transfer of rear fender fittings, attachment and perform water seepage test. To transfer of rear windscreen glass to facilitate bodywork repair. To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. To apply paint protection system (PPS) maintain and enhancement To Check Electrical Lighting Concerned. To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing. Towing Fees Towing Fees Towing Fees To drap diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing. Towing Fees Towing Fees Towing Fees Total Total Society of the performance of the following and testing. Towing Fees Towing Fees Towing Fees Total Total Society of the performance of the following and testing. Towing Fees Towing Fees Total Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Towing Fees Total Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Total Society of the performance of the following and testing. Total Society of the performance of the following and testing.	Is author to hear approved from Insurance Combany Achiev ledged by Repairer Signature:		5day	/	
To check steering geometry and computer wheel alignment To repair and realign rear exhaust pipe. S 170.00 X To transfer of tire, rim and on wheel balancing. To reinstall rear bumper parking sensor. To transfer of rear fender fittings, attachment and perform water seepage test. S 4 170.00 X To transfer of rear windscreen glass to facilitate bodywork repair. To transfer of rear bumper fittings, attachment and perform water seepage test. S 4 170.00 X To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. S 4 380.00 X To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. S 4 380.00 X To apply paint protection system (PPS) maintain and enhancement S 4 380.00 X To Check Electrical Lighting Concerned. To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing. Towing Fees S 7 150.00 X TOTAL TOTAL TOTAL S 19,350.00 TOTAL S 55,686.28	(LUMP SUM) Repair Days		25-DAY	'S	
To check steering geometry and computer wheel alignment To repair and realign rear exhaust pipe. To transfer of tire, rim and on wheel balancing. To transfer of rear funder fittings, attachment and perform water seepage test. To transfer of rear windscreen glass to facilitate bodywork repair. To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, trimings, garnish, fittings and other, to enable repair. To apply paint protection system (PPS) maintain and enhancement To Check Electrical Lighting Concerned. To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing. Towing Fees Towing Fees TOTAL	Parts prices are subject to confirmation Over All Total	\$	55	,686.28	
To check steering geometry and computer wheel alignment Solution To repair and realign rear exhaust pipe. To transfer of tire, rim and on wheel balancing. To reinstall rear bumper parking sensor. To transfer of rear fender fittings, attachment and perform water seepage test. To transfer of rear windscreen glass to facilitate bodywork repair. To transfer of rear bumper fittings, attachment and perform water seepage test. Solution To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. Solution To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. To apply paint protection system (PPS) maintain and enhancement To Check Electrical Lighting Concerned. To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing. Towing Fees \$ 220.00 X 170.00 X 170.00 X 380.00 X 380.00 X 380.00 X	the Repairer of the following: To resurvey below/either approx pareting	→	19	,330.00	-
To check steering geometry and computer wheel alignment To repair and realign rear exhaust pipe. To transfer of tire, rim and on wheel balancing. To reinstall rear bumper parking sensor. To transfer of rear fender fittings, attachment and perform water seepage test. To transfer of rear windscreen glass to facilitate bodywork repair. To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. To apply paint protection system (PPS) maintain and enhancement To Check Electrical Lighting Concerned. To drop diesel tank, pipes, hoses to facilitate		\$			-
To check steering geometry and computer wheel alignment Solution 220.00 X To repair and realign rear exhaust pipe. To transfer of tire, rim and on wheel balancing. To reinstall rear bumper parking sensor. To transfer of rear fender fittings, attachment and perform water seepage test. To transfer of rear windscreen glass to facilitate bodywork repair. To transfer of rear bumper fittings, attachment and perform water seepage test. To transfer of rear bumper fittings, attachment and perform water seepage test. To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. To apply paint protection system (PPS) maintain and enhancement \$ 170.00 X \$ 380.00 X	[2] [전계: 10.1] [20] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2	\$	nn	380.00	X
To check steering geometry and computer wheel alignment \$ 220.00 X To repair and realign rear exhaust pipe. \$ 170.00 X To transfer of tire, rim and on wheel balancing. \$ 170.00 X To reinstall rear bumper parking sensor. \$ 170.00 X To transfer of rear fender fittings, attachment and perform water seepage test. \$ 170.00 X To transfer of rear windscreen glass to facilitate bodywork repair. \$ 170.00 X To transfer of rear bumper fittings, attachment and perform water seepage test. \$ 170.00 X To transfer of rear bumper fittings, attachment and perform water seepage test. \$ 170.00 X To transfer of rear bumper fittings, attachment and perform water seepage test. \$ 380.00 X To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ 380.00 X	To Check Electrical Lighting Concerned.	\$		170.00	201
To check steering geometry and computer wheel alignment \$ 220.00 X To repair and realign rear exhaust pipe. \$ 170.00 X To transfer of tire, rim and on wheel balancing. \$ 170.00 X To reinstall rear bumper parking sensor. \$ 170.00 66 To transfer of rear fender fittings, attachment and perform water seepage test. \$ 380.00 X To transfer of rear windscreen glass to facilitate bodywork repair. \$ 4 170.00 X To transfer of rear bumper fittings, attachment and perform water seepage test. \$ 380.00 X To transfer of rear bumper fittings, attachment and perform water seepage test. \$ 380.00 X		\$	4	380.00	X
To check steering geometry and computer wheel alignment \$ 220.00 X To repair and realign rear exhaust pipe. \$ 170.00 X To transfer of tire, rim and on wheel balancing. \$ 170.00 X To reinstall rear bumper parking sensor. \$ 170.00 6 To transfer of rear fender fittings, attachment and perform water seepage test. \$ 280.00 X To transfer of rear windscreen glass to facilitate bodywork repair. \$ 4 170.00 X		\$	4	380.00	X
To check steering geometry and computer wheel alignment \$ 220.00 X To repair and realign rear exhaust pipe. \$ 170.00 X To transfer of tire, rim and on wheel balancing. \$ 170.00 X To reinstall rear bumper parking sensor. \$ 170.00 6 To transfer of rear fender fittings, attachment and perform water seepage test. \$ 380.00 X		\$	7	380.00	X
To check steering geometry and computer wheel alignment \$ 220.00 X To repair and realign rear exhaust pipe. \$ 170.00 X To transfer of tire, rim and on wheel balancing. \$ 170.00 X To reinstall rear bumper parking sensor. \$ 170.00 X		\$	4	170.00	X
To check steering geometry and computer wheel alignment \$ 220.00 X To repair and realign rear exhaust pipe. \$ 170.00 X To transfer of tire, rim and on wheel balancing. \$ 170.00 X		\$	n	380.00	X
To check steering geometry and computer wheel alignment \$ 220.00 X To repair and realign rear exhaust pipe. \$ 170.00 X	To reinstall rear bumper parking sensor.	\$		170.00	601
To check steering geometry and computer wheel alignment \$ 220.00 X	To transfer of tire, rim and on wheel balancing.	\$	4	170.00	X
To check steering geometry and computer wheel	To repair and realign rear exhaust pipe.	\$	5	170.00	X
To Rust-Proofing Of The Affected Areas.		\$	nn	220.00	X
170.00 /-	To Rust-Proofing Of The Affected Areas.	\$		170.00	601

AAD1908-078

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI19014196/KTD3N2

Date:

23/08/2019

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MS004930

Claimant

SHF570U

Insured Vehicle No:

SKS172G

Vehicle No: Date of Loss:

10/08/2019

Nature of Claim:

TP

Claim No: M1906151

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHF570U

Make & Model:

RENAULT LATITUDE, 2.0 L (A) 20/06/2014 (Man. Year: 2014)

Engine No: Chassis No: M9R8839C001450

Reg. Date:

Metallic White/Red

Odometer:

VF1ABL15AUC278228 461479 km

Colour:

1995 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Engine Capacity:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60R16

Rear Tyre Size:

215/60R16

Front Left Side:

Giti 8 mm Giti 8 mm Rear Left Side: Rear Right Side: Giti 7 mm Giti 7 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,336.27	8,702.65	27,633.62	76.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,350.00	1,520.00	17,830.00	92.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	55,686.27	10,222.65	45,463.62	81.64
Approved Total (Overridden) (S	5\$)	8,200.00		
(5	55,686.27	8,200.00	47,486.27	85.27
+ GST 7.00/7.00% (S	일어지기	574.00	3,324.04	85.27
Nett Amount (S	59,584.31	8,774.00	50,810.31	85.27

INSPECTION

Date of Assignment:

15/08/2019

Date Inspected:

14/08/2019 Inspected At:

Nett Amount (S\$)

Trans Cab Auto Services Pte Ltd - Amk

(HQ)

No 2 Ang Mo Kio St 63 Singapore 569111

Estimated Period of Repair:

5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Aug 2019)

Parts: 143 RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF570U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Recommended Parts o. Qty Part No. Particulars		Condition	Repairer's	Amount	
1	1	*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL	
2	1		Bent	768.84 FL	*768.84 FL	
3	1		Distorted	113.47 FL	*113.47 FL	
1	1		Serviceable	135.97 FL	*-FL	
5	1		Serviceable	44.99 FL	*- FL	
6	1		Scratched	43.61 FL	*43.61 FL	
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*-FL	
В	1		Serviceable	44.99 FL	*-FL	
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*-FL	
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL	
11	1	*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*-FL	
12	1	*BUMPER BEAM BRACKET RH REAR	Distorted	225.95 FL	*225.95 FL	
13	1	*BOOT REAR	Bent	2,872.68 FL		
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*-FL	
15	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*-FL	
16	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*-FL	
17	1	*BOOT BADGE RENAULT	Necessary	225.36 FL		
18	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL	
19	1	*BOOT STRUT LH	Serviceable	276.08 FL	*-FL	
20	1	*BOOT STRUT RH	Serviceable	276.08 FL		
21	1	*BOOT HINGE LH	Repair	367.84 FL		
22	1	*BOOT HINGE RH	Repair	367.84 FL		
23	1	*BOOT INNER TRIM	Serviceable	586.45 FL		
24	1	*BOOT SWITCH	Serviceable	168.13 FL	*-FL	
25	1	*BOOT LOCK	Repair	202.67 FL		
26	1	*BOOT LOCK CATCH	Repair	74.40 FL		
27	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL		
28	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL		
29	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL		
30	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL		
31	1	*WHEELARCH REAR RH	Serviceable	543.47 FL		
32	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL		
33	1	*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL		
34	1	*WHEELARCH REAR LH	Repair	543.47 FL		
35	1	*TAILLAMP RH	Mtg Cracked	552.55 FL	*552.55 FL	
36	1	*TAILLAMP PANEL RH	Repair	986.70 FL		
37	1	*TAILLAMP LH	Serviceable	552.55 FL		
38	1	*TAILLAMP PANEL LH	Repair	986.70 FL		
39	1	*OUTER PANEL REAR (END PANEL)	Bent		*1,471.77 FI	
40	1	*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL		
41	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)		2,189.88 FL		
42	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL		
43	1	*EXHAUST REAR	Repair	7,489.05 FL		
44	1	*EXHAUST CAP REAR	Repair	230.49 FL	*-FI	

y Part No. Particulars	Condition	Repairer's	Amount	
*FUEL FLAP	Serviceable	343.57 FL	*-FL	
*BOOT WEATHERSTRIP (50%)	Cut	290.75 FS	*161.53 FS	
*SET PARKING AID	Shorted	700.00 FS	*400.00 FS	
*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS	
*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS	
*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS	
*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS	
*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS	
*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS	
*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS	
*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS	
*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*-FS	
*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS	
*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS	
*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS	
*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS	
*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*-FS	
*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS	
*SPARE TYRE	Serviceable	330.00 FS	*- FS	
*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*-F8	
*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS	
*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS	
*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS	
*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS	
*TAILLAMP CLIP LH	Not Necessary	5.00 FS		
*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS		
*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*-FS	
*REAR LEFT TYRE	Serviceable	330.00 FS		
*REAR LEFT TYRE RIM	Serviceable	380.00 FS		
*REAR RIGHT TYRE	Serviceable	330.00 FS	*-F8	
*REAR RIGHT TYRE RIM	Serviceable	380.00 FS		
*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*-F8	
ise part. S=SpcNett. L=ListItemDisc.				
- List Item Discount on L Item			9,581.66 879.01	
	Total Parts (S\$)	36,336.27	8,702.65	
ise part	*REAR RIGHT TYRE *REAR RIGHT TYRE RIM *REAR BUMPER PROTECTOR . S=SpcNett. L=ListItemDisc. - List Item Discount on L Item	*REAR RIGHT TYRE RIM Serviceable *REAR BUMPER PROTECTOR Serviceable .S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	*REAR RIGHT TYRE Serviceable 330.00 FS *REAR RIGHT TYRE RIM Serviceable 380.00 FS *REAR BUMPER PROTECTOR Serviceable 100.00 FS . S=SpcNett. L=ListItemDisc. Sub Total (S\$) 39,925.21 - List Item Discount on L Items 10.00/10.00% (S\$) 3,588.94 Total Parts (S\$) 36,336.27	

Recommended Miscellaneous Items There are no new miscellaneous items selected.

No	commended Labour Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	7,500.00	600.00
3	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	. New	380.00	0.00
4	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
5	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
7	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
11	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
12	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
13	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
14	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New)	380.00	0.00
17	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
18	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
19	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING	New	380.00	0.00
20	TOWING FEES	New	150.00	0.00
	Gross Labou	ır Cost (S\$)	19,350.00	1,520.00

< END OF ESTIMATES >