

ASS. REC. BY:

REF: CS/PC1 19014209/114 f3ⁿ²

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Karant

of PC1

Date/Time: 15.8.19 2.46p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 7520R

Insured: SHA 1416C

at Workshop m/s Li Shung

Tel: 83987469

of BIK K # 01-18 Pandan Loop

Policy No:

Claim No: D19005089 MPST

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15.8.19 3.16p.m

Person Contacted: Khar Kian

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 7520R - x
	SHA 1416C - NSI / NI 16024579 / H196m2 DOA - 22/12/2016
	21/8@10:54am- Revised price advise via email.
	lump sum \$1800 f.
	4days (Red: 3161.36', 630%)

Tajm

FCI

SLG 7520R. 2016 old.

①

Honda Vozel 1496

Gold

75328

24/11/201052

②
③
④

215/60R16

⑤

15/11/201052

1000	6	1000	6
1200	6	1200	6
1400	6	1400	6
1600	6	1600	6

Li Sheng

19/8/19 03pm

Put o/s

Toh

RECEIVED 19 DEC 2019

11/2 Typist

Print Report
Print Report

Days Of Repair

4

Resurvey No. of Trip

1

Add Fee:

1000
1000
1000
1000

1000

1000

1000

1000

1000

1000

135

50

90

30

265

TP

1800/-



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005089MFSH

Date: 21/8/2019

Our Ref: CS/FCI19014209/T1tf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 7520R

Please be informed that we had conducted the inspection of the abovementioned vehicle
19/8/2019 at the premises of M/s Li Sheng have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,961.36</u>
Revised Estimate Amount	: S\$ <u>2,282.80</u>
"Check" Items Amount	: S\$ <u>1,961.84</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the front o/s portion



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-08-2019	Our Ref No. D19005089MFSH
Accident Date	02-08-2019	Claim Type. Third Party
Insured Vehicle	SHA1416C	Third Party Vehicle. SLG7520R
Survey Location	BLK K #01-18 PANDAN LOOP	
Contact Person.	TOH KHAR KIAN	
Contact No.	0/ 83987469	Fax No. 67744885
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LI SHENG AUTOMOBILE TRADING	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 21 August 2019 10:54 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005089MFSH/1
Attachments: PRELI ADVISED OF SLG 7520R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLG 7520R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 15 August 2019 3:22 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005089MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 14 August 2019 3:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005089MFSH/1

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

MS FIRST CAPITAL

Your Ref Vehicle No:
SHA1416C (TP claim)

Date: 13/8/2019
Vehicle No: SLG7520R
Model: HONDA VEZEL
Date of loss: 2/8/2019
Our ref: LSA299TJS
Year: 2016

Qty	Description	List Price	Remarks
1.00	FRONT BUMPER	\$ 801.70	de
2.00	FRONT BUMPER RETAINER	\$ 20.90 41.80	14-X, RH-21
1.00	FRONT BUMPER LOWER LIP	\$ 279.60	de
1.00	FRONT RHS FENDER	\$ 580.00	bt
1.00	FRONT FENDER INNER SHEILD	\$ 260.30	Run
1.00	FRONT RHS FENDER ARC GARNISH	\$ 158.00	at
1.00	FRONT BUMPER TOWING CAP	\$ 18.30	at
1.00	FRONT RHS FOG LAMP	\$ 327.00	Run
1.00	FRONT FOG LAMP COVER	\$ 45.00	de
1.00	FRONT HEADLAMP	\$ 1,820.00	87 X
1.00	FRONT HEADLAMP BRACKET	\$ 45.00	Run
TOTAL:		\$ 4,376.70	1903.50
LESS 20 %:		\$ 875.34	
		\$ 3,501.36	1522.80

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 700.00	300
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 600.00	400
1.00	CHECK WIRING	\$ 80.00	30
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 80.00	30
TOTAL:		\$ 1,460.00	760
SUBTOTAL:		\$ 4,961.36	

Estimate prepared by: TOH KHAR KIAN

Telephone : 83987469

tohkk 90@hotmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjah 97495749
WP
19/8/19 @ 3pm
to suve lkkauto.com
Lumpsum
Repair after repair
3-4 days
2282.80
4541800

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

MS FIRST CAPITAL

Your Ref Vehicle No:
SHA1416C (TP claim)

Date: 13/8/2019
Vehicle No: SLG7520R
Model: HONDA VEZEL
Date of loss: 2/8/2019
Our ref: LSA299TJS
Year: 2016

Qty	Description	List Price	Remarks
1.00	FRONT BUMPER	\$ 801.70	de
2.00	FRONT BUMPER RETAINER	\$ 20.90 41.80	LH-X, RH-X
1.00	FRONT BUMPER LOWER LIP	\$ 279.60	de
1.00	FRONT RHS FENDER	\$ 580.00	bt
1.00	FRONT FENDER INNER SHEILD	\$ 260.30	?
1.00	FRONT RHS FENDER ARC GARNISH	\$ 158.00	at
1.00	FRONT BUMPER TOWING CAP	\$ 18.30	at
1.00	FRONT RHS FOG LAMP	\$ 327.00	?
1.00	FRONT FOG LAMP COVER	\$ 45.00	de
1.00	FRONT HEADLAMP	\$ 1,820.00	?
1.00	FRONT HEADLAMP BRACKET	\$ 45.00	?
TOTAL:		\$ 4,376.70	\$1903.50
LESS 20 %:		\$ 875.34	\$ 380.70
		\$ 3,501.36	\$ 1522.80

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 700.00	300
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 600.00	400
1.00	CHECK WIRING	\$ 80.00	30
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 80.00	30
TOTAL:		\$ 1,460.00	\$760

SUBTOTAL: \$ 4,961.36 \$2282.80

Estimate prepared by: TOH KHAR KIAN

Telephone : 83987469

tohkk_90@hotmail.com

Tanjin 97495749
"wp"
19/8/190 3pm
to sure 1khauto.com
bump sum
Repair after repair
3-4 days
-20%
= \$1826.24
= \$1800*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014209/T1f3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-12-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1416C	Veh. Inspected	SLG 7520R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005089MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	15/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11201052	Colour	GOLD	
Odometer	75328	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2019	Inspection Date	19/08/2019	
Survey held at	LI SHENG AUTOMOBILE TRADING BLK 1, PANDAN LOOP, #01-16 SINGAPORE 128219.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7520R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	801.70	801.70
2	FRONT BUMPER RETAINER	O/S NECESSARY / N/S NOT NECESSARY	41.80	20.90
1	FRONT BUMPER LOWER LIP	DEFORMED	279.60	279.60
1	FRONT RHS FENDER	BENT	580.00	580.00
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	260.30	-
1	FRONT RHS FENDER ARC GARNISH	CUT	158.00	158.00
1	FRONT BUMPER TOWING CAP	CUT	18.30	18.30
1	FRONT RHS FOG LAMP	NOT NECESSARY	327.00	-
1	FRONT FOG LAMP COVER	DEFORMED	45.00	45.00
1	FRONT HEAD LAMP	NOT NECESSARY	1,820.00	-
1	FRONT HEAD LAMP BRACKET	NOT NECESSARY	45.00	-
	LESS 20% DISCOUNT		-875.34	-380.70
			3,501.36	1,522.80
	LABOUR			
	LABOUR FOR REPAIR ON AFFECTED AREA.		700.00	300.00
	SPRAY PAINT ON AFFECTED AREA.		600.00	400.00
	CHECK WIRING.		80.00	30.00
	APPLY RUST PROOF ON AFFECTED PANEL.		80.00	30.00
			1,460.00	760.00
	GRAND TOTAL		4,961.36	2,282.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00

Report Ref No. CS/FCI19014209/T1tf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.